

## EUROGUIDE - MAKE MODEL YEAR GUIDELINES

The Euroguide is a document to help identify the right products needed for TPMS maintenance. There are three different coverage lists : a "Make\Model\Year Look up", a "Sensor Look Up" and a "Service Kits Look Up".

**Make\Model\Year Look up:** This list helps identify the right sensors needed using a Make/Model/Year classification.

1/ Choose the car manufacturer and the model of the car in the column "Make Model".

2/ Identify the code of the car in the second column "Model code".

3/ The columns "Start of Application" and "End of Application" show if the car has been fitted with a TPMS direct system by the car manufacturer during this period of time.

4/ If the car falls within this time range, all the necessary information in the following columns can be found (same line, from left to the right)

5/ **Schrader Part Number:** This is the new After Market reference to order the matching sensor for the car.

6/ **OE Sensor reference:** This is car manufacturer's part number for the sensor.

7/ **Sensor Description :** This is the name and description of the sensor matching with the selected car.

Notice: VDO and HUF are protected brands of the companies VDO and HUF. Schrader is a distributor of VDO and HUF products. Product design, description and brands are properties of HUF and VDO.

TPMS Euroshop makes every effort to ensure that the information contained in this list is correct, but cannot guarantee 100% accuracy of the information. Customers should be aware that they buy and use any products on this website at their own risk. This list will be regularly updated.

For further information: [tpmseuroshop.com](mailto:tpmseuroshop.com) or [aftermarket@schradereurope.com](mailto:aftermarket@schradereurope.com)

Car Make	Car Model Code	Start of application	End of application	OE sensor reference	Schrader Part Number (NEW)	Sensor Description	Direct TPMS Car Park in market 2017
<b>Alfa Romeo</b>							
159	939	2005-07	EOP	51839114	4054	TRW Clamp-in Variable Angle ver 2 433MHz Fiat	243
169	N936	2015-11	EOP	68105280AF	4016	Conti Snap-in TG1D 433MHz Chrysler	58
4C	4C	2013-06	2021-03	05154876AA	3009	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	3,776
8C Competizione	920	2007-01	EOP	99760602100	4001	Beru-Huf Clamp-in Separate valve G1 433MHz Porsche	72
Brera	946	2005-11	2010-12	51839114	4054	TRW Clamp-in Variable Angle ver 2 433MHz Fiat	22
Giulia	952	2016-05	EOP	68105280AF	4016	Conti Snap-in TG1D 433MHz Chrysler	34,477
MiTo	955	2013-08	EOP	53104671	3016	Schrader Snap-in GEN4 type 433MHz Fiat	38,669
MiTo	955	2008-06	2013-07	51839114	4054	TRW Clamp-in Variable Angle ver 2 433MHz Fiat	472
Spider	946	2006-06	2010-12	51839114	4054	TRW Clamp-in Variable Angle ver 2 433MHz Fiat	22
Spider	J12A	2015-04	EOP	BHB637140	4028	Conti Clamp-in TG1C 433MHz Mazda	56
Spider	946(2)	2011-01	EOP	51839114	4054	TRW Clamp-in Variable Angle ver 2 433MHz Fiat	1
Stelvio	949	2017-01	EOP	50547691	4102	Conti Clamp-in TG1C 433MHz Alfa Giulia	8,585
<b>Alpina</b>							
Alpina 3	E90	2007-03	2009-09	36236798726	4007	Beru-Huf Clamp-in Separate valve G2.4 433MHz BMW	65
Alpina 3	E90	2009-09	2012-12	36106856227	4010	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	1
Alpina 3	E90	2013-01	EOP	36106856227	4010	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	11
Alpina 3	F30	2012-03	EOP	6855539	4043	Conti Clamp-in TG1C 433MHz BMW	891
Alpina 3	F32	2013-04	EOP	6855539	4043	Conti Clamp-in TG1C 433MHz BMW	8
Alpina 4	F32	2014-03	EOP	6855539	4043	Conti Clamp-in TG1C 433MHz BMW	435
Alpina 5	F10	2014-03	2017-10	36106798872	4069	Beru-Huf Clamp-in 433MHz BMW	156
Alpina 5	F10	2010-01	2014-02	36106790054	4010	Beru-Huf Clamp-in Separate valve G3.3 433MHz BMW	99
Alpina 5	G30	2017-01	EOP	36106872774	3057	Schrader Clamp-in Gen Delta 433MHz BMW	38
Alpina 6	E63	2006-03	EOP	36236798726	4007	Beru-Huf Clamp-in Separate valve G2.4 433MHz BMW	6
Alpina 6	F06	2014-03	2018-10	36106798872	4069	Beru-Huf Clamp-in 433MHz BMW	3
Alpina 6	F12	2010-12	2014-02	36106856227	4010	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	15
Alpina 6	F12	2015-01	EOP	36106798872	4069	Beru-Huf Clamp-in 433MHz BMW	63
Alpina 7	F01	2014-03	EOP	36106798872	4069	Beru-Huf Clamp-in 433MHz BMW	1
Alpina 7	F01	2010-09	2014-02	36106856227	4010	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	5
Alpina 7	G11	2016-01	EOP	36106872774	3057	Schrader Clamp-in Gen Delta 433MHz BMW	25
XD3	F25	2014-03	EOP	36106798872	4069	Beru-Huf Clamp-in 433MHz BMW	483
XD3	F25	2010-09	2014-02	36106856227	4010	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	14
<b>Aston Martin</b>							
Cygnnet	630L	2014-06	EOP	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1
DB11	VH500	2016-01	EOP	A0009050030	3013	Schrader Clamp-in Gen Gamma 433MHz Daimler	1,053
DB9	AM803	2012-07	EOP	AD43-360671-AA	4009	Beru-Huf Clamp-in Separate valve G1.2 433MHz Fiat Group	546
DB9	AM803	2009-01	2012-06	AD43-360671-AA	4009	Beru-Huf Clamp-in Separate valve G1.2 433MHz Fiat Group	15
DB9	VH500	2016-10	EOP	CD23-360671-CA	4009	Beru-Huf Clamp-in Separate valve G1.2 433MHz Fiat Group	29
DBS	AM803	2009-01	EOP	AD43-360671-AA	4009	Beru-Huf Clamp-in Separate valve G1.2 433MHz Fiat Group	2
Lagonda	COMET	2015-01	EOP	CD23-360671-CA	4009	Beru-Huf Clamp-in Separate valve G1.2 433MHz Fiat Group	8
Rapide	VH400	2010-01	EOP	282189	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz Fiat	502
V12 Zagato	Zagato	2012-09	EOP	CD23-360671-CA	4009	Beru-Huf Clamp-in Separate valve G1.2 433MHz Fiat Group	1
V8 Vantage	AM305	2009-01	EOP	AD43-360671-AA	4009	Beru-Huf Clamp-in Separate valve G1.2 433MHz Fiat Group	45
V8 Vantage	VH600	2014-01	2016-12	AD43-360671-AA	4009	Beru-Huf Clamp-in Separate valve G1.2 433MHz Fiat Group	42

Car Make	Car Model Code	Start of application	End of application	OE sensor reference	Schrader Part Number (NEW)	Sensor Description	Direct TPMS Car Park in market 2017
V8 Vantage	VH600(1)	2017-01	EOP	CD23-360671-CA	4009	Beru-Huf Clamp-in Separate valve G1.2 433MHz Fiat Group	12
Vanquish	AM310	2012-06	EOP	CD23-360671-CA	4009	Beru-Huf Clamp-in Separate valve G1.2 433MHz Fiat Group	775
Vantage	AM305	2014-03	EOP	AD43-360671-AA	4009	Beru-Huf Clamp-in Separate valve G1.2 433MHz Fiat Group	1,981
Vantage	VH600	2017-01	EOP	CD23-360671-CA	4009	Beru-Huf Clamp-in Separate valve G1.2 433MHz Fiat Group	61
<b>Audi</b>							
A3 Sportback	AU370	2012-06	EOP	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	78,453
A4	AU461/AU471	2004-11	2007-10	7PP907275F	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	2,165
A4	AU481	2015-01	EOP	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	4,833
A4	AU491	2014-10	2021-10	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	15,966
A4 Allroad	AU486	2009-03	2015-12	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	4
A4 Allroad	AU496	2016-01	2022-12	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	10
A4 Allroad	AU492/4	2016-04	EOP	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	50
A4 Cabrio	AU465/AU475	2008-08	EOP	7PP907275F	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	1
A4 Cabrio	AU465/AU475	2006-01	2008-07	7PP907275F	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	433
A5	AU484	2006-12	2015-06	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	1,135
A5	AU494	2015-07	2021-12	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	4,628
A5 Cabrio	AU485	2008-11	EOP	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	17,894
A5 Cabrio	AU495	2016-01	2022-12	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	1,815
A5 Sportback	AU483	2009-07	EOP	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	12,388
A5 Sportback	AU493	2016-10	EOP	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	6,525
A6	AU561	2009-06	2011-03	7PP907275F	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	433
A6	AU561	2004-05	2009-06	7PP907275F	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	433
A6	AU571	2011-01	EOP	7PP907275F	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	98,483
A6 Allroad	AU566	2009-06	2011-08	7PP907275F	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	130
A6 Allroad	AU566	2006-05	2009-06	7PP907275F	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	130
A6 Allroad	AU566	2000-04	2005-08	4D0907275C	4001	Beru-Huf Clamp-in Separate valve G1.2 433MHz VW Group	130
A6 Allroad	AU572/4	2012-01	EOP	7PP907275F	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	4,802
A7	AU573	2010-09	EOP	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	5,344
A8	AU631	1999-09	2010-07	4D0907275C	4001	Beru-Huf Clamp-in Separate valve G1.2 433MHz VW Group	6,495
A8	AU641	2009-11	EOP	7PP907275F	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	17,216
A8	AU651	2017-01	EOP	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	1,716
C-MPV	AU378	2016-04	EOP	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	28
Q1	AU276	2016-01	EOP	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	56
Q2	AU276	2016-01	EOP	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	77,850
Q3	AU316	2011-07	2018-03	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	59,226
Q4	AU319	2016-08	EOP	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	55
Q5	AU416	2008-09	EOP	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	33,685
Q5	AU426	2016-01	2022-12	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	10,840
Q7	AU716	2006-03	2009-06	7PP907275F	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	2,165
Q7	AU716	2014-06	EOP	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	2,831
Q7	AU716	2009-06	2014-05	7PP907275F	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	3,278
R8	AU714	2009-06	2015-03	7PP907275F	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	718
R8	AU714	2007-04	2009-06	7PP907275F	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	433
R8	AU624	2015-01	EOP	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	3,817
TT	AU334	2014-02	EOP	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	17
<b>Bentley</b>							
Azure	BY824	2006-06	2011-12	7PP907275F	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	4
Azure	BY835	2013-10	2020-10	7PP907275F	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	23
Bentayga	BY636	2016-01	EOP	7PP907275F	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	2,265
Continental	ROLLS ROYCE	2014-03	EOP	4F0907275B	4009	Beru-Huf Clamp-in Separate valve G2.2 433MHz VW/Porsche	1
Continental Flying Spur	BY611	2005-03	2010-12	7PP907275F	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	1,300
Continental Flying Spur	BY621	2010-01	EOP	7PP907275F	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	2,100
Continental Flying Spur	BY611(2)	2011-01	EOP	7PP907275F	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	2
Continental GT	BY634	2017-07	EOP	7PP907275F	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	26
Continental GT	BY614	2003-09	2005-05	4D0907275	4001	Beru-Huf Clamp-in Separate valve G1 433MHz VW Group	4
Continental GT	BY624	2014-03	EOP	4F0907275B	4009	Beru-Huf Clamp-in Separate valve G2.2 433MHz VW/Porsche	2,803
Continental GTC	BY615	2006-12	EOP	7PP907275F	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	2,603
Continental GTC	BY625	2011-11	EOP	7PP907275F	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	3,246
E-CUV	BY716	2014-11	2022-10	7PP907275F	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	48
E-CUV	BY736	2016-03	EOP	7PP907275F	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	33
Mulsanne	BY831	2009-09	EOP	7PP907275F	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	706
Mulsanne	BY731	2014-03	EOP	7PP907275F	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	711
<b>BMW</b>							
1-Series	E80	2014-06	2016-12	6855539	4043	Conti Clamp-in TG1C 433MHz BMW	2
1-Series	F20	2011-07	2016-12	6855539	4043	Conti Clamp-in TG1C 433MHz BMW	268,851
1-Series	E88/E82	2009-09	2011-07	36106856227	4010	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	433

# Make Model Year Look Up

Europe, Ver. 2.0,  
Update 09/2017

Car Make	Car Model Code	Start of application	End of application	OE sensor reference	Schrader Part Number (NEW)	Sensor Description	Direct TPMS Car Park in market 2017
2-Series	F22	2013-11	2016-12	6855539	4043	Conti Clamp-in TG1C 433MHz BMW	62,948
2-Series Active Tourer	F45	2014-07	2016-12	6855539	4043	Conti Clamp-in TG1C 433MHz BMW	181,605
2-Series Gran Tourer	F46	2015-01	2016-12	6855539	4043	Conti Clamp-in TG1C 433MHz BMW	94,087
3-Series	E46	1997-05	2004-12	36112360420	4002	Beru-Huf Clamp-in Separate valve G1.2 433MHz BMW	2,165
3-Series	E46	2005-01	EOP	36112360420	4002	Beru-Huf Clamp-in Separate valve G1.2 433MHz BMW	16
3-Series	E90	2014-03	EOP	36106856227	4010	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	35
3-Series	F30	2012-03	2016-12	6855539	4043	Conti Clamp-in TG1C 433MHz BMW	257,891
3-Series	E90/E91/E92/E93	2009-09	2014-02	36106856227	4010	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	43
3-Series	E90/E91/E92/E93	2006-06	2009-09	36236798726	4007	Beru-Huf Clamp-in Separate valve G2.4 433MHz BMW	43
3-Series GT	F34	2013-03	2016-12	6855539	4043	Conti Clamp-in TG1C 433MHz BMW	40,982
4-Series	F32	2013-10	2016-12	6855539	4043	Conti Clamp-in TG1C 433MHz BMW	89,909
4-Series	F82	2013-10	2016-12	6855539	4043	Conti Clamp-in TG1C 433MHz BMW	433
4-Series	F82	2017-01	EOP	36106881890	4043	Conti Clamp-in TG1C 433MHz BMW	433
4-Series Gran Coupe	F36	2014-07	2016-12	6855539	4043	Conti Clamp-in TG1C 433MHz BMW	69,041
5-Series	F10	2014-03	2016-10	36106798872	4069	Beru-Huf Clamp-in 433MHz BMW	136,379
5-Series	F10	2010-09	2014-02	36106790054	4010	Beru-Huf Clamp-in Separate valve G3.3 433MHz BMW	22,254
5-Series	E39	1998-09	2003-07	36118378682	4002	Beru-Huf Clamp-in Separate valve G1 433MHz BMW	1,299
5-Series	E60/E61/F07	2004-01	2010-08	36236798726	4007	Beru-Huf Clamp-in Separate valve G2.4 433MHz BMW	866
5-Series	G30	2017-01	EOP	36106872774	3057	Schrader Clamp-in Gen Delta 433MHz BMW	76,153
5-Series GT	F07	2014-03	2017-03	36106798872	4069	Beru-Huf Clamp-in 433MHz BMW	7,062
5-Series GT	F07	2010-09	2014-02	36106790054	4010	Beru-Huf Clamp-in Separate valve G3.3 433MHz BMW	350
5-Series GT	G32	2017-01	EOP	36106872774	3057	Schrader Clamp-in Gen Delta 433MHz BMW	1,953
6-Series	E63	2006-03	2010-12	36236798726	4007	Beru-Huf Clamp-in Separate valve G2.4 433MHz BMW	433
6-Series	F12	2014-03	2017-12	36106798872	4069	Beru-Huf Clamp-in 433MHz BMW	6,744
6-Series	F12	2011-03	2014-02	36106856227	4010	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	230
6-Series Gran Coupe	F06	2014-03	2018-10	36106798872	4069	Beru-Huf Clamp-in 433MHz BMW	10,999
6-Series Gran Coupe	F06	2011-03	2014-02	36106856227	4010	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	216
7-Series	F01	2014-06	EOP	36106856227	4010	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	40
7-Series	G11	2015-07	2022-06	36106872774	3057	Schrader Clamp-in Gen Delta 433MHz BMW	27,570
7-Series	E39	1998-09	2001-10	36112360420	4002	Beru-Huf Clamp-in Separate valve G1.2 433MHz BMW	1,299
7-Series	E65	2001-11	2003-11	36112360420	4002	Beru-Huf Clamp-in Separate valve G1.2 433MHz BMW	1,299
7-Series	E65/E66	2006-03	2008-07	36236798726	4007	Beru-Huf Clamp-in Separate valve G2.4 433MHz BMW	1,299
7-Series	F01/F02/E68	2008-09	2010-08	36236798726	4007	Beru-Huf Clamp-in Separate valve G2.4 433MHz BMW	1,299
i3	I01	2013-08	2016-12	6855539	4043	Conti Clamp-in TG1C 433MHz BMW	29,279
i8	I12	2014-01	2016-12	6855539	4043	Conti Clamp-in TG1C 433MHz BMW	5,855
X1	E84	2014-03	2015-06	36106798872	4069	Beru-Huf Clamp-in 433MHz BMW	20,892
X1	E84	2009-09	2014-02	36106856227	4010	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	3,104
X1	F48	2015-07	2021-12	36106881890	4043	Conti Clamp-in TG1C 433MHz BMW	193,946
X2	F47	2016-01	2022-12	36106881890	4043	Conti Clamp-in TG1C 433MHz BMW	56
X3	F25	2010-11	2014-02	36106856227	4010	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	6,897
X3	F25	2014-03	EOP	36106798872	4069	Beru-Huf Clamp-in 433MHz BMW	143,196
X3	G01	2017-01	EOP	36106872774	3057	Schrader Clamp-in Gen Delta 433MHz BMW	4,830
X3	E83	2003-03	2010-08	36236798726	4007	Beru-Huf Clamp-in Separate valve G2.4 433MHz BMW	433
X4	F26	2014-04	2020-03	36106798872	4069	Beru-Huf Clamp-in 433MHz BMW	66,665
X5	E70	2006-10	2010-09	36236798726	4007	Beru-Huf Clamp-in Separate valve G2.4 433MHz BMW	3,248
X5	E70	2010-03	EOP	36106856227	4010	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	3,252
X5	F15	2013-05	2016-12	6855539	4043	Conti Clamp-in TG1C 433MHz BMW	128,297
X5	E53	1999-10	2004-04	36146752128	4003	Beru-Huf Clamp-in Separate valve G1.2 plus 433MHz BMW	1,299
X6	E71	2007-12	2011-10	36236798726	4007	Beru-Huf Clamp-in Separate valve G2.4 433MHz BMW	433
X6	E71	2011-12	EOP	36106856227	4010	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	3
X6	F16	2014-08	2016-12	6855539	4043	Conti Clamp-in TG1C 433MHz BMW	35,072
Z4	E89	2014-03	EOP	36106798872	4069	Beru-Huf Clamp-in 433MHz BMW	6,915
Z4	E89	2010-09	2014-02	36106856227	4010	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	364
Z4	E89	2009-05	2010-08	36236798726	4007	Beru-Huf Clamp-in Separate valve G2.4 433MHz BMW	22
Z4 Coupe	E86	2006-04	2008-08	36236798726	4007	Beru-Huf Clamp-in Separate valve G2.4 433MHz BMW	43
<b>Bugatti</b>							
Royale	BG831	2016-01	EOP	7PP907275F	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	14
Veyron	BG824	2011-12	EOP	7PP907275F	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	15
Veyron	BG824	2005-09	2011-11	7PP907275F	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	2
<b>Buick</b>							
Park Avenue	G-CAR	1997-01	2004-06	25789964	3049	Schrader Snap-in GEN4 type 433MHz GM	22
<b>Cadillac</b>							
ATS	A1BL	2014-07	EOP	20925925	3054	Schrader Clamp-in Gen J 433MHz GM	211
ATS	A1SL	2012-07	EOP	20925925	3054	Schrader Clamp-in Gen J 433MHz GM	309
CT6	O1SL	2016-01	EOP	13589601	3063	Schrader Snap-in Faraday 433MHz GM	183
CTS	A1LL	2013-09	EOP	20925925	3054	Schrader Clamp-in Gen J 433MHz GM	397
CTS	GMX206	2008-01	EOP	20922901	3049	Schrader Snap-in GEN4 type 433MHz GM	47

Car Make	Car Model Code	Start of application	End of application	OE sensor reference	Schrader Part Number (NEW)	Sensor Description	Direct TPMS Car Park in market 2017
CTS	GMX226	2010-06	EOP	20922901	3049	Schrader Snap-in GEN4 type 433MHz GM	43
CTS	GMX322	2013-09	EOP	25774007	3055	Schrader Clamp-in Gen J 433MHz GM	6
CTS	GMX322	2006-01	2007-06	25774007	3055	Schrader Clamp-in Gen J 433MHz GM	56
ELR	D1BLI	2016-01	EOP	13594222	3071	Schrader Snap-in Faraday 433MHz GM	4
Escalade	GMT926	2005-12	EOP	22853740	3049	Schrader Snap-in GEN4 type 433MHz GM (China)	36
Escalade	K2UL	2014-01	EOP	22853740	3049	Schrader Snap-in GEN4 type 433MHz GM (China)	486
SRX	GMT166	2009-07	EOP	25789964	3049	Schrader Snap-in GEN4 type 433MHz GM	364
SRX	GMT265	2005-06	2009-02	25789964	3049	Schrader Snap-in GEN4 type 433MHz GM	87
SRX	C1UL	2016-01	EOP	13598773	3063	Schrader Snap-in Faraday 433MHz GM (China)	12
STS	GMX295	2005-06	2011-04	25758221	3053	Schrader Clamp-in Gen J 433MHz GM	22
XLR	GMX215	2003-05	2009-04	25758221	3053	Schrader Clamp-in Gen J 433MHz GM	22
XT5	C1UL	2016-01	EOP	13598773	3063	Schrader Snap-in Faraday 433MHz GM (China)	364
XTS	P1LL	2012-05	EOP	22853740	3049	Schrader Snap-in GEN4 type 433MHz GM (China)	11
<b>Chevrolet</b>							
Aveo	G1SC	2010-11	2016-12	22853740	3049	Schrader Snap-in GEN4 type 433MHz GM (China)	350
Aveo	G1SC	2010-11	2018-05	22853740	3049	Schrader Snap-in GEN4 type 433MHz GM (China)	95
Aveo	T250	2014-03	EOP	22853740	3049	Schrader Snap-in GEN4 type 433MHz GM (China)	2
Aveo	G1JC	2014-03	EOP	22853740	3049	Schrader Snap-in GEN4 type 433MHz GM (China)	12
Camaro	A1BC	2015-10	EOP	20925925	3054	Schrader Clamp-in Gen J 433MHz GM	1,889
Camaro	GMX521	2010-11	EOP	20925925	3054	Schrader Clamp-in Gen J 433MHz GM	1,141
Captiva	C100	2006-06	2014-05	25789964	3049	Schrader Snap-in GEN4 type 433MHz GM	8,540
Captiva	C100	2006-06	EOP	25789964	3049	Schrader Snap-in GEN4 type 433MHz GM	7,548
Colorado	GMI700	2011-10	EOP	20925925	3054	Schrader Clamp-in Gen J 433MHz GM	4
Colorado (LCV)	GMT355	2003-10	EOP	25758221	3053	Schrader Clamp-in Gen J 433MHz GM	43
Corvette	GMX245	2010-02	2014-12	20925925	3054	Schrader Clamp-in Gen J 433MHz GM	1,311
Corvette	GMX245	2004-07	2010-01	25758221	3053	Schrader Clamp-in Gen J 433MHz GM	2,598
Corvette	Y1BC	2014-03	EOP	13581560	3033	Schrader Clamp-in Gen Gamma 433MHz GM	2,091
Corvette	GMX245(2)	2014-03	EOP	20925925	3054	Schrader Clamp-in Gen J 433MHz GM	2
Cruze	D1SC	2008-10	EOP	22853740	3049	Schrader Snap-in GEN4 type 433MHz GM (China)	175
Cruze	D1JC	2014-06	EOP	22853740	3049	Schrader Snap-in GEN4 type 433MHz GM (China)	17
Cruze	D1WC	2014-06	EOP	22853740	3049	Schrader Snap-in GEN4 type 433MHz GM (China)	16
Express	GMT610	2014-06	EOP	22853740	3049	Schrader Snap-in GEN4 type 433MHz GM (China)	3
Express (PC)	GMT610	2002-07	EOP	22853740	3049	Schrader Snap-in GEN4 type 433MHz GM (China)	65
Malibu	V300	2014-07	EOP	13581561	3062	Schrader Snap-in GEN4 type 433MHz GM	2
Malibu	V300	2010-07	2011-06	20922901	3049	Schrader Snap-in GEN4 type 433MHz GM	30
Malibu	GMX351	2015-01	EOP	13581561	3062	Schrader Snap-in GEN4 type 433MHz GM	1
Malibu	GMX386	2014-03	EOP	13581561	3062	Schrader Snap-in GEN4 type 433MHz GM	1
Orlando	J309	2010-09	2017-12	22853740	3049	Schrader Snap-in GEN4 type 433MHz GM (China)	94
Orlando	D1NC	2014-06	EOP	22853740	3049	Schrader Snap-in GEN4 type 433MHz GM (China)	464
Silverado	K2XC	2014-06	EOP	22853740	3049	Schrader Snap-in GEN4 type 433MHz GM (China)	1,251
Spark	M1JC	2009-07	EOP	22853740	3049	Schrader Snap-in GEN4 type 433MHz GM (China)	126
Suburban	GMT931	2006-03	EOP	22853740	3049	Schrader Snap-in GEN4 type 433MHz GM (China)	37
Tahoe	GMT921	2014-03	EOP	20925925	3054	Schrader Clamp-in Gen J 433MHz GM	63
Trailblazer (LCV)	GMT360	2001-01	EOP	25774007	3055	Schrader Clamp-in Gen J 433MHz GM	217
Trax	G1UC	2012-03	EOP	22853740	3049	Schrader Snap-in GEN4 type 433MHz GM (China)	11,647
Volt	D1JCI	2010-11	EOP	13348393	3026	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	773
Volt	D2JCI	2015-06	2020-09	13594222	3071	Schrader Snap-in Faraday 433MHz GM	70
<b>Chrysler</b>							
300	LE48	2014-06	EOP	56029400AD	3008	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	9
300	LX	2011-01	2016-06	56029400AD	3008	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	1
300	LX	2016-07	EOP	Info not available	3065	Schrader Clamp-in Gen Delta 433MHz Chrysler	1
300/300C	LE48	2005-06	2010-06	56029359AC	3006	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	4,330
Delta	844	2013-02	EOP	51839114	4054	TRW Clamp-in Variable Angle ver 2 433MHz Fiat	1
Grand Voyager	RT	2011-01	2017-09	56029398AB	3007	Schrader Snap-in GEN4 type 433MHz Chrysler	3
Grand Voyager	RT	2007-07	2011-01	56029359AC	3006	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	1,299
Grand Voyager	RU	2016-01	EOP	68105280AF	4016	Conti Snap-in TG1D 433MHz Chrysler	2
Sebring	JS41C	2006-08	EOP	56029359AC	3006	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	89
Sebring Convertible	JS27	2007-02	EOP	56029359AC	3006	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	132
Town & Country	RT	2007-07	2011-01	56029359AC	3006	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	433
Viper	ZD	2012-12	EOP	56029398AB	3007	Schrader Snap-in GEN4 type 433MHz Chrysler	1
Voyager	RT	2014-06	EOP	56029398AB	3007	Schrader Snap-in GEN4 type 433MHz Chrysler	8
Ypsilon	846	2011-04	EOP	53104671	3016	Schrader Snap-in GEN4 type 433MHz Fiat	181,771
<b>Citroen</b>							
Berlingo	B9	2013-10	2017-01	9811536380	3002	Schrader Snap-in HS with 20deg angle 433MHz PSA	204,733
Berlingo	B9	2008-01	2013-09	5430W0	3000	Schrader Snap-in GEN4 type 433MHz PSA	98
Berlingo Multispace	B9	2013-10	EOP	9811536380	3002	Schrader Snap-in HS with 20deg angle 433MHz PSA	140,481
C4	B5	2004-11	2008-06	5430T4	4031	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	2,165
C4	B7	2014-01	2017-12	9811536380	3002	Schrader Snap-in HS with 20deg angle 433MHz PSA	43
C4	B7	2010-06	2014-01	5430W0	3000	Schrader Snap-in GEN4 type 433MHz PSA	29,877

Car Make	Car Model Code	Start of application	End of application	OE sensor reference	Schrader Part Number (NEW)	Sensor Description	Direct TPMS Car Park in market 2017
C4 Aircross	ZC(2)	2016-08	EOP	4250C477	4073	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	56
C4 Aircross	J4	2014-04	EOP	1612477080	4073	Conti Clamp-in TG1C 433MHz Conti PSA	31,586
C4 Picasso	B58	2013-10	EOP	5430W0	3000	Schrader Snap-in GEN4 type 433MHz PSA	13
C4 Picasso	B58	2006-05	2013-09	5430W0	3000	Schrader Snap-in GEN4 type 433MHz PSA	86,606
C5	X3/X40	2004-08	2007-12	5430T4	4031	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	67,981
C5	X40	2000-12	2004-07	543002	3004	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Large Grommet Seal 433MHz PSA	51,960
C5	X7	2013-09	2016-09	9811536380	3002	Schrader Snap-in HS with 20deg angle 433MHz PSA	24,379
C5	X7	2008-01	2013-09	5430T4	4031	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	43,740
C6	X6	2005-09	2012-12	5430T4	4031	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	1,083
C8	V3	2014-07	EOP	5430T4	4031	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	12
C8	V3	2005-09	2014-06	5430T4	4031	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	8,668
C8	V3	2002-02	2005-10	543002	3004	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Large Grommet Seal 433MHz PSA	8,660
C-Crosser	I4	2014-03	EOP	4250C477	4073	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	1
C-Elysee	M3/M4	2012-10	EOP	9811536380	3002	Schrader Snap-in HS with 20deg angle 433MHz PSA	32,805
C-ZERO	S4	2014-06	EOP	1612477080	4073	Conti Clamp-in TG1C 433MHz Conti PSA	3,643
DS4	B75	2010-12	2014-01	5430W0	3000	Schrader Snap-in GEN4 type 433MHz PSA	13,840
DS4	B75	2014-02	EOP	9811536380	3002	Schrader Snap-in HS with 20deg angle 433MHz PSA	56,850
DS5	B81	2014-02	EOP	9811536380	3002	Schrader Snap-in HS with 20deg angle 433MHz PSA	37,380
DS5	B81	2011-06	2014-01	5430W0	3000	Schrader Snap-in GEN4 type 433MHz PSA	8,638
Jumper	X2/50	2013-12	EOP	05154876AA	3009	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	136,332
Jumper	X2/50	2006-01	2013-11	5430W0	3000	Schrader Snap-in GEN4 type 433MHz PSA	98
Jumper Chassis	X2/50	2014-06	EOP	05154876AA	3009	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	4
Jumper Combi	X2/50	2014-06	EOP	05154876AA	3009	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	15,386
Jumpy	G9	2014-06	EOP	9808859080	3003	Schrader Snap-in HS with 20deg angle 433MHz PSA HP	38,026
Jumpy Combi	G9	2014-06	EOP	9808859080	3003	Schrader Snap-in HS with 20deg angle 433MHz PSA HP	6,638
Nemo	225	2007-10	2015-12	53104671	3016	Schrader Snap-in GEN4 type 433MHz Fiat	13,470
Nemo	225(2)	2015-10	2022-12	53104671	3016	Schrader Snap-in GEN4 type 433MHz Fiat	27
Nemo Multispace	225	2007-10	EOP	53104671	3016	Schrader Snap-in GEN4 type 433MHz Fiat	5,073
Nemo Multispace	225(2)	2015-10	EOP	53104671	3016	Schrader Snap-in GEN4 type 433MHz Fiat	19
<b>Dacia</b>							
Dokker	K67	2014-06	EOP	40700932R-D	3041	Schrader Snap-in HS with 20deg angle 433MHz Renault	91,842
Dokker Van	F67	2014-06	EOP	40700932R-D	3041	Schrader Snap-in HS with 20deg angle 433MHz Renault	65,961
Duster	H79	2010-02	EOP	40700932R-D	3041	Schrader Snap-in HS with 20deg angle 433MHz Renault	169,151
Duster Oroch	U79	2017-01	EOP	40700932R-D	3041	Schrader Snap-in HS with 20deg angle 433MHz Renault	21
Duster Pickup	H79	2016-01	EOP	40700932R-D	3041	Schrader Snap-in HS with 20deg angle 433MHz Renault	34
Duster Pickup	U79	2015-10	EOP	40700932R-D	3041	Schrader Snap-in HS with 20deg angle 433MHz Renault	21
Duster Pro	H79	2014-06	EOP	40700932R-D	3041	Schrader Snap-in HS with 20deg angle 433MHz Renault	10
Lodgy	J92	2012-01	EOP	40700932R-D	3041	Schrader Snap-in HS with 20deg angle 433MHz Renault	77,666
Logan	L52	2012-11	EOP	40700932R-D	3041	Schrader Snap-in HS with 20deg angle 433MHz Renault	17,946
Logan	L90	2014-06	EOP	40700932R-D	3041	Schrader Snap-in HS with 20deg angle 433MHz Renault	1
Logan MCV	K52	2013-04	EOP	40700932R-D	3041	Schrader Snap-in HS with 20deg angle 433MHz Renault	31,856
Logan Pickup	U90	2014-03	EOP	40700932R-D	3041	Schrader Snap-in HS with 20deg angle 433MHz Renault	1
Logan Van	F90	2014-06	EOP	40700932R-D	3041	Schrader Snap-in HS with 20deg angle 433MHz Renault	53
Sandero	B52	2012-10	EOP	40700932R-D	3041	Schrader Snap-in HS with 20deg angle 433MHz Renault	129,202
Sandero Pro	B52	2012-10	EOP	40700932R-D	3041	Schrader Snap-in HS with 20deg angle 433MHz Renault	1
<b>Dodge</b>							
Avenger	JS41D	2006-11	EOP	56029359AC	3006	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	68
Caliber	PM49	2006-01	EOP	56029359AC	3006	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	217
Caravan	RT	2011-06	2017-05	56029398AB	3007	Schrader Snap-in GEN4 type 433MHz Chrysler	44
Challenger	LC22	2010-02	2017-09	56029398AB	3007	Schrader Snap-in GEN4 type 433MHz Chrysler	207
Challenger	LC22	2008-01	2010-01	56029359AC	3006	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	87
Charger	LD	2010-12	2014-09	56029398AB	3007	Schrader Snap-in GEN4 type 433MHz Chrysler	87
Charger	LD	2014-10	2016-06	68241067AA	3007	Schrader Snap-in GEN4 type 433MHz Chrysler	1
Charger	LX48D	2010-11	EOP	56029398AB	3007	Schrader Snap-in GEN4 type 433MHz Chrysler	50
Durango	WD75	2010-11	EOP	56029398AB	3007	Schrader Snap-in GEN4 type 433MHz Chrysler	673
Journey	JC49	2011-01	2014-06	56029398AB	3007	Schrader Snap-in GEN4 type 433MHz Chrysler	43
Journey	JC49	2014-07	2015-09	68241067AA	3007	Schrader Snap-in GEN4 type 433MHz Chrysler	55
Nitro	KA	2006-08	EOP	56029359AC	3006	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	153
Ram	DS	2010-01	2013-06	56029398AB	3007	Schrader Snap-in GEN4 type 433MHz Chrysler	690
Ram	DS	2013-07	2017-12	68239720AB	4068	TRW Snap-in Fixed Angle ver 1 433MHz Chrysler	2,567
Viper	ZD	2015-07	EOP	05154876AA	3009	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	4
Viper	ZD	2013-08	2015-06	56029400AD	3008	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	2
<b>Ferrari</b>							
550 Maranello	F133	2002-03	EOP	248887	4009	Beru-Huf Clamp-in Separate valve G1.2 433MHz Fiat Group	217
612 Scaglietti	F137	2004-04	2011-06	185189	4001	Beru-Huf Clamp-in Separate valve G1 433MHz Fiat Group	217
California	F149	2014-11	EOP	228887	4009	Beru-Huf Clamp-in Separate valve G2.3 433MHz Fiat	1,910
California	F149	2008-07	2014-10	228887	4009	Beru-Huf Clamp-in Separate valve G2.3 433MHz Fiat	2,240
California	F149(2)	2017-01	EOP	228887	4009	Beru-Huf Clamp-in Separate valve G2.3 433MHz Fiat	553
Enzo	Enzo	2003-09	2004-12	193867	4005	Beru-Huf Clamp-in Separate valve G1 plus 433MHz Ferrari	69

Car Make	Car Model Code	Start of application	End of application	OE sensor reference	Schrader Part Number (NEW)	Sensor Description	Direct TPMS Car Park in market 2017
F12	F152	2012-10	EOP	282189	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz Fiat	1,606
F430	F131	2007-07	2009-12	228887	4009	Beru-Huf Clamp-in Separate valve G2.3 433MHz Fiat	22
F430	F131	2005-05	2007-06	185189	4001	Beru-Huf Clamp-in Separate valve G1 433MHz Fiat Group	22
F430 Scuderia	F131	2007-07	2012-06	99760602120	4009	Beru-Huf Clamp-in Separate valve G2.3 433MHz Fiat	43
F458	F142	2009-12	EOP	228887	4009	Beru-Huf Clamp-in Separate valve G2.3 433MHz Fiat	5,318
F488	F142M	2015-01	EOP	282189	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz Fiat	3,300
F599 GTB	F141	2004-03	EOP	185189	4001	Beru-Huf Clamp-in Separate valve G1 433MHz Fiat Group	39
FF	F151	2011-06	EOP	282189	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz Fiat	825
LaFerrari	F150	2013-07	EOP	282189	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz Fiat	228
<b>Fiat</b>							
124	J12F	2016-01	EOP	BHB637140	4028	Conti Clamp-in TG1C 433MHz Mazda	10,493
1-Tonne Pickup	4P00	2016-01	EOP	4250C477	4073	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	56
500	312	2015-08	EOP	53104671	3016	Schrader Snap-in GEN4 type 433MHz Fiat	373,590
500	312	2007-05	2015-07	53104671	3016	Schrader Snap-in GEN4 type 433MHz Fiat	115,893
500C	312	2007-05	EOP	53104671	3016	Schrader Snap-in GEN4 type 433MHz Fiat	69,597
Bravo	198	2007-01	EOP	51839114	4054	TRW Clamp-in Variable Angle ver 2 433MHz Fiat	674
Doblo	223	2014-06	EOP	53104671	3016	Schrader Snap-in GEN4 type 433MHz Fiat	0
Doblo	263	2009-12	EOP	53104671	3016	Schrader Snap-in GEN4 type 433MHz Fiat	147,821
Doblo Combi	263	2014-06	EOP	53104671	3016	Schrader Snap-in GEN4 type 433MHz Fiat	3,286
Ducato	X2/50	2014-06	EOP	05154876AA	3009	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	29,351
Ducato Chassis	X2/50	2014-06	EOP	05154876AA	3009	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	0
Ducato Combi	X2/50	2014-06	EOP	05154876AA	3009	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	10,675
Fiorino	225	2014-06	EOP	53104671	3016	Schrader Snap-in GEN4 type 433MHz Fiat	5,708
Fiorino Qubo	225	2014-06	EOP	53104671	3016	Schrader Snap-in GEN4 type 433MHz Fiat	2,745
Freemont	JF	2016-01	EOP	68241067AB	3007	Schrader Snap-in GEN4 type 433MHz Chrysler	3,028
Freemont	JF	2014-07	2015-09	68241067AA	3007	Schrader Snap-in GEN4 type 433MHz Chrysler	14,418
Freemont	JF	2011-03	2014-06	56029398AB	3007	Schrader Snap-in GEN4 type 433MHz Chrysler	31,962
Fullback	4P00	2016-01	EOP	4250C477	4073	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	11,749
Idea	350	2003-09	EOP	51750439	3017	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz Fiat/GM	236
Linea	200	2007-03	EOP	53104671	3016	Schrader Snap-in GEN4 type 433MHz Fiat	14
Punto	199	2005-09	EOP	51839114	4054	TRW Clamp-in Variable Angle ver 2 433MHz Fiat	228,150
Qubo	225	2007-10	EOP	53104671	3016	Schrader Snap-in GEN4 type 433MHz Fiat	6,234
Scudo	G9	2013-11	2015-12	9808859080	3003	Schrader Snap-in HS with 20deg angle 433MHz PSA HP	17,514
Scudo	G9	2016-01	EOP	9808859080	3003	Schrader Snap-in HS with 20deg angle 433MHz PSA HP	11,187
Scudo	G9	2006-09	2013-10	9677130580	3001	Schrader Snap-in GEN4 type 433MHz PSA HP	36
Scudo Chassis	G9	2014-03	EOP	9808859080	3003	Schrader Snap-in HS with 20deg angle 433MHz PSA HP	2
Scudo Combi	G9	2013-11	EOP	9808859080	3003	Schrader Snap-in HS with 20deg angle 433MHz PSA HP	5,407
Scudo Combi	G9	2006-09	2013-10	9677130580	3001	Schrader Snap-in GEN4 type 433MHz PSA HP	36
Sedici	YY2	2014-06	EOP	43139-61M00	4065	Conti Clamp-in TG1C 433MHz Suzuki	813
Strada	178	1998-09	EOP	53104671	3016	Schrader Snap-in GEN4 type 433MHz Fiat	102
Strada	326	2013-01	EOP	53104671	3016	Schrader Snap-in GEN4 type 433MHz Fiat	9
Talento	X82	2016-01	EOP	40700932R-D	3041	Schrader Snap-in HS with 20deg angle 433MHz Renault	25,516
Talento Combi	X82	2016-01	EOP	40700932R-D	3041	Schrader Snap-in HS with 20deg angle 433MHz Renault	1,599
Ulysse	V1	2005-11	2010-10	9673198580/9681102280	4031	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	650
Ulysse	V1	2002-02	2005-10	543002	3004	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Large Grommet Seal 433MHz PSA	1,299
<b>Fisker</b>							
Karma	K1	2014-03	EOP	C131124501000	4086	Lear Snap-in Fixed Angle ver 1 433MHz Fisker sensor	11
<b>Ford</b>							
B-Max	B232	2014-06	EOP	EV6T-1A180-CB	3021	Schrader Snap-in Faraday 433MHz Ford (China)	135,824
C-MAX	C344	2014-03	EOP	EV6T-1A180-CB	3021	Schrader Snap-in Faraday 433MHz Ford (China)	281,355
Ecosport	B515	2014-10	EOP	EV6T-1A180-CB	3021	Schrader Snap-in Faraday 433MHz Ford (China)	145,970
Ecosport	B515	2012-07	2014-09	DR3V-1A180-BB	3019	Schrader Clamp-in Fixed 20deg angle 433MHz Ford	6,810
Edge	CD539	2014-08	EOP	F2GT-1A180-CB	3023	Schrader Snap-in Faraday 433MHz Ford (China)	18,399
Edge	U387	2014-06	EOP	BB5T-1A180-AA	3020	Schrader Snap-in GEN4 type 433MHz Ford	260
Edge	CD389	2015-01	EOP	F2GT-1A180-CB	3023	Schrader Snap-in Faraday 433MHz Ford (China)	62
Escape	C520	2012-04	2017-06	BB5T-1A180-AA	3020	Schrader Snap-in GEN4 type 433MHz Ford	2
Escape	C520(2)	2014-03	EOP	EV6T-1A180-CB	3021	Schrader Snap-in Faraday 433MHz Ford (China)	2
Expedition	U222(2)	2005-01	2008-11	BB5T-1A180-AA	3020	Schrader Snap-in GEN4 type 433MHz Ford	43
Explorer	U502	2010-11	EOP	BB5T-1A180-AA	3020	Schrader Snap-in GEN4 type 433MHz Ford	168
F-150	P415	2008-09	2014-06	BB5T-1A180-AA	3020	Schrader Snap-in GEN4 type 433MHz Ford	43
F-150	P552	2015-03	EOP	EV6T-1A180-CB	3021	Schrader Snap-in Faraday 433MHz Ford (China)	236
F-150	P415(2)	2014-03	EOP	EV6T-1A180-CB	3021	Schrader Snap-in Faraday 433MHz Ford (China)	2
Fiesta	B299	2016-01	EOP	EV6T-1A180-CB	3021	Schrader Snap-in Faraday 433MHz Ford (China)	410,397
Fiesta	B299	2014-05	2015-12	EV6T-1A180-CB	3021	Schrader Snap-in Faraday 433MHz Ford (China)	308,937
Fiesta	B479	2017-01	2022-03	F2GT-1A180-CB	3023	Schrader Snap-in Faraday 433MHz Ford (China)	170,222
Fiesta Van	B299	2014-06	EOP	EV6T-1A180-CB	3021	Schrader Snap-in Faraday 433MHz Ford (China)	22,718
Fiesta Van	B479	2017-01	EOP	F2GT-1A180-CB	3023	Schrader Snap-in Faraday 433MHz Ford (China)	2,588
Fiesta Van	B256/257	2014-03	EOP	EV6T-1A180-CB	3021	Schrader Snap-in Faraday 433MHz Ford (China)	1
Focus	C346	2014-03	EOP	EV6T-1A180-CB	3021	Schrader Snap-in Faraday 433MHz Ford (China)	662,000

Car Make	Car Model Code	Start of application	End of application	OE sensor reference	Schrader Part Number (NEW)	Sensor Description	Direct TPMS Car Park in market 2017
Focus (LCV)	C346	2010-12	EOP	EV6T-1A180-CB	3021	Schrader Snap-in Faraday 433MHz Ford (China)	9
Focus C-Max	C214	2014-03	EOP	EV6T-1A180-CB	3021	Schrader Snap-in Faraday 433MHz Ford (China)	2
F-Series	P415	2014-03	EOP	EV6T-1A180-CB	3021	Schrader Snap-in Faraday 433MHz Ford (China)	18
F-Series	P552	2015-01	EOP	EV6T-1A180-CB	3021	Schrader Snap-in Faraday 433MHz Ford (China)	33
F-Series	P 415	2008-09	2014-02	BB5T-1A180-AA	3020	Schrader Snap-in GEN4 type 433MHz Ford	8
Galaxy	CD340	2015-01	EOP	8G921A189-KB	4023	Conti Clamp-in TG1B 433MHz Ford	152
Galaxy	CD340	2006-01	2014-12	8G921A189-KB	4023	Conti Clamp-in TG1B 433MHz Ford	4,118
Galaxy	CD390	2015-06	2022-06	F2GT-1A180-CB	3023	Schrader Snap-in Faraday 433MHz Ford (China)	43,649
GT	S922	2017-01	EOP	HG7Z-1A189-B	3101	Schrader CISI Black Faraday 433MHz Ford (Service)	40
Kuga	C520	2012-11	2019-09	EV6T-1A180-CB	3021	Schrader Snap-in Faraday 433MHz Ford (China)	370,102
Mondeo	CD345	2007-01	2015-03	8G921A189-KB	4023	Conti Clamp-in TG1B 433MHz Ford	6,591
Mondeo	CD391	2014-10	EOP	EV6T-1A180-CB	3021	Schrader Snap-in Faraday 433MHz Ford (China)	206,160
Mustang	S197	2014-05	EOP	DR3V-1A180-DA	3024	Schrader Clamp-in Fixed 20deg angle 433MHz Ford - (Service)	2
Mustang	S197	2004-09	2014-04	DR3V-1A180-DA	3024	Schrader Clamp-in Fixed 20deg angle 433MHz Ford - (Service)	433
Mustang	S550	2014-05	EOP	F2GT-1A180-CB	3023	Schrader Snap-in Faraday 433MHz Ford (China)	31,502
Ranger	P375	2014-06	EOP	EV6T-1A180-CB	3021	Schrader Snap-in Faraday 433MHz Ford (China)	94,180
S-MAX	CD340	2006-02	EOP	8G921A159-AE	4021	Conti Clamp-in TG1C 433MHz Ford	4,771
S-MAX	CD539	2015-06	2021-06	F2GT-1A180-CB	3023	Schrader Snap-in Faraday 433MHz Ford (China)	78
S-MAX	CD389	2015-01	EOP	F2GT-1A180-CB	3023	Schrader Snap-in Faraday 433MHz Ford (China)	89,420
Tourneo Connect	V408	2014-03	EOP	EV6T-1A180-CB	3021	Schrader Snap-in Faraday 433MHz Ford (China)	43,324
Tourneo Courier	B460	2014-10	EOP	EV6T-1A180-CB	3021	Schrader Snap-in Faraday 433MHz Ford (China)	22,676
Tourneo Courier	B460	2014-03	2014-09	DR3V-1A180-BB	3019	Schrader Clamp-in Fixed 20deg angle 433MHz Ford	992
Tourneo Custom	V362	2013-04	EOP	DV6T-1A180-AA	3020	Schrader Snap-in GEN4 type 433MHz Ford (China)	51,380
Transit	V184	2014-06	EOP	EV6T-1A180-CB	3021	Schrader Snap-in Faraday 433MHz Ford (China)	1
Transit	V347	2014-06	EOP	EV6T-1A180-CB	3021	Schrader Snap-in Faraday 433MHz Ford (China)	4
Transit	V348	2014-06	EOP	EV6T-1A180-CB	3021	Schrader Snap-in Faraday 433MHz Ford (China)	3
Transit	V363	2013-06	EOP	DV6T-1A180-AA	3020	Schrader Snap-in GEN4 type 433MHz Ford (China)	237,743
Transit	V347,V348	2014-03	EOP	DR3V-1A180-BB	3019	Schrader Clamp-in Fixed 20deg angle 433MHz Ford	5
Transit Chassis	V348	2014-03	EOP	DR3V-1A180-BB	3019	Schrader Clamp-in Fixed 20deg angle 433MHz Ford	1
Transit Chassis	V363	2013-06	EOP	DV6T-1A180-AA	3020	Schrader Snap-in GEN4 type 433MHz Ford (China)	1,230
Transit Combi	V184	2014-03	EOP	DR3V-1A180-BB	3019	Schrader Clamp-in Fixed 20deg angle 433MHz Ford	9
Transit Combi	V347	2014-03	EOP	DR3V-1A180-BB	3019	Schrader Clamp-in Fixed 20deg angle 433MHz Ford	1
Transit Combi	V348	2014-03	EOP	DR3V-1A180-BB	3019	Schrader Clamp-in Fixed 20deg angle 433MHz Ford	11
Transit Combi	V348,V363	2013-06	2021-03	DV6T-1A180-AA	3020	Schrader Snap-in GEN4 type 433MHz Ford (China)	45
Transit Combi	V363	2013-06	EOP	DV6T-1A180-AA	3020	Schrader Snap-in GEN4 type 433MHz Ford (China)	23,495
Transit Combi	V347,V348	2014-03	EOP	DR3V-1A180-BB	3019	Schrader Clamp-in Fixed 20deg angle 433MHz Ford	1
Transit Connect	V408	2014-03	EOP	EV6T-1A180-CB	3021	Schrader Snap-in Faraday 433MHz Ford (China)	162,869
Transit Courier	B460	2014-10	EOP	EV6T-1A180-CB	3021	Schrader Snap-in Faraday 433MHz Ford (China)	64,245
Transit Courier	B460	2014-03	2014-09	DR3V-1A180-BB	3019	Schrader Clamp-in Fixed 20deg angle 433MHz Ford	2,274
Transit Custom	V362	2013-04	EOP	DV6T-1A180-AA	3020	Schrader Snap-in GEN4 type 433MHz Ford (China)	322,772
<b>Genesis</b>							
G90	HI	2016-01	EOP	52933-3M000	4052	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	14
<b>GMC</b>							
Savana	GMT610	2002-07	2012-01	25789964	3049	Schrader Snap-in GEN4 type 433MHz GM	17
Savana Cargo	GMT610	2002-07	EOP	25789964	3049	Schrader Snap-in GEN4 type 433MHz GM	42
Sierra	GMT902	2006-10	2009-05	22853740	3049	Schrader Snap-in GEN4 type 433MHz GM (China)	65
Sierra	GMT902	2009-06	EOP	20922901	3049	Schrader Snap-in GEN4 type 433MHz GM	6
Sierra	K2XG	2013-04	EOP	22853740	3049	Schrader Snap-in GEN4 type 433MHz GM (China)	31
Yukon	GMT922	2014-03	EOP	22853740	3049	Schrader Snap-in GEN4 type 433MHz GM (China)	6
Yukon	K2UG	2014-03	EOP	22853740	3049	Schrader Snap-in GEN4 type 433MHz GM (China)	330
Yukon	GMT922(2)	2005-12	2013-12	22853740	3049	Schrader Snap-in GEN4 type 433MHz GM (China)	218
<b>Great Wall</b>							
Steed	K2/K4	2014-06	EOP	3641110AK80XA	4083	SATE Clamp-in 433MHz Great Wall	1,738
Voleex C20R	CH035	2014-03	EOP	3641110AK80XA	4083	SATE Clamp-in 433MHz Great Wall	17
Voleex C30	CH041	2014-03	EOP	3641110AK80XA	4083	SATE Clamp-in 433MHz Great Wall	176
<b>Honda</b>							
Accord	2GA	2013-07	EOP	42753-TL0-G520	4072	Conti Clamp-in TG1C 433MHz Conti Honda	2
Accord	QE	2013-07	EOP	42753-TL0-G520	4072	Conti Clamp-in TG1C 433MHz Conti Honda	854
Accord	QP	2013-07	EOP	42753-TL0-G520	4072	Conti Clamp-in TG1C 433MHz Conti Honda	342
Jazz	2AP,2HQ	2014-06	EOP	42753-TL0-G520	4072	Conti Clamp-in TG1C 433MHz Conti Honda	8
Jazz	2WF	2014-09	EOP	42753-TL0-G520	4072	Conti Clamp-in TG1C 433MHz Conti Honda	82,890
Jazz	2AP	2014-03	EOP	42753-TL0-G520	4072	Conti Clamp-in TG1C 433MHz Conti Honda	1,374
<b>Hummer</b>							
H2	H2	2002-04	2008-12	25789964	3049	Schrader Snap-in GEN4 type 433MHz GM	130
H3	GMT345	2005-03	2012-01	25789964	3049	Schrader Snap-in GEN4 type 433MHz GM	66

# Make Model Year Look Up

Europe, Ver. 2.0,  
Update 09/2017

Car Make	Car Model Code	Start of application	End of application	OE sensor reference	Schrader Part Number (NEW)	Sensor Description	Direct TPMS Car Park in market 2017
<b>Hyundai</b>							
C-Green	AE	2016-01	EOP	52933-3X300	4053	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	24
Elantra	AD	2015-01	EOP	52933-D4100	4085	Conti Clamp-in TG1C 433MHz HKMC Conti LoS Optima	4,072
Elantra	HD	2014-03	EOP	52933-3X300	4053	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	33
Elantra	MD	2014-03	EOP	52933-3X300	4053	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	56
Equus	HI	2016-03	EOP	52933-2M650	4060	Conti Clamp-in TG1C 433MHz HKMC	2
Genesis	DH	2014-03	EOP	52933-3N100	4059	Conti Clamp-in TG1C 433MHz HKMC	524
Genesis Coupe	BK	2014-03	EOP	52933-3N100	4059	Conti Clamp-in TG1C 433MHz HKMC	23
Genesis Coupe	VK	2015-11	EOP	52933-3N100	4059	Conti Clamp-in TG1C 433MHz HKMC	17
Genesis Coupe	IK	2017-01	EOP	52933-3N100	4059	Conti Clamp-in TG1C 433MHz HKMC	1
Grandeur	IG	2017-01	EOP	52933-D4100	4085	Conti Clamp-in TG1C 433MHz HKMC Conti LoS Optima	9
H1	TQ	2014-03	EOP	52933-4H100	4089	Conti Clamp-in TG1C 433MHz HKMC H1 Starex	352
H1 Combi	TQ	2014-03	EOP	52933-4H100	4089	Conti Clamp-in TG1C 433MHz HKMC H1 Starex	63
H1 Van	TQ	2014-03	EOP	52933-4H100	4089	Conti Clamp-in TG1C 433MHz HKMC H1 Starex	446
H100	HR	2014-03	EOP	52933-A5100	4060	Conti Clamp-in TG1C 433MHz HKMC	5
H100	TQ	2014-03	EOP	52933-4H100	4089	Conti Clamp-in TG1C 433MHz HKMC H1 Starex	2,632
H100 Van	HR	2014-03	EOP	52933-A5100	4060	Conti Clamp-in TG1C 433MHz HKMC	180
H100 Van	LU	2017-01	EOP	52933-A5100	4060	Conti Clamp-in TG1C 433MHz HKMC	347
H100 Van	TQ	2014-03	EOP	52933-4H100	4089	Conti Clamp-in TG1C 433MHz HKMC H1 Starex	1,016
H100 Van	AU	2014-01	EOP	52933-A5100	4060	Conti Clamp-in TG1C 433MHz HKMC	246
i10	PA	2007-10	2013-10	52933-2L600	4026	Conti Clamp-in TG1B 433MHz HKMC	17
i10	IA	2013-11	EOP	52933-B2100	3059	Schrader Snap-in HS with 20deg angle 433MHz HKMC	277,664
i10	IA,PA	2007-10	EOP	52933-2L600	4026	Conti Clamp-in TG1B 433MHz HKMC	7,258
i20	PB	2008-08	2014-06	52933-1J000	4027	Conti Clamp-in TG1C 433MHz HKMC	218
i20	GB	2014-01	EOP	52933-C1100	3060	Schrader Snap-in Faraday 433MHz HKMC	261,846
i20	GB,IB	2014-11	EOP	52933-C1100	3060	Schrader Snap-in Faraday 433MHz HKMC	67
i30	FD	2007-10	2011-10	52933-2L600	4026	Conti Clamp-in TG1B 433MHz HKMC	2,217
i30	GD	2011-11	2016-07	52933-3N100	4059	Conti Clamp-in TG1C 433MHz HKMC	205,342
i30	PD	2016-08	EOP	52933-D4100	4085	Conti Clamp-in TG1C 433MHz HKMC Conti LoS Optima	61,776
i40	VF	2014-04	EOP	52933-3V600	4078	TRW Clamp-in Variable Angle ver 1 433MHz HKMC	60,518
i40	VF	2011-04	2014-03	52933-3V100	4061	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	1,767
i40	IF	2017-01	EOP	52933-D9100	4087	Conti Clamp-in TG1C 433MHz HKMC Conti QL Platform	6,325
i800	TQ	2014-06	EOP	52933-4H100	4089	Conti Clamp-in TG1C 433MHz HKMC H1 Starex	1,986
iLoad	TQ	2014-03	EOP	52933-4H100	4089	Conti Clamp-in TG1C 433MHz HKMC H1 Starex	443
ioniq	AE	2016-01	EOP	52933-F2000	4085	Conti Clamp-in TG1C 433MHz HKMC Conti LoS Optima	18,764
ix20	JC	2013-05	EOP	52933-2M650	4060	Conti Clamp-in TG1C 433MHz HKMC	120,598
ix20	JC(1)	2010-09	2013-09	52933-1J000	4027	Conti Clamp-in TG1C 433MHz HKMC	88
ix25	OS	2017-01	EOP	52933-2M650	4060	Conti Clamp-in TG1C 433MHz HKMC	14,929
iX35	LM	2014-03	EOP	52933-2S400	4062	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	120,371
iX35	LM	2010-09	2014-02	52933-3M000	4052	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	10,936
ix55	EN	2014-03	EOP	52933-3N100	4059	Conti Clamp-in TG1C 433MHz HKMC	4
Santa Fe	CM	2005-12	EOP	52933-2B000	4057	Lear Snap-in Fixed Angle ver 1 433MHz HKMC	160
Santa Fe	DM	2012-04	EOP	52933-3N100	4059	Conti Clamp-in TG1C 433MHz HKMC	46,578
Starex	A1	2014-03	EOP	52933-4H100	4089	Conti Clamp-in TG1C 433MHz HKMC H1 Starex	9
Sub-Compact SUV	IB	2015-05	EOP	52933-1J000	4027	Conti Clamp-in TG1C 433MHz HKMC	76
Tucson	TL	2015-01	EOP	52933-C1100	3060	Schrader Snap-in Faraday 433MHz HKMC	334,018
Veloster	FS	2011-02	EOP	52933-2V100	3056	Schrader Snap-in GEN4 type 433MHz HKMC	884
Veloster	JS	2017-01	EOP	52933-2V100	3056	Schrader Snap-in GEN4 type 433MHz HKMC	8
<b>Infiniti</b>							
EX	P53B	2007-10	2016-03	407001AY0A	3039	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	1,085
FX	P53C	2014-09	2020-09	40700-6WY0A	4047	Pacific Clamp-in Fixed Angle ver 1 433MHz Nissan	13
FX	P53C	2008-03	2014-08	407001AY0A	3039	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	1,405
G	L53A	2013-04	2019-01	40700-6WY0A	4047	Pacific Clamp-in Fixed Angle ver 1 433MHz Nissan	1
G	L53A	2006-08	2013-03	407001AY0A	3039	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	449
JX	P42J	2014-03	EOP	407003JA0A	4071	Conti Clamp-in TG1C 433MHz Conti Nissan	1
M	L53E	2009-12	EOP	40700JY00B	3038	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	883
Q30	GD1A	2015-10	EOP	A0009050030	3013	Schrader Clamp-in Gen Gamma 433MHz Daimler	22,582
Q50	L53H	2014-03	EOP	407003JA0A	4071	Conti Clamp-in TG1C 433MHz Conti Nissan	8,413
Q50	D53H	2013-04	EOP	407003JA0A	4071	Conti Clamp-in TG1C 433MHz Conti Nissan	60
Q60	L53A	2013-11	EOP	40700-6WY0A	4047	Pacific Clamp-in Fixed Angle ver 1 433MHz Nissan	67
Q60	L53H	2016-01	EOP	407003JA0A	4071	Conti Clamp-in TG1C 433MHz Conti Nissan	16
Q60	D53H	2015-05	EOP	407003JA0A	4071	Conti Clamp-in TG1C 433MHz Conti Nissan	805
Q70	L53E	2013-11	EOP	40700-6WY0A	4047	Pacific Clamp-in Fixed Angle ver 1 433MHz Nissan	1,279
QX30	GD1A	2016-01	EOP	A0009050030	3013	Schrader Clamp-in Gen Gamma 433MHz Daimler	10,310
QX40	PD2A	2017-04	EOP	40700-6WY0A	4047	Pacific Clamp-in Fixed Angle ver 1 433MHz Nissan	23
QX50	P53B	2014-06	EOP	40700-6WY0A	4047	Pacific Clamp-in Fixed Angle ver 1 433MHz Nissan	467
QX50	P53B(2)	2015-11	EOP	407003JA0A	4071	Conti Clamp-in TG1C 433MHz Conti Nissan	45
QX70	P53C	2013-08	EOP	40700-6WY0A	4047	Pacific Clamp-in Fixed Angle ver 1 433MHz Nissan	4,821
QX70	P53J	2016-01	EOP	407003JA0A	4071	Conti Clamp-in TG1C 433MHz Conti Nissan	40



Car Make	Car Model Code	Start of application	End of application	OE sensor reference	Schrader Part Number (NEW)	Sensor Description	Direct TPMS Car Park in market 2017
<b>Jaguar</b>							
F-PACE	X761	2016-01	EOP	C2D47173	4066	Conti Clamp-in TG1C 433MHz JLR	36,671
F-Type	X152	2012-10	EOP	C2D21599	4019	Conti Clamp-in TG1C 433MHz Ford	15,223
I-PACE	X590	2017-01	EOP	GX63-1A159-AA	4066	Conti Clamp-in TG1C 433MHz JLR	468
RD-7	X760	2015-04	EOP	GX63-1A159-AA	4066	Conti Clamp-in TG1C 433MHz JLR	78
XE	X760	2015-01	EOP	C2D47173	4066	Conti Clamp-in TG1C 433MHz JLR	64,178
XF	X250	2007-11	EOP	LR032835	4023	Conti Clamp-in TG1B 433MHz Ford	25,116
XF	X260	2015-09	EOP	C2D47173	4066	Conti Clamp-in TG1C 433MHz JLR	34,758
XJ	X351	2014-03	EOP	C2D21599	4019	Conti Clamp-in TG1C 433MHz Ford	5,139
XJ	X350	2003-05	2009-09	LR032835	4023	Conti Clamp-in TG1B 433MHz Ford	1,299
XK	X150	2014-03	EOP	C2D21599	4019	Conti Clamp-in TG1C 433MHz Ford	7
XK	X150	2006-01	2014-02	LR032835	4023	Conti Clamp-in TG1B 433MHz Ford	430
X-Type	X400	2007-01	EOP	LR032835	4023	Conti Clamp-in TG1B 433MHz Ford	866
<b>Jeep</b>							
C-CUV	MP	2016-01	EOP	68105280AF	4016	Conti Snap-in TG1D 433MHz Chrysler	24
Cherokee	KK	2007-07	EOP	56029359AC	3006	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	456
Cherokee	KL	2013-05	EOP	68249197AA	4068	TRW Snap-in Fixed Angle ver 1 433MHz Chrysler	34,930
Compass	MK49	2014-09	3005	56029481AB	3005	Schrader Snap-in GEN4 type 433MHz Chrysler	1,454
Compass	MK49	2006-05	2014-08	56029481AB	3005	Schrader Snap-in GEN4 type 433MHz Chrysler	8,093
Compass	MP	2017-01	EOP	53305555	4016	Conti Snap-in TG1D 433MHz Chrysler	7,787
Compass	551	2017-01	EOP	53305555	4016	Conti Snap-in TG1D 433MHz Chrysler	1,650
Grand Cherokee	WK74	2016-04	EOP	68252495AA	4018	Conti Clamp-in TG1C 433MHz Jeep FCA	23,398
Grand Cherokee	WK74	2010-07	2016-03	56029398AB	3007	Schrader Snap-in GEN4 type 433MHz Chrysler	38,757
Grand Cherokee	WH	2005-03	2010-06	56029359AC	3006	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	4,330
Patriot	MK74	2006-12	2014-08	56029481AB	3005	Schrader Snap-in GEN4 type 433MHz Chrysler	868
Patriot	MK74	2014-09	EOP	56029481AB	3005	Schrader Snap-in GEN4 type 433MHz Chrysler	3
Renegade	520	2014-03	2019-12	68105280AF	4016	Conti Snap-in TG1D 433MHz Chrysler	191,456
Wrangler	JK72	2010-10	2013-12	56029398AB	3007	Schrader Snap-in GEN4 type 433MHz Chrysler	5,300
Wrangler	JK72	2014-03	EOP	68241067AA	3007	Schrader Snap-in GEN4 type 433MHz Chrysler	20,445
Wrangler	JK72	2006-08	2010-09	56029359AC	3006	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	2,165
Wrangler	JK72(2)	2014-01	EOP	68241067AA	3007	Schrader Snap-in GEN4 type 433MHz Chrysler	75
Wrangler (LCV)	JK72	2006-08	EOP	56029359AC	3006	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	885
<b>Kia</b>							
Cadenza	YG	2016-01	EOP	52933-D9100	4087	Conti Clamp-in TG1C 433MHz HKMC Conti QL Platform	1
Carens	RP	2012-12	EOP	52933-3N100	4059	Conti Clamp-in TG1C 433MHz HKMC	68,316
Carens	UN	2014-03	EOP	52933-3N100	4059	Conti Clamp-in TG1C 433MHz HKMC	2,292
Carnival	VQ	2014-03	EOP	52933-2M650	4060	Conti Clamp-in TG1C 433MHz HKMC	1
Carnival	YP	2014-07	EOP	52933-B2100	3059	Schrader Snap-in HS with 20deg angle 433MHz HKMC	5
Cee'd	ED	2006-01	2012-02	52933-2L600	4026	Conti Clamp-in TG1B 433MHz HKMC	22
Cee'd	JD	2012-03	EOP	52933-3N100	4059	Conti Clamp-in TG1C 433MHz HKMC	33,320
Grand Carnival	YP	2014-09	EOP	52933-2M650	4060	Conti Clamp-in TG1C 433MHz HKMC	12
New Carens	RP	2013-06	EOP	52933-3N100	4059	Conti Clamp-in TG1C 433MHz HKMC	9
Niro	DE	2016-01	EOP	52933-F2000	4085	Conti Clamp-in TG1C 433MHz HKMC Conti LoS Optima	23,556
Optima	JF	2015-07	EOP	52933-D4100	4085	Conti Clamp-in TG1C 433MHz HKMC Conti LoS Optima	25,269
Optima	TF	2013-08	2015-06	52933-2M650	4060	Conti Clamp-in TG1C 433MHz HKMC	337
Optima	TF	2011-09	2013-08	52933-1J000	4027	Conti Clamp-in TG1C 433MHz HKMC	27
Picanto	TA	2014-04	EOP	52933-3N100	4059	Conti Clamp-in TG1C 433MHz HKMC	138,189
Picanto	JA	2017-01	EOP	52933-D9100	4087	Conti Clamp-in TG1C 433MHz HKMC Conti QL Platform	42,023
Rio	UB	2012-03	EOP	52933-3X300	4053	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	158,299
Rio	QB	2014-03	EOP	52933-3V600	4078	TRW Clamp-in Variable Angle ver 1 433MHz HKMC	8,660
Rio	QB(1)	2000-01	EOP	52933-3J000	4056	Lear Clamp-in Variable Angle ver 1 433MHz HKMC	4
Sorento	UM	2014-01	EOP	52933-2M650	4060	Conti Clamp-in TG1C 433MHz HKMC	42,864
Sorento	XM	2012-07	EOP	52933-2M650	4060	Conti Clamp-in TG1C 433MHz HKMC	475
Sorento	XM	2009-05	2012-09	52933-1J000	4027	Conti Clamp-in TG1C 433MHz HKMC	40
Soul	AM	2008-10	EOP	52933-1J000	4027	Conti Clamp-in TG1C 433MHz HKMC	1
Soul	PS	2013-11	EOP	52933-B2100	3059	Schrader Snap-in HS with 20deg angle 433MHz HKMC	47,066
Sportage	SL	2010-01	EOP	52933-2S410	4062	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	167,922
Sportage	QL	2016-01	EOP	52933-D9100	4087	Conti Clamp-in TG1C 433MHz HKMC Conti QL Platform	272,288
Venga	YN	2014-03	EOP	52933-3N100	4059	Conti Clamp-in TG1C 433MHz HKMC	90,683
<b>Lada</b>							
Granta	2190	2015-04	2016-06	407003VU0A	4032	Conti Clamp-in TG1C 433MHz Renault	930
Kalina	1117-1119	2014-03	EOP	407004CB0A	4034	Conti Snap-in TG1D 433MHz Renault	420
Kalina	2192	2013-07	EOP	407004CB0A	4034	Conti Snap-in TG1D 433MHz Renault	1,227
<b>Lamborghini</b>							
Aventador	LB834	2011-05	EOP	7PP907275F	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	43
Aventador	LB734	2014-03	EOP	7PP907275F	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	910
Gallardo	LB714	2010-02	2013-05	4F0907275D	4009	Beru-Huf Clamp-in Separate valve G2.3 433MHz VW/Porsche	448
Gallardo	LB714	2007-06	2010-01	4F0907275D	4009	Beru-Huf Clamp-in Separate valve G2.3 433MHz VW/Porsche	433
Gallardo	LB724	2013-06	2021-03	7PP907275F	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	45

Car Make	Car Model Code	Start of application	End of application	OE sensor reference	Schrader Part Number (NEW)	Sensor Description	Direct TPMS Car Park in market 2017
Gallardo	LB614	2014-03	EOP	7PP907275F	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	19
Huracan	LB724	2014-03	EOP	7PP907275F	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	36
Huracan	LB624	2014-03	EOP	7PP907275F	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	1,793
Murcielago	LB824	2010-11	EOP	4F0907275D	4009	Beru-Huf Clamp-in Separate valve G2.3 433MHz VW/Porsche	1
<b>Lancia</b>							
Delta	844	2008-04	EOP	51839114	4054	TRW Clamp-in Variable Angle ver 2 433MHz Fiat	2,821
Delta	PK	2014-06	EOP	53104671	3016	Schrader Snap-in GEN4 type 433MHz Fiat	57
Flavia	JS27	2010-10	EOP	68078768AA	4015	Conti Clamp-in TG1C 433MHz Chrysler	654
Flavia	UF	2014-02	EOP	68105280AF	4016	Conti Snap-in TG1D 433MHz Chrysler	8
Musa	848	2004-07	EOP	51750439	3017	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz Fiat/GM	255
Phedra	(blank)	2001-01	2010-10	9673198580/9681102280	4031	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	650
Thema	LX	2011-01	EOP	56029400AD	3008	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	1,765
Voyager	RT	2013-08	EOP	9673198580/9681102280	4031	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	3,660
Voyager	RT	2007-07	2011-01	56029359AC	3006	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	2,165
Voyager	RT	2011-02	2013-07	56029398AB	3007	Schrader Snap-in GEN4 type 433MHz Chrysler	25
Voyager	RU	2015-11	EOP	68105280AF	4016	Conti Snap-in TG1D 433MHz Chrysler	16
Voyager	RA	2015-11	EOP	68105280AF	4016	Conti Snap-in TG1D 433MHz Chrysler	17
Voyager	RT, RU	2011-01	2015-10	56029398AB	3007	Schrader Snap-in GEN4 type 433MHz Chrysler	5
<b>Land Rover</b>							
Defender	L316	2014-06	EOP	LR021935	4019	Conti Clamp-in TG1C 433MHz Ford	26,053
Defender (LCV)	L316	2014-06	EOP	LR021935	4019	Conti Clamp-in TG1C 433MHz Ford	37
Discovery	L319	2009-09	EOP	LR021935	4019	Conti Clamp-in TG1C 433MHz Ford	37,230
Discovery	L462	2016-02	EOP	LR070840	4066	Conti Clamp-in TG1C 433MHz JLR	19,820
Discovery (LCV)	L319	2004-07	2009-09	RQH500470	4023	Conti Clamp-in TG1B 433MHz Ford	58
Discovery (LCV)	L462	2017-02	EOP	LR070840	4066	Conti Clamp-in TG1C 433MHz JLR	5
Discovery Sport	L550	2014-01	EOP	LR021935	4019	Conti Clamp-in TG1C 433MHz Ford	115,613
Freelander	L359	2014-03	EOP	LR021935	4019	Conti Clamp-in TG1C 433MHz Ford	8,415
Freelander	L550	2006-10	EOP	LR021935	4019	Conti Clamp-in TG1C 433MHz Ford	93
Range Rover	L322	2005-01	2009-12	RQH500470	4023	Conti Clamp-in TG1B 433MHz Ford	1
Range Rover	L405	2015-06	EOP	LR070840	4066	Conti Clamp-in TG1C 433MHz JLR	31,991
Range Rover	L405	2010-01	EOP	LR021935	4019	Conti Clamp-in TG1C 433MHz Ford	45,495
Range Rover (LCV)	L322	2002-03	2003-02	YDB000060	4003	Beru-Huf Clamp-in Separate valve G1,2 plus 433MHz Land Rover	217
Range Rover Evoque	L538	2012-01	EOP	LR021935	4019	Conti Clamp-in TG1C 433MHz Ford	200,212
Range Rover Grand Evoque	L560	2017-01	EOP	C2D47173	4066	Conti Clamp-in TG1C 433MHz JLR	14,934
Range Rover Sport	L494	2014-03	EOP	FW931A159AB	4019	Conti Clamp-in TG1C 433MHz Conti Volvo	88,969
Range Rover Sport	L494	2015-06	EOP	LR070840	4066	Conti Clamp-in TG1C 433MHz JLR	63,995
<b>Lexus</b>							
CT	080A	2014-06	EOP	42607-30070	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	29,310
GS	920L	2014-06	EOP	42607-30070	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	5,106
IS	030L	2014-06	EOP	42607-30070	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	2
IS	400A	2013-07	EOP	42607-30070	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	24,740
IS	720A	2015-02	EOP	42607-30070	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	49
LF-A	973L	2014-06	EOP	42607-30070	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1
LS	250L	2014-01	EOP	42607-30070	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	427
LS	200B	2017-01	EOP	42607-30070	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	4
NX	600A	2014-03	EOP	42607-30070	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	46,253
RC	720A	2014-01	EOP	42607-30070	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	2,857
RX	640L	2014-06	2016-09	42607-30070	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	5,061
RX	740A	2016-10	EOP	42607-48020	4114	Pacific Clamp-in Fixed Angle ver 1 433MHz Lexus	36,039
<b>Lotus</b>							
3-ELEVEN	3-ELEVEN	2016-01	EOP	B121G600F	3058	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	46
Elise	Monza	2008-01	EOP	B121G600F	3058	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	1,371
Evora	Eagle	2010-01	EOP	B121G600F	3058	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	876
Exige	Monza	2008-01	EOP	B121G600F	3058	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	1,140
<b>Mahindra</b>							
Bolero	CL/MM	2014-06	EOP	1805BA0131N-A	3062	Schrader Snap-in GEN4 type 433MHz Mahindra	1
Bolero	U301	2015-07	EOP	1805BA0131N-A	3062	Schrader Snap-in GEN4 type 433MHz Mahindra	2
Goa	W105	2015-01	EOP	1805BA0131N-A	3062	Schrader Snap-in GEN4 type 433MHz Mahindra	276
KUV100	S101	2016-01	EOP	1805BA0131N-A	3062	Schrader Snap-in GEN4 type 433MHz Mahindra	19
NC	CL/MM	2014-06	EOP	1805BA0131N-A	3062	Schrader Snap-in GEN4 type 433MHz Mahindra	4
Scorpio	U202	2015-01	EOP	1805BA0131N-A	3062	Schrader Snap-in GEN4 type 433MHz Mahindra	7
Thar	CL/MM	2014-06	EOP	1805BA0131N-A	3062	Schrader Snap-in GEN4 type 433MHz Mahindra	4
XUV500	W201	2014-06	EOP	1805BA0131N-A	3062	Schrader Snap-in GEN4 type 433MHz Mahindra	1,174
<b>Maserati</b>							
Allien	M165	2016-01	EOP	05154876AA	3009	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	33
Ghibli	M157	2013-11	EOP	05154876AA	3009	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	15,151
GranCabrio	M147	2009-09	2015-06	99760602120	4009	Beru-Huf Clamp-in Separate valve G2.3 433MHz Fiat	161
GranCabrio	M147	2015-07	2017-12	05154876AA	3009	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	445

Car Make	Car Model Code	Start of application	End of application	OE sensor reference	Schrader Part Number (NEW)	Sensor Description	Direct TPMS Car Park in market 2017
GranTurismo	M145	2010-09	2013-12	282189	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz Fiat	13
GranTurismo	M145	2014-01	2020-03	05154876AA	3009	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	1,081
GT Coupe	M145	2009-07	2013-12	228887	4009	Beru-Huf Clamp-in Separate valve G2.3 433MHz Fiat	224
GT Coupe	M145	2002-01	2009-06	248887	4009	Beru-Huf Clamp-in Separate valve G1.2 433MHz Fiat Group	217
GT Coupe	M145(2)	2014-01	EOP	05154876AA	3009	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	23
GT Coupe	M138	2014-03	EOP	95518233/670002790	3009	Schrader Clamp-in Gen Gamma 433MHz Maserati / Alfa Romeo	1
Levante	WM	2015-04	2021-09	05154876AA	3009	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	61
Levante	M161	2016-01	EOP	05154876AA	3009	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	6,460
Quattroporte	M139	2010-01	EOP	228887	4009	Beru-Huf Clamp-in Separate valve G2.3 433MHz Fiat	433
Quattroporte	M139	2004-04	2009-12	248887	4009	Beru-Huf Clamp-in Separate valve G1.2 433MHz Fiat Group	437
Quattroporte	M156	2013-01	EOP	05154876AA	3009	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	2,645
<b>Mazda</b>							
2	J03	2014-05	EOP	BHB637140	4028	Conti Clamp-in TG1C 433MHz Mazda	27,948
2	J64F	2007-12	EOP	BBP337140B	4028	Conti Clamp-in TG1C 433MHz Mazda	21
2	J03W	2014-01	EOP	BHB637140	4028	Conti Clamp-in TG1C 433MHz Mazda	64,181
3	J68C	2009-06	2013-03	GS1D37140	4028	Conti Clamp-in TG1C 433MHz Mazda	991
5	J74G	2010-07	EOP	BHB637140	4028	Conti Clamp-in TG1C 433MHz Mazda	9,027
6	J61A	2012-09	2014-02	BHB637140	4028	Conti Clamp-in TG1C 433MHz Mazda	1
6	J61A	2007-08	2012-08	GS1D37140	4028	Conti Clamp-in TG1C 433MHz Mazda	173
6	J71E	2014-03	EOP	BBP337140B	4028	Conti Clamp-in TG1C 433MHz Mazda	66,516
B-Series	J26E	2015-06	EOP	BB5T-1A180-AA	3020	Schrader Snap-in GEN4 type 433MHz Ford	3
BT-50	J26E	2011-05	EOP	BB5T-1A180-AA	3020	Schrader Snap-in GEN4 type 433MHz Ford	6
CX-3	BCUV	2014-10	2019-10	BBP337140B	4028	Conti Clamp-in TG1C 433MHz Mazda	260
CX-3	J03K	2015-01	EOP	BBP337140B	4028	Conti Clamp-in TG1C 433MHz Mazda	118,999
CX-5	J53C	2011-11	2014-02	BBP337140B	4028	Conti Clamp-in TG1C 433MHz Mazda	155,203
CX-5	J53C(2)	2014-03	2016-12	BBP337140B	4028	Conti Clamp-in TG1C 433MHz Mazda	95
CX-5	J72A	2017-01	2018-12	BBP337140B	4028	Conti Clamp-in TG1C 433MHz Mazda	4,148
CX-7	J31H	2009-06	EOP	GS1D37140	4028	Conti Clamp-in TG1C 433MHz Mazda	81
CX-9	J50C	2010-08	2015-12	BHB637140	4028	Conti Clamp-in TG1C 433MHz Mazda	879
MX-5	J04C	2010-03	2014-02	BBP337140B	4028	Conti Clamp-in TG1C 433MHz Mazda	82
MX-5	J12A	2015-01	2019-12	BHB637140	4028	Conti Clamp-in TG1C 433MHz Mazda	21,757
MX-5	J04C(2)	2014-03	2014-12	BHB637140	4028	Conti Clamp-in TG1C 433MHz Mazda	18
Premacy	J54L	2014-03	EOP	BHB637140	4028	Conti Clamp-in TG1C 433MHz Mazda	3
<b>Maybach</b>							
57/62	W240	2002-09	EOP	A0055422318	4001	Beru-Huf Clamp-in Separate valve G1.2 433MHz Daimler	221
<b>McLaren</b>							
MP4-12C	P11	2011-04	EOP	11B0015CP	4009	Beru-Huf Clamp-in Separate valve G1.2 433MHz Fiat Group	18
P1	P12	2013-01	EOP	11B0015CP	4009	Beru-Huf Clamp-in Separate valve G1.2 433MHz Fiat Group	3
P13	P13	2015-08	EOP	11B0015CP	4009	Beru-Huf Clamp-in Separate valve G1.2 433MHz Fiat Group	30
Sports Series	P13	2015-01	EOP	11B0015CP	4009	Beru-Huf Clamp-in Separate valve G1.2 433MHz Fiat Group	1,587
Super Series	P11	2014-03	EOP	11B0015CP	4009	Beru-Huf Clamp-in Separate valve G1.2 433MHz Fiat Group	591
Ultimate Series	P12	2014-03	EOP	11B0015CP	4009	Beru-Huf Clamp-in Separate valve G1.2 433MHz Fiat Group	17
<b>Mercedes-Benz</b>							
A-Class	S176	2014-03	EOP	A0009050030	3013	Schrader Clamp-in Gen Gamma 433MHz Daimler	390,579
B-Class	W246	2013-01	EOP	A0009057200	3011	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	260,679
C-Class	C204	2014-03	EOP	A0009057200	3011	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	4,768
C-Class	C205	2015-01	EOP	A0009050030	3013	Schrader Clamp-in Gen Gamma 433MHz Daimler	68,265
C-Class	W204	2013-01	EOP	A0009057200	3011	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	5,176
C-Class	W205	2014-01	2021-03	A0009050030	3013	Schrader Clamp-in Gen Gamma 433MHz Daimler	467,653
C-Class	W203	2000-01	2006-12	A0055422318	4001	Beru-Huf Clamp-in Separate valve G1.2 433MHz Daimler	13
C-Class Coupe	C204	2012-12	EOP	A0009057200	3011	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	23
C-Class Coupe	C205	2015-06	EOP	A0009050030	3013	Schrader Clamp-in Gen Gamma 433MHz Daimler	76
Citan	VS10	2012-09	EOP	40700932R-D	3041	Schrader Snap-in HS with 20deg angle 433MHz Renault	62,864
Citan Combi	VS10	2014-01	EOP	40700932R-D	3041	Schrader Snap-in HS with 20deg angle 433MHz Renault	15,378
CL	C216	2006-07	2014-03	A0025406717	4040	Conti Clamp-in MB_no RF link Siemens VDO 433MHz Daimler	78
CL	C217	2014-04	2020-06	A0009057200	3011	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	77
CL	C215	1999-07	2005-09	A0055422318	4001	Beru-Huf Clamp-in Separate valve G1.2 433MHz Daimler	130
CLA	C117	2012-12	2014-11	A0009057200	3011	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	174
CLA	C117	2014-12	EOP	A0009050030	3013	Schrader Clamp-in Gen Gamma 433MHz Daimler	181,126
CLC	C203	2014-06	EOP	A0009057200	3011	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	1
CLK	C209	2014-06	EOP	A0009057200	3011	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	1

Car Make	Car Model Code	Start of application	End of application	OE sensor reference	Schrader Part Number (NEW)	Sensor Description	Direct TPMS Car Park in market 2017
CLS	C218	2014-12	EOP	A0009050030	3013	Schrader Clamp-in Gen Gamma 433MHz Daimler	24,728
CLS	C218	2013-01	2014-11	A0009057200	3011	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	4,282
CLS	C218	2009-08	2012-12	A0009054100	3011	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	2,166
CLS	C219	2004-10	2005-06	A0055422318	4001	Beru-Huf Clamp-in Separate valve G1.2 433MHz Daimler	217
CLS	C219	2005-01	2009-07	A0025406717	4040	Conti Clamp-in MB_no RF link Siemens VDO 433MHz Daimler	260
E-Class	C207	2014-06	EOP	A0009050030	3013	Schrader Clamp-in Gen Gamma 433MHz Daimler	34,364
E-Class	C238	2017-07	EOP	A0009052102	3057	Schrader Clamp-in Gen Delta 433MHz Daimler	7,470
E-Class	W212	2014-12	EOP	A0009050030	3013	Schrader Clamp-in Gen Gamma 433MHz Daimler	90,160
E-Class	W212	2013-01	2014-11	A0009057200	3011	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	25,095
E-Class	W212	2009-04	2012-12	A0009054100	3011	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	4,677
E-Class	W213	2015-11	2023-03	A0009052102	3057	Schrader Clamp-in Gen Delta 433MHz Daimler	157,459
E-Class Coupe	C207	2009-01	2012-12	A0009054100	3011	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	1,559
G-Class	G463/461	2014-03	EOP	A0009050030	3013	Schrader Clamp-in Gen Gamma 433MHz Daimler	11,434
GLA	X156	2014-12	2020-12	A0009050030	3013	Schrader Clamp-in Gen Gamma 433MHz Daimler	181,342
GLA	X156	2014-01	2014-11	A0009057200	3011	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	26,318
GLC	X253	2015-01	EOP	A0009050030	3013	Schrader Clamp-in Gen Gamma 433MHz Daimler	142,494
GLC Coupe	C253	2016-01	EOP	A0009050030	3013	Schrader Clamp-in Gen Gamma 433MHz Daimler	20,926
GL-Class	X164	2009-06	2012-12	A0009054100	3011	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	1,302
GL-Class	X164	2006-09	2009-07	A0025406717	4040	Conti Clamp-in MB_no RF link Siemens VDO 433MHz Daimler	43
GL-Class	X166	2013-01	EOP	A0009057200	3011	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	7,108
GLE	W166	2015-01	EOP	A0009050030	3013	Schrader Clamp-in Gen Gamma 433MHz Daimler	55,244
GLE Coupe	C292	2015-01	EOP	A0009050030	3013	Schrader Clamp-in Gen Gamma 433MHz Daimler	29,474
GLK	X204	2012-12	2015-09	A0009057200	3011	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	22,178
GLK	X253	2015-10	EOP	A0009050030	3013	Schrader Clamp-in Gen Gamma 433MHz Daimler	78
GLS	X166	2015-01	EOP	A0009050030	3013	Schrader Clamp-in Gen Gamma 433MHz Daimler	8,605
GT	C190	2014-01	EOP	A0009050030	3013	Schrader Clamp-in Gen Gamma 433MHz Daimler	7,794
G-Wagen	G463/461	2013-01	2022-12	A0009057200	3011	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	71
G-Wagen	G463/461	2007-04	2012-12	A0009054100	3011	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	654
G-Wagen (LCV)	G463/461	2012-12	2022-12	A0009057200	3011	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	14
MLC	C292	2012-12	EOP	A0009050030	3013	Schrader Clamp-in Gen Gamma 433MHz Daimler	75
ML-Class	W166	2011-07	2012-12	A0009054100	3011	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	3
ML-Class	W166	2014-07	EOP	A0009050030	3013	Schrader Clamp-in Gen Gamma 433MHz Daimler	10,968
R-Class	V251	2013-01	EOP	A0009057200	3011	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	68
R-Class	V251	2005-06	2009-07	A0025406717	4040	Conti Clamp-in MB_no RF link Siemens VDO 433MHz Daimler	325
R-Class	V251	2009-07	2012-12	A0009054100	3011	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	652
S-Class	W221	2005-10	2009-06	A0025406717	4040	Conti Clamp-in MB_no RF link Siemens VDO 433MHz Daimler	2,165
S-Class	W221	2013-01	2013-06	A0009057200	3011	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	3
S-Class	W221	2009-07	2012-12	A0009054100	3011	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	2,168
S-Class	W222	2014-12	EOP	A0009050030	3013	Schrader Clamp-in Gen Gamma 433MHz Daimler	34,593
S-Class	W220	1999-07	2005-09	A0055422318	4001	Beru-Huf Clamp-in Separate valve G1.2 433MHz Daimler	650
S-Class Coupe	C217	2014-07	EOP	A0009050030	3013	Schrader Clamp-in Gen Gamma 433MHz Daimler	10,472
S-Class Pullman	X222	2014-03	EOP	A0009050030	3013	Schrader Clamp-in Gen Gamma 433MHz Daimler	46
SL	R230	2005-01	2009-07	A0025406717	4040	Conti Clamp-in MB_no RF link Siemens VDO 433MHz Daimler	866
SL	R230	2001-01	2005-05	A0055422318	4001	Beru-Huf Clamp-in Separate valve G1.2 433MHz Daimler	650
SL	R231	2013-01	2014-05	A0009057200	3011	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	834
SL	R231	2009-08	2012-12	A0009054100	3011	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	1,518
SL	R231	2014-06	EOP	A0009050030	3013	Schrader Clamp-in Gen Gamma 433MHz Daimler	4,997
SLC	R172	2016-01	EOP	A0009050030	3013	Schrader Clamp-in Gen Gamma 433MHz Daimler	16,748
SLK	R172	2014-12	EOP	A0009050030	3013	Schrader Clamp-in Gen Gamma 433MHz Daimler	11,374
SLK	R172	2013-01	2014-11	A0009057200	3011	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	7,961
SLR	C199	2004-01	2010-12	A0055422318	4001	Beru-Huf Clamp-in Separate valve G1.2 433MHz Daimler	433
SLS	C197	2013-01	2023-09	A0009057200	3011	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	323
SLS	C197	2010-02	2012-12	A0009054100	3011	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	871
Sprinter	NCV3	2014-06	EOP	A0009057200	3011	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	335,198
Sprinter (LCV)	NCV3	2006-06	2011-10	A0025409517	4038	Conti Clamp-in MB_no RF link Siemens VDO 433MHz Daimler	4,330
Sprinter Combi	NCV3	2013-01	EOP	A0009057200	3011	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	29,052

Car Make	Car Model Code	Start of application	End of application	OE sensor reference	Schrader Part Number (NEW)	Sensor Description	Direct TPMS Car Park in market 2017
Vario	T2N	2014-03	EOP	A4479050500	3012	Schrader Snap-in HS with 10deg angle 433MHz Daimler	38
V-Class	VS20	2014-03	EOP	A4479050500	3012	Schrader Snap-in HS with 10deg angle 433MHz Daimler	84,529
V-Class	W638	2014-06	EOP	A4479050500	3012	Schrader Snap-in HS with 10deg angle 433MHz Daimler	408
Viano	VS20	2014-06	EOP	A4479050500	3012	Schrader Snap-in HS with 10deg angle 433MHz Daimler	4
Viano	W639	2014-03	EOP	A4479050500	3012	Schrader Snap-in HS with 10deg angle 433MHz Daimler	4,033
Viano (LCV)	VS20	2014-08	2023-07	A4479050500	3012	Schrader Snap-in HS with 10deg angle 433MHz Daimler	28
Viano (LCV) (Mid-Line)	W639	2003-07	2014-06	A0025409517	4038	Conti Clamp-in MB_no RF link Siemens VDO 433MHz Daimler	2,165
Vito	VS20	2014-07	EOP	A4479050500	3012	Schrader Snap-in HS with 10deg angle 433MHz Daimler	141,449
Vito Combi	W639	2014-03	EOP	A0025409517	4038	Conti Clamp-in MB_no RF link Siemens VDO 433MHz Daimler	3
Vito Combi	VS20	2012-12	2023-04	A0009057200	3011	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	43,128
<b>Mini</b>							
Clubman	F54	2015-07	2016-12	6855539	4043	Conti Clamp-in TG1C 433MHz BMW	34,423
Clubman	R55	2009-08	EOP	36106886227	4010	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	43
Clubman	R55	2007-08	2009-09	36236798726	4007	Beru-Huf Clamp-in Separate valve G2.4 433MHz BMW	43
Clubman	F55	2013-11	2016-12	6855539	4043	Conti Clamp-in TG1C 433MHz BMW	650
Clubman	F55	2017-01	EOP	36106881890	4043	Conti Clamp-in TG1C 433MHz BMW	650
Clubman / Cooper	F55	2013-11	2016-12	6855539	4043	Conti Clamp-in TG1C 433MHz BMW	650
Clubman / Cooper	F55	2017-01	EOP	36106881890	4043	Conti Clamp-in TG1C 433MHz BMW	650
Clubvan	F54	2015-07	2016-12	6855539	4043	Conti Clamp-in TG1C 433MHz BMW	25
Clubvan	R55	2012-07	2015-06	36106886227	4010	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	5
Cooper	F55	2013-11	2015-05	6855539	4043	Conti Clamp-in TG1C 433MHz BMW	650
Cooper	F55	2017-01	EOP	36106881890	4043	Conti Clamp-in TG1C 433MHz BMW	650
Cooper	F55	2015-06	2016-12	6855539	4043	Conti Clamp-in TG1C 433MHz BMW	650
Cooper	F57	2015-11	2016-12	6855539	4043	Conti Clamp-in TG1C 433MHz BMW	65
Cooper	F57	2017-01	EOP	36106881890	4043	Conti Clamp-in TG1C 433MHz BMW	65
Countryman	R60	2014-07	EOP	36106798872	4069	Beru-Huf Clamp-in 433MHz BMW	85,351
Countryman	R60	2010-08	2014-06	36106886227	4010	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	18,709
Countryman	F60	2016-01	EOP	6855539	4043	Conti Clamp-in TG1C 433MHz BMW	59,200
Coupe	R58	2011-07	2014-06	36106886227	4010	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	166
Coupe	R58	2014-07	EOP	36106798872	4069	Beru-Huf Clamp-in 433MHz BMW	1,458
Mini	F56	2013-12	2016-12	6855539	4043	Conti Clamp-in TG1C 433MHz BMW	286,416
Mini	R56	2014-06	2015-05	6855539	4043	Conti Clamp-in TG1C 433MHz BMW	34
Paceman	R61	2012-11	2014-06	36106886227	4010	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	3,059
Paceman	R61	2014-07	EOP	36106798872	4069	Beru-Huf Clamp-in 433MHz BMW	10,198
Roadster	R59	2011-12	2014-06	36106886227	4010	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	285
Roadster	R59	2014-07	EOP	36106798872	4069	Beru-Huf Clamp-in 433MHz BMW	1,121
<b>Mitsubishi</b>							
ASX	ZC	2014-06	EOP	4250C477	4073	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	131,151
Attrage	EL-L	2014-03	EOP	4250C275	4079	Conti Snap-in TG1D 433MHz Conti Mitsubishi	566
B-SUV	BSUV	2017-01	EOP	4250C275	4079	Conti Snap-in TG1D 433MHz Conti Mitsubishi	28
Colt	ZM	2014-03	EOP	4250C275	4079	Conti Snap-in TG1D 433MHz Conti Mitsubishi	1
C-SUV	BSUV	2017-01	EOP	4250C477	4073	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	28
i-MiEV	TQ	2014-06	EOP	4250C477	4073	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	1,878
L200	CR	2014-06	EOP	4250C477	4073	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	60
L200	4P00	2014-11	EOP	4250C477	4073	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	41,113
L200	4P00,CR	2014-06	EOP	4250C477	4073	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	6,387
Lancer	GS41	2014-06	EOP	4250C477	4073	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	10,399
Lancer	JT41	2014-06	EOP	4250C477	4073	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	3
Mirage	EL	2013-05	EOP	4250C275	4079	Conti Snap-in TG1D 433MHz Conti Mitsubishi	5,633
Outlander	RE	2014-06	EOP	4250C477	4073	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	125,397
Outlander	GS45X,RE	2014-03	EOP	4250C477	4073	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	2,235
Pajero	BK	2014-07	EOP	4250C477	4073	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	20,368

Car Make	Car Model Code	Start of application	End of application	OE sensor reference	Schrader Part Number (NEW)	Sensor Description	Direct TPMS Car Park in market 2017
Pajero	GSPJ	2016-07	EOP	4250C275	4079	Conti Snap-in TG1D 433MHz Conti Mitsubishi	6
Pajero	4T45	2017-01	EOP	4250C275	4079	Conti Snap-in TG1D 433MHz Conti Mitsubishi	6
Pajero (LCV)	BK	2014-07	EOP	4250C275	4079	Conti Snap-in TG1D 433MHz Conti Mitsubishi	14
Pajero Sport	4P45	2015-01	EOP	4250C275	4079	Conti Snap-in TG1D 433MHz Conti Mitsubishi	1,805
Pinin Pajero	MINICAB	2014-03	EOP	4250C275	4079	Conti Snap-in TG1D 433MHz Conti Mitsubishi	1
Spacestar	EL	2014-07	EOP	4250C477	4073	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	81,971
<b>Nissan</b>							
370Z	C53D	2008-10	2014-06	40700JY00B	3038	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	3,627
370Z	C53D(2)	2014-07	2016-03	40700-6WY0A	4047	Pacific Clamp-in Fixed Angle ver 1 433MHz Nissan	43
370Z	RC53D	2009-03	EOP	40700JY00B	3038	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	1,195
370Z	RC53D(2)	2016-04	EOP	40700-6WY0A	4047	Pacific Clamp-in Fixed Angle ver 1 433MHz Nissan	43
Atleon	F91A	2014-06	EOP	407003VU0A	4032	Conti Clamp-in TG1C 433MHz Renault	4
Atleon	F91B	2014-03	EOP	407003VU0A	4032	Conti Clamp-in TG1C 433MHz Renault	24
Atleon	F91G	2014-01	EOP	407003VU0A	4032	Conti Clamp-in TG1C 433MHz Renault	28
Cabstar	F91A	2014-06	EOP	407003VU0A	4032	Conti Clamp-in TG1C 433MHz Renault	15,033
Cabstar	F91A(2)	2017-01	EOP	407003VU0A	4032	Conti Clamp-in TG1C 433MHz Renault	5,778
Cabstar E	F91A	2014-06	EOP	407003VU0A	4032	Conti Clamp-in TG1C 433MHz Renault	3,895
C-Hatch	B12L	2014-10	EOP	407003VU0A	4032	Conti Clamp-in TG1C 433MHz Renault	97
Cube	X12B	2014-10	EOP	407003VU0A	4032	Conti Clamp-in TG1C 433MHz Renault	1
Evalia	X11M	2014-03	EOP	407003VU0A	4032	Conti Clamp-in TG1C 433MHz Renault	489
Frontier	H60A	2014-09	2023-03	407003VU0A	4032	Conti Clamp-in TG1C 433MHz Renault	3
GT-R	D52E	2016-01	EOP	407003VU0A	4032	Conti Clamp-in TG1C 433MHz Renault	1,017
GT-R	D52E	2007-09	2014-06	40700JY00B	3038	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	2,409
GT-R	D52E	2014-07	2015-12	40700-6WY0A	4047	Pacific Clamp-in Fixed Angle ver 1 433MHz Nissan	2,805
Interstar	X70	2014-06	EOP	40700932R-D	3041	Schrader Snap-in HS with 20deg angle 433MHz Renault	1
Juke	P12C	2015-10	2016-12	40700-5ZH0A	4115	Pacific Snap-In 433Mhz Nissan	224,235
Juke	P12C	2010-05	2015-09	40700-6WY0A	4047	Pacific Clamp-in Fixed Angle ver 1 433MHz Nissan	130,052
Leaf	B12G	2010-10	2015-09	40700-6WY0A	4047	Pacific Clamp-in Fixed Angle ver 1 433MHz Nissan	54,744
Micra	B02A	2010-03	2016-11	40700-3HN0B	4077	Pacific Clamp-in Fixed Angle 433MHz Nissan	143,143
Micra	B02E	2016-12	EOP	407004CB0A	4034	Conti Snap-in TG1D 433MHz Renault	83,352
Murano	P42D	2007-10	EOP	40700JY00B	3038	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	19
Murano	P42M	2014-10	2015-05	407003JA0A	4071	Conti Clamp-in TG1C 433MHz Conti Nissan	46
Murano	P42M	2015-06	EOP	40700-6WY0A	4047	Pacific Clamp-in Fixed Angle ver 1 433MHz Nissan	1,021
Navara	H60A	2014-09	EOP	40700JY00B	3038	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	52,496
Navara	H61B	2004-10	EOP	40700JY00B	3038	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	362
Navara	D22.H61B	2014-03	EOP	40700JY00B	3038	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	3
Note	J02C	2013-08	EOP	407003VU0A	4032	Conti Clamp-in TG1C 433MHz Renault	140,759
Note	L11E	2014-03	EOP	407003VU0A	4032	Conti Clamp-in TG1C 433MHz Renault	13
NP300	D22	2014-03	EOP	407003VU0A	4032	Conti Clamp-in TG1C 433MHz Renault	168
NP300	H60A	2014-09	EOP	407003VU0A	4032	Conti Clamp-in TG1C 433MHz Renault	131
NT500	F91G	2014-03	EOP	407003VU0A	4032	Conti Clamp-in TG1C 433MHz Renault	2,028
NV200	X11M	2014-04	2016-09	407003VU0A	4032	Conti Clamp-in TG1C 433MHz Renault	55,873
NV200 Combi	X11M	2014-04	EOP	407003VU0A	4032	Conti Clamp-in TG1C 433MHz Renault	17,572

Car Make	Car Model Code	Start of application	End of application	OE sensor reference	Schrader Part Number (NEW)	Sensor Description	Direct TPMS Car Park in market 2017
NV300	X82	2014-09	EOP	40700932R-D	3041	Schrader Snap-in HS with 20deg angle 433MHz Renault	9,248
NV300 Combi	X82	2014-09	EOP	40700932R-D	3041	Schrader Snap-in HS with 20deg angle 433MHz Renault	1,864
NV400	X62	2014-06	EOP	40700932R-D	3041	Schrader Snap-in HS with 20deg angle 433MHz Renault	21,098
NV400 Combi	X62	2014-06	EOP	40700932R-D	3041	Schrader Snap-in HS with 20deg angle 433MHz Renault	1,276
NV400 Combi	X61F	2014-03	EOP	407003VU0A	4032	Conti Clamp-in TG1C 433MHz Renault	4
Pathfinder	P61B	2004-08	EOP	40700JY00B	3038	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	157
Pathfinder (LCV)	P61B	2014-06	EOP	407003JA0A	4071	Conti Clamp-in TG1C 433MHz Conti Nissan	4
Patrol	Y62	2014-06	EOP	40700-3HN0B	4077	Pacific Clamp-in Fixed Angle 433MHz Nissan	1
Pixo	YC5	2009-01	EOP	40700JY00B	3038	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	3
Primera	ED	2001-12	2007-05	40700AV600	3037	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz Nissan	1,299
Pulsar	B12L	2014-03	2016-09	407003VU0A	4032	Conti Clamp-in TG1C 433MHz Renault	100,297
Qashqai	P32S	2014-03	2016-09	407003VU0A	4032	Conti Clamp-in TG1C 433MHz Renault	745,371
Sentra	L12F	2014-08	EOP	407003VU0A	4032	Conti Clamp-in TG1C 433MHz Renault	1
Tiida	B11C	2014-03	2016-09	407003VU0A	4032	Conti Clamp-in TG1C 433MHz Renault	1
X-Trail	P32R	2013-11	2016-09	407003VU0A	4032	Conti Clamp-in TG1C 433MHz Renault	137,712
<b>Opel</b>							
Adam	GM 4403	2013-01	2014-07	13581562	3027	Schrader Snap-in GEN4 type 433MHz GM	280
Adam	GM 4403	2014-08	2015-08	13581561	3062	Schrader Snap-in GEN4 type 433MHz GM	45,360
Adam	GM 4403	2015-08	EOP	13581561	3062	Schrader Snap-in GEN4 type 433MHz GM	124,723
Agila	H0310	2014-06	EOP	43139-61M00	4065	Conti Clamp-in TG1C 433MHz Suzuki	4,243
Ampera	D1JOI	2011-09	EOP	13348393	3026	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	339
Ampera	D2JCI	2015-01	EOP	13594222	3071	Schrader Snap-in Faraday 433MHz GM	39
Ampera	D2JOI	2016-01	EOP	13594222	3071	Schrader Snap-in Faraday 433MHz GM	43
Ampera-e	G2KCZ	2017-01	EOP	13589601	3063	Schrader Snap-in Faraday 433MHz GM	3,514
Antara	C105	2010-11	2015-12	22853740	3049	Schrader Snap-in GEN4 type 433MHz GM (China)	11,994
Antara	C105	2016-01	EOP	13598773	3063	Schrader Snap-in Faraday 433MHz GM (China)	3,901
Antara	C105	2006-08	2010-11	25789964	3049	Schrader Snap-in GEN4 type 433MHz GM	520
Astra	D2JO	2015-08	EOP	13594222	3071	Schrader Snap-in Faraday 433MHz GM	479,352
Astra	GM A3300	2014-01	EOP	13348393	3026	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	1,895
Astra	GM A3300	2011-07	2013-12	13348393	3026	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	217
Astra	GM A3300	2004-01	2011-06	13172567	3031	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	2,165
Astra	GM P3400	2009-10	2011-09	13327259	3026	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	5,196
Astra	GM P3400	2014-06	EOP	13581560	3033	Schrader Clamp-in Gen Gamma 433MHz GM	247,604
Astra	GM P3400	2011-09	2014-05	13348393	3026	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	7,501
Astra Van	D2JO	2015-01	EOP	13594222	3071	Schrader Snap-in Faraday 433MHz GM	526
Astra Van	D2JO,GM P3400	2014-06	EOP	13581560	3033	Schrader Clamp-in Gen Gamma 433MHz GM	3
Astra Van	GM A3300	2004-01	EOP	13172567	3031	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	91
Astra Van	GM P3400	2014-06	EOP	13581560	3033	Schrader Clamp-in Gen Gamma 433MHz GM	117
Bolt	G2KCZ	2017-01	EOP	13589601	3063	Schrader Snap-in Faraday 433MHz GM	15
Cascada	D1AO	2013-01	2014-05	13348393	3026	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	798
Cascada	D1AO	2014-06	EOP	13581560	3033	Schrader Clamp-in Gen Gamma 433MHz GM	12,112
Combo	263	2014-06	EOP	53104671	3016	Schrader Snap-in GEN4 type 433MHz Fiat	66,053
Combo Combi	263	2014-06	EOP	53104671	3016	Schrader Snap-in GEN4 type 433MHz Fiat	6,671
Corsa	GM 4530	2014-11	2015-02	13581561	3062	Schrader Snap-in GEN4 type 433MHz GM	33,892
Corsa	GM 4530	2015-03	EOP	13581561	3062	Schrader Snap-in GEN4 type 433MHz GM	668,109
Corsa Van	GM S4400	2007-07	2014-10	13581562	3027	Schrader Snap-in GEN4 type 433MHz GM	12
Corsa Van	GM 4530	2014-03	EOP	13581561	3062	Schrader Snap-in GEN4 type 433MHz GM	15,136
Equinox	D2UC	2017-01	EOP	13594222	3071	Schrader Snap-in Faraday 433MHz GM	9,322
Insignia	GM G3700	2008-10	2011-09	13327259	3026	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	21,650
Insignia	GM G3700	2014-05	EOP	13581560	3033	Schrader Clamp-in Gen Gamma 433MHz GM	169,626
Insignia	GM G3700	2011-09	2014-04	13348393	3026	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	20,869
Insignia	E2JO	2017-04	EOP	13597645	3025	Schrader Snap-in Faraday 433MHz GM	48,683
Karl	M2JO	2015-01	EOP	13598773	3063	Schrader Snap-in Faraday 433MHz GM (China)	105,604
Meriva	GM S4470	2014-08	EOP	13581561	3062	Schrader Snap-in GEN4 type 433MHz GM	114,400
Mokka	G1UO	2012-06	2015-08	22853740	3049	Schrader Snap-in GEN4 type 433MHz GM (China)	177,549
Mokka	G1UO	2015-09	EOP	13598773	3063	Schrader Snap-in Faraday 433MHz GM (China)	381,005
Movano	X62	2009-10	EOP	40700932R-D	3041	Schrader Snap-in HS with 20deg angle 433MHz Renault	66,510
Movano Combi	X62	2009-10	EOP	40700932R-D	3041	Schrader Snap-in HS with 20deg angle 433MHz Renault	2,423
Signum	(blank)	2004-11	EOP	13172567	3031	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	238
Vectra	GM Z3200	2002-01	2008-09	13172567	3031	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	25,980
Viva	M2JO	2015-01	EOP	13598773	3063	Schrader Snap-in Faraday 433MHz GM (China)	30,259
Vivaro	X82	2014-09	EOP	40700932R-D	3041	Schrader Snap-in HS with 20deg angle 433MHz Renault	149,372
Vivaro Combi	X82	2014-09	EOP	40700932R-D	3041	Schrader Snap-in HS with 20deg angle 433MHz Renault	36,509
VXR8	Z2	2014-03	EOP	20925925	3054	Schrader Clamp-in Gen J 433MHz GM	31
Zafira	GM A3370	2011-07	2016-09	13348393	3026	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	10,160
Zafira	GM A3370	2005-04	2011-06	13172567	3031	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	2,165
Zafira	GM P3470	2015-01	EOP	13581560	3033	Schrader Clamp-in Gen Gamma 433MHz GM	177
Zafira Tourer	GM P3470	2014-06	EOP	13581560	3033	Schrader Clamp-in Gen Gamma 433MHz GM	162,768
Zafira Tourer	GM P3470	2011-09	2014-05	13348393	3026	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	17,556

Car Make	Car Model Code	Start of application	End of application	OE sensor reference	Schrader Part Number (NEW)	Sensor Description	Direct TPMS Car Park in market 2017
<b>Peugeot</b>							
1007	PF1	2005-01	EOP	5430T4	4031	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	866
1007	A08	2014-03	EOP	5430T4	4031	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	1
207	A7	2005-11	2013-09	5430T4	4031	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	2,165
207	A7	2013-09	2016-06	9811536380	3002	Schrader Snap-in HS with 20deg angle 433MHz PSA	1,876
3008	T84	2008-11	2013-09	5430W0	3000	Schrader Snap-in GEN4 type 433MHz PSA	88,778
3008	T84	2016-10	EOP	9811536380	3002	Schrader Snap-in HS with 20deg angle 433MHz PSA	9,650
3008	T84	2013-09	2016-09	9811536380	3002	Schrader Snap-in HS with 20deg angle 433MHz PSA	166,092
301	M3/M4	2012-10	EOP	9811536380	3002	Schrader Snap-in HS with 20deg angle 433MHz PSA	8,098
307	T5	2003-11	2006-12	5430T4	4031	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	61,053
307	T5	2007-01	2007-12	5430W0	3000	Schrader Snap-in GEN4 type 433MHz PSA	86,600
308	T7	2015-02	EOP	9811536380	3002	Schrader Snap-in HS with 20deg angle 433MHz PSA	152
308	T7	2013-09	2015-01	9811536380	3002	Schrader Snap-in HS with 20deg angle 433MHz PSA	4,208
308	T7	2007-04	2013-08	5430W0	3000	Schrader Snap-in GEN4 type 433MHz PSA	49,375
4007	I3	2014-03	EOP	1612477080	4073	Conti Clamp-in TG1C 433MHz Conti PSA	1
4008	ZC(2)	2016-09	EOP	1612477080	4073	Conti Clamp-in TG1C 433MHz Conti PSA	53
4008	J3	2014-06	EOP	1612477080	4073	Conti Clamp-in TG1C 433MHz Conti PSA	5,399
407	D2	2004-01	2006-02	5430T4	4031	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	173,200
5008	T87	2009-09	2013-09	5430W0	3000	Schrader Snap-in GEN4 type 433MHz PSA	55,001
5008	T87	2013-09	EOP	9811536380	3002	Schrader Snap-in HS with 20deg angle 433MHz PSA	93,220
508	W2	2010-11	2013-09	5430T4	4031	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	30,323
508	W2	2013-09	2017-06	9811536380	3002	Schrader Snap-in HS with 20deg angle 433MHz PSA	122,540
508 RXH	W24	2013-09	2017-12	9811536380	3002	Schrader Snap-in HS with 20deg angle 433MHz PSA	12
607	Z8	2004-10	2009-03	5430T4	4031	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	7,361
607	Z8	1999-09	2004-10	543002	3004	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Large Grommet Seal 433MHz PSA	10,825
807	V2	2004-10	EOP	5430T4	4031	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	13,459
807	V2	2002-02	2004-09	543002	3004	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Large Grommet Seal 433MHz PSA	9,093
Boxer	X2/50	2013-12	EOP	05154876AA	3009	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	168,441
Boxer Combi	X2/50	2013-12	EOP	05154876AA	3009	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	5,160
Expert	G9	2014-06	EOP	9808859080	3003	Schrader Snap-in HS with 20deg angle 433MHz PSA HP	35,080
Expert (LCV)	G9	2006-09	2013-12	9677130580	3001	Schrader Snap-in GEN4 type 433MHz PSA HP	43
Expert Tepee	G9	2014-06	EOP	9808859080	3003	Schrader Snap-in HS with 20deg angle 433MHz PSA HP	6,352
iOn	S3	2014-06	EOP	4250C477	4073	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	4,690
Partner	B9	2014-06	EOP	9811536380	3002	Schrader Snap-in HS with 20deg angle 433MHz PSA	248,077
Partner Tepee	B9	2014-06	EOP	9811536380	3002	Schrader Snap-in HS with 20deg angle 433MHz PSA	82,726
RCZ	T75	2009-12	2013-09	5430W0	3000	Schrader Snap-in GEN4 type 433MHz PSA	6,507
RCZ	T75	2013-10	2016-12	9811536380	3002	Schrader Snap-in HS with 20deg angle 433MHz PSA	7,751
<b>Porsche</b>							
911	991	2011-12	2015-08	7PP907275F	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	41
911	991	2015-09	EOP	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	72
911	997	2008-04	2011-12	7PP907275F	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	3,464
911	997	2004-07	2008-03	99760602100	4001	Beru-Huf Clamp-in Separate valve G1 433MHz Porsche	1,299
911	PO674	2014-03	EOP	7PP907275F	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	46,075
918 Spyder	918	2015-01	EOP	7PP907275F	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	9
918 Spyder	918	2013-09	2014-12	7PP907275F	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	3



Car Make	Car Model Code	Start of application	End of application	OE sensor reference	Schrader Part Number (NEW)	Sensor Description	Direct TPMS Car Park in market 2017
918 Spyder	PO815	2014-03	EOP	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	14
918 Spyder	PO715	2014-03	EOP	7PP907275F	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	171
Boxster	981	2012-01	EOP	7PP907275F	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	18,667
Boxster	987	2004-11	2008-10	99760602100	4001	Beru-Huf Clamp-in Separate valve G1 433MHz Porsche	1,083
Boxster	987	2008-11	2011-12	7PP907275F	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	1,084
Cayenne	E2	2002-12	2006-12	95536166101	4005	Beru-Huf Clamp-in Separate valve G1.2 plus 433MHz Porsche	1,299
Cayenne	E2	2014-05	EOP	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	91
Cayenne	E2	2007-01	2010-12	7PP907275F	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	2,165
Cayenne	E2	2010-06	2014-05	7PP907275F	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	6,525
Cayenne	PO536	2017-01	2024-08	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	1,318
Cayenne	PO526	2014-03	EOP	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	50,336
Cayman	981	2013-03	EOP	7PP907275F	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	11,583
Cayman	987	2005-01	2008-01	99760602100	4001	Beru-Huf Clamp-in Separate valve G1 433MHz Porsche	650
Cayman	987	2009-02	2013-02	7PP907275F	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	875
Cayman	981_PO444	2017-01	EOP	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	3
Macan	PO416	2013-11	EOP	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	73,083
Panamera	970	2009-09	2013-12	7PP907275F	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	3,934
Panamera	970	2014-01	EOP	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	45
Panamera	PO620	2013-04	2022-07	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	52
Panamera	PO623	2016-01	EOP	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	7,136
Panamera	PO613	2014-03	EOP	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	7,017
<b>Qoros</b>							
3	CF11	2014-07	EOP	42753-TL0-G520	4072	Conti Clamp-in TG1C 433MHz Conti Honda	680
3	CF14	2014-11	EOP	42753-TL0-G520	4072	Conti Clamp-in TG1C 433MHz Conti Honda	685
3 Cross	CF14K	2015-03	EOP	42753-TL0-G520	4072	Conti Clamp-in TG1C 433MHz Conti Honda	253
<b>Ram</b>							
1500	DS	2014-03	2017-12	68239720AB	4068	TRW Snap-in Fixed Angle ver 1 433MHz Chrysler	2,088
<b>Renault</b>							
Alaskan	U60A	2016-01	EOP	407003VU0A	4032	Conti Clamp-in TG1C 433MHz Renault	5,157
Captur	J87	2013-01	2015-12	40700932R-D	3041	Schrader Snap-in HS with 20deg angle 433MHz Renault	274,672
Clio	X85	2014-06	EOP	40700932R-D	3041	Schrader Snap-in HS with 20deg angle 433MHz Renault	1
Clio	X85	2005-04	2014-05	8200253215	3040	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz Renault	12,990
Clio	X98	2014-06	EOP	407009987R	3073	Schrader Snap-in Faraday 433MHz Renault T4	293,981
Clio Van	X85	2014-06	EOP	40700932R-D	3041	Schrader Snap-in HS with 20deg angle 433MHz Renault	135
Clio Van	X98	2012-07	EOP	40700932R-D	3041	Schrader Snap-in HS with 20deg angle 433MHz Renault	107,945
Clio Van	X10_X98	2014-03	EOP	407009987R	3073	Schrader Snap-in Faraday 433MHz Renault T4	3
Espace	J81	2002-07	EOP	8200023746	3042	Schrader Clamp-in Gen 2/3 Type fixed 10deg angle Small Grommet Seal 433MHz Renault	53,637
Espace	JFC	2015-01	EOP	407004CB0A	4034	Conti Snap-in TG1D 433MHz Renault	70,865
Fluence	L38	2009-10	EOP	407000435R	4035	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	10,783
Grand Espace	J81	2002-07	EOP	8200023746	3042	Schrader Clamp-in Gen 2/3 Type fixed 10deg angle Small Grommet Seal 433MHz Renault	4,332
Grand Scenic	J95	2009-01	EOP	407000435R	4035	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	8,660
Kadjar	HFE	2015-01	EOP	407004CB0A	4034	Conti Snap-in TG1D 433MHz Renault	307,775
Kangoo	XFG	2017-10	2026-03	407004CB0A	4034	Conti Snap-in TG1D 433MHz Renault	8
Kangoo	X61(1)	2007-10	EOP	40700932R-D	3041	Schrader Snap-in HS with 20deg angle 433MHz Renault	95
Kangoo Passenger	X61	2007-10	EOP	40700932R-D	3041	Schrader Snap-in HS with 20deg angle 433MHz Renault	45,033
Kangoo Passenger	XFG	2017-10	EOP	407004CB0A	4034	Conti Snap-in TG1D 433MHz Renault	3

Car Make	Car Model Code	Start of application	End of application	OE sensor reference	Schrader Part Number (NEW)	Sensor Description	Direct TPMS Car Park in market 2017
Koleos	H45	2014-01	EOP	407003VU0A	4032	Conti Clamp-in TG1C 433MHz Renault	8,438
Koleos	H45	2008-02	2013-12	407001AY0A	3039	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	130
Laguna	LFD	2015-01	2021-09	407004CB0A	4034	Conti Snap-in TG1D 433MHz Renault	72
Laguna	X74	2000-12	2007-09	8200023746	3042	Schrader Clamp-in Gen 2/3 Type fixed 10deg angle Small Grommet Seal 433MHz Renault	108,250
Laguna	X91	2007-10	EOP	407000435R	4035	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	48,739
Laguna Coupe	D91	2014-07	EOP	407000435R	4035	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	164
Laguna Coupe	D91	2008-07	2014-06	407000435R	4035	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	6,928
Latitude	L43	2010-09	EOP	407000435R	4035	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	650
Master	X62	2009-11	EOP	40700932R-D	3041	Schrader Snap-in HS with 20deg angle 433MHz Renault	262,454
Master	X24	2014-03	EOP	40700932R-D	3041	Schrader Snap-in HS with 20deg angle 433MHz Renault	123
Master Chassis	X62	2014-03	EOP	40700932R-D	3041	Schrader Snap-in HS with 20deg angle 433MHz Renault	4
Master Passenger	X62	2009-11	EOP	40700932R-D	3041	Schrader Snap-in HS with 20deg angle 433MHz Renault	8,427
Megane	B32	2009-11	EOP	407000435R	4035	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	4,330
Megane	B32,X95	2011-05	EOP	407000435R	4035	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	582
Megane	BFB	2015-01	EOP	407004CB0A	4034	Conti Snap-in TG1D 433MHz Renault	57
Megane	LFF	2016-01	EOP	407004CB0A	4034	Conti Snap-in TG1D 433MHz Renault	8,936
Megane	X64	1997-01	2002-10	8200023746	3042	Schrader Clamp-in Gen 2/3 Type fixed 10deg angle Small Grommet Seal 433MHz Renault	8,660
Megane	X84	2008-12	EOP	407000435R	4035	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	142
Megane	X84	2002-11	2008-11	407005578R	4036	Conti Clamp-in TG1B Siemens VDO 433MHz Renault	43,300
Megane	X95	2008-11	EOP	407000435R	4035	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	193,490
Megane	BFB(2)	2015-04	2021-12	407004CB0A	4034	Conti Snap-in TG1D 433MHz Renault	68
Megane Van	BFB	2015-01	EOP	407000435R	4035	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	12
Megane Van	X95	2014-06	EOP	407000435R	4035	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	6,829
Modus	J77	2004-05	EOP	8200253215	3040	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz Renault	2,166
Scenic	J95	2015-01	EOP	407000435R	4035	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	148,453
Scenic	J95	2009-01	EOP	407000435R	4035	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	234,880
Scenic	J95	2003-06	2007-10	407005578R	4036	Conti Clamp-in TG1B Siemens VDO 433MHz Renault	51,980
Scenic	JFA	2016-01	EOP	407004CB0A	4034	Conti Snap-in TG1D 433MHz Renault	183,530
Scenic	J64	1997-01	2003-06	8200023746	3042	Schrader Clamp-in Gen 2/3 Type fixed 10deg angle Small Grommet Seal 433MHz Renault	8,660
Trafic	X82	2014-03	2026-03	40700932R-D	3041	Schrader Snap-in HS with 20deg angle 433MHz Renault	202,373
Trafic Passenger	X82	2014-03	EOP	40700932R-D	3041	Schrader Snap-in HS with 20deg angle 433MHz Renault	49,914
Trafic Passenger	X83	2014-03	EOP	40700932R-D	3041	Schrader Snap-in HS with 20deg angle 433MHz Renault	138
Twingo	X07	2014-03	EOP	40700932R-D	3041	Schrader Snap-in HS with 20deg angle 433MHz Renault	270,665
Twingo	X44	2007-01	2016-09	40700932R-D	3041	Schrader Snap-in HS with 20deg angle 433MHz Renault	25
Twingo Van	X07	2014-10	EOP	40700932R-D	3041	Schrader Snap-in HS with 20deg angle 433MHz Renault	862
Twingo Van	X44	2014-03	EOP	40700932R-D	3041	Schrader Snap-in HS with 20deg angle 433MHz Renault	1
Vel Satis	X73	2001-09	2009-11	8200023746	3042	Schrader Clamp-in Gen 2/3 Type fixed 10deg angle Small Grommet Seal 433MHz Renault	108,250
Wind	X33	2010-06	2016-09	40700932R-D	3041	Schrader Snap-in HS with 20deg angle 433MHz Renault	1
Zoe	X10	2012-09	EOP	407000435R	4035	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	69,995
<b>Rolls-Royce</b>							
Dawn	RR06	2016-01	EOP	36106856227	4010	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	597
Ghost	RR04	2009-12	2010-08	36236798726	4007	Beru-Huf Clamp-in Separate valve G2.4 433MHz BMW	22
Ghost	RR04	2010-09	EOP	36106856227	4010	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	517
Phantom	RR01	2007-09	2011-12	36236798726	4007	Beru-Huf Clamp-in Separate valve G2.4 433MHz BMW	87
Phantom	RR01	2012-01	EOP	36106856227	4010	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	58
Phantom	RR11	2017-01	EOP	36106872774	3057	Schrader Clamp-in Gen Delta 433MHz BMW	62
Phantom Coupe	RR02	2014-06	EOP	36106856227	4010	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	39
Phantom Drophead Coupe	RR02	2006-08	EOP	36236798726	4007	Beru-Huf Clamp-in Separate valve G2.4 433MHz BMW	196
Wrath	RR05	2014-03	EOP	36106856227	4010	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	803
<b>Saab</b>							
Saab 9-3	SB440	2007-07	EOP	B121G600F	3058	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	3
<b>Scion</b>							
tC	745L	2015-01	EOP	42607-30070	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1
<b>Skoda</b>							
Citigo	SK120	2011-10	EOP	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	11,753
Fabia	SK260	2014-03	EOP	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	45,429

# Make Model Year Look Up

Europe, Ver. 2.0,  
Update 09/2017

Car Make	Car Model Code	Start of application	End of application	OE sensor reference	Schrader Part Number (NEW)	Sensor Description	Direct TPMS Car Park in market 2017
Fabia Van	SK260	2014-03	EOP	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	49
Kodiak	SK326/1	2016-01	EOP	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	4,739
Octavia	SK371	2012-11	2019-06	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	65,547
Octavia (LCV)	SK371	2012-11	EOP	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	1
Praktik	SK337	2016-01	EOP	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	3
Rapid	SK251/1	2012-09	2020-04	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	9
Rapid	SK351/3	2014-03	EOP	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	7,266
Rapid Spaceback	SK253/1	2013-10	EOP	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	9
Rapid Spaceback	SK350/3	2014-03	EOP	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	14,206
Roomster	SK337	2016-01	EOP	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	6
Roomster (LCV)	SK258	2006-04	EOP	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	1
Superb	SK461	2008-03	EOP	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	453
Superb	SK481	2014-11	EOP	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	18,849
Yeti	SK316	2009-06	EOP	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	19,469
Yeti (LCV)	SK316	2009-06	EOP	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	1
<b>Smart</b>							
forfour	W453	2014-03	EOP	40700932R-D	3041	Schrader Snap-in HS with 20deg angle 433MHz Renault	105,011
Fortwo	A451	2016-01	EOP	A0009057200	3011	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	668
Fortwo	A451	2013-01	2015-12	A0009057200	3011	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	2,549
Fortwo	C453	2014-03	EOP	40700932R-D	3041	Schrader Snap-in HS with 20deg angle 433MHz Renault	192,587
<b>Ssangyong</b>							
Actyon	C100	2014-03	EOP	41990-34000	3068	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	60
Actyon Sports	Q150	2014-03	EOP	41990-34000	3068	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	296
Actyon SUT	Q150	2014-11	EOP	41990-34000	3068	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	412
Actyon SUT	Q100	2014-03	EOP	41990-34000	3068	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	174
Korando	K150	2014-03	EOP	41990-34000	3068	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	36
Korando C	C200/AS11	2013-08	EOP	41990-34000	3068	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	17,110
Korando Sports	Q150	2014-11	EOP	41990-34000	3068	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	444
LUVi	X100	2016-01	EOP	41990-35000	4084	Huf Snap-in 433MHz Huf Ssangyong	73
Musso	Q150	2016-01	EOP	41990-34000	3068	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	315
Rexton	Y200	2014-05	EOP	41990-34000	3068	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	6,467
Rexton	Y400	2016-10	EOP	41990-34000	3068	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	556
Rexton SC	Y200	2014-05	EOP	41990-34000	3068	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	28
Rodius	A100	2014-05	EOP	41990-34000	3068	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	6,244
Tivoli	X100	2015-01	EOP	41990-35000	4084	Huf Snap-in 433MHz Huf Ssangyong	24,085
Tivoli Air	X105	2016-01	EOP	41990-35000	4084	Huf Snap-in 433MHz Huf Ssangyong	26
Tivoli XLV	X105	2016-01	EOP	41990-35000	4084	Huf Snap-in 433MHz Huf Ssangyong	4,392
<b>Subaru</b>							
BRZ	E88	2014-01	EOP	SU003 05268	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota/Subaru	1,541
C-Concept	VL9	2014-06	EOP	28103FJ000	3064	Schrader Snap-in HS with 20deg angle 433MHz Subaru	84
Forester	FM5	2014-01	EOP	28103FJ000	3064	Schrader Snap-in HS with 20deg angle 433MHz Subaru	45,617
Forester	PF3	2014-01	EOP	28103FJ000	3064	Schrader Snap-in HS with 20deg angle 433MHz Subaru	9
Impreza	MF1	2014-01	EOP	28103FJ000	3064	Schrader Snap-in HS with 20deg angle 433MHz Subaru	2,968
Impreza	ZR1	2014-01	EOP	28103FJ000	3064	Schrader Snap-in HS with 20deg angle 433MHz Subaru	549
Impreza	HR3	2017-01	EOP	28103FL000/FL00A	3076	Schrader Snap-in Faraday 433MHz Subaru	4,246
Justy	D71A	2014-01	EOP	28103FJ000	3064	Schrader Snap-in HS with 20deg angle 433MHz Subaru	1
Legacy	BF4	2014-01	EOP	28103FJ000	3064	Schrader Snap-in HS with 20deg angle 433MHz Subaru	1,648
Legacy	EZ5	2014-03	EOP	28103FJ000	3064	Schrader Snap-in HS with 20deg angle 433MHz Subaru	753
Levorg	VL9	2015-09	EOP	28103FJ000	3064	Schrader Snap-in HS with 20deg angle 433MHz Subaru	9,436
Outback	04AL	2014-11	EOP	28103FJ000	3064	Schrader Snap-in HS with 20deg angle 433MHz Subaru	32
Outback	BF4	2014-09	EOP	28103FJ000	3064	Schrader Snap-in HS with 20deg angle 433MHz Subaru	23,735
Outback	EZ5	2014-03	EOP	28103FJ000	3064	Schrader Snap-in HS with 20deg angle 433MHz Subaru	6
Trezia	217A	2014-01	EOP	28103FJ000	3064	Schrader Snap-in HS with 20deg angle 433MHz Subaru	290
Tribeca	00X(2)	2016-05	EOP	28103FJ000	3064	Schrader Snap-in HS with 20deg angle 433MHz Subaru	10
WRX	MF1	2014-03	EOP	28103FJ000	3064	Schrader Snap-in HS with 20deg angle 433MHz Subaru	2
WRX	VL9	2014-03	EOP	28103FJ000	3064	Schrader Snap-in HS with 20deg angle 433MHz Subaru	2,075
XV	MF1	2014-01	EOP	28103FJ000	3064	Schrader Snap-in HS with 20deg angle 433MHz Subaru	32,241
<b>Suzuki</b>							
Alto	YC5	2014-06	EOP	43139-61M00	4065	Conti Clamp-in TG1C 433MHz Suzuki	1,710
Baleno	YR	2015-01	EOP	43139-61M00	4065	Conti Clamp-in TG1C 433MHz Suzuki	51,682
B-Cross	YJ	2016-01	EOP	43139-61M00	4065	Conti Clamp-in TG1C 433MHz Suzuki	56
B-Hatch	YRA	2015-01	EOP	43139-61M00	4065	Conti Clamp-in TG1C 433MHz Suzuki	58
Carry Van	YV7	2015-04	EOP	43139-61M00	4065	Conti Clamp-in TG1C 433MHz Suzuki	8
Celerio	YLA	2014-03	EOP	43139-61M00	4065	Conti Clamp-in TG1C 433MHz Suzuki	71,734
Grand Vitara	YT4	2014-06	EOP	43139-61M00	4065	Conti Clamp-in TG1C 433MHz Suzuki	3,120
Ignis	YJ	2016-01	EOP	43139-61M00	4065	Conti Clamp-in TG1C 433MHz Suzuki	47,028
Jimny	YR7	2014-06	EOP	43139-61M00	4065	Conti Clamp-in TG1C 433MHz Suzuki	34,156
Jimny	YR6,YR7	2014-06	EOP	43139-61M00	4065	Conti Clamp-in TG1C 433MHz Suzuki	5,177
Splash	YV1	2014-06	EOP	43139-61M00	4065	Conti Clamp-in TG1C 433MHz Suzuki	3,947

# Make Model Year Look Up

Europe, Ver. 2.0,  
Update 09/2017

Car Make	Car Model Code	Start of application	End of application	OE sensor reference	Schrader Part Number (NEW)	Sensor Description	Direct TPMS Car Park in market 2017
Splash	YV4	2013-09	EOP	43139-61M00	4065	Conti Clamp-in TG1C 433MHz Suzuki	2
Splash	YV5	2015-05	EOP	43139-61M00	4065	Conti Clamp-in TG1C 433MHz Suzuki	64
Splash	YV1,YV4	2014-06	EOP	43139-61M00	4065	Conti Clamp-in TG1C 433MHz Suzuki	2
Swift	YP6	2014-04	EOP	43139-61M00	4065	Conti Clamp-in TG1C 433MHz Suzuki	27,552
Swift	YP6,YP7	2014-06	EOP	43139-61M00	4065	Conti Clamp-in TG1C 433MHz Suzuki	95,559
Swift	YS	2016-01	EOP	43139-61M00	4065	Conti Clamp-in TG1C 433MHz Suzuki	51,201
SX4	YY1	2013-08	EOP	43139-61M00	4065	Conti Clamp-in TG1C 433MHz Suzuki	234
SX4	YY1,YY3	2013-08	EOP	43139-61M00	4065	Conti Clamp-in TG1C 433MHz Suzuki	3,948
SX4	YY3	2014-03	EOP	43139-61M00	4065	Conti Clamp-in TG1C 433MHz Suzuki	1
SX4 S-Cross	YAA	2013-11	EOP	43139-61M00	4065	Conti Clamp-in TG1C 433MHz Suzuki	98,979
Vitara	YFA	2015-01	EOP	43139-61M00	4065	Conti Clamp-in TG1C 433MHz Suzuki	182,155
Vitara	YG4/YH4	2014-03	EOP	43139-61M00	4065	Conti Clamp-in TG1C 433MHz Suzuki	40
<b>Tesla</b>							
Model S	Model S	2014-09	EOP	1034602-00-A	4081	Conti Clamp-in TG1C 433MHz Silver Stem Tesla	38,911
Model S	Model S	2013-05	2014-08	FS1511	4058	Baolong Clamp-in Variable angle detachable valve 433MHz Tesla	4,393
Model X	Model X	2015-08	EOP	1034602-00-A	4081	Conti Clamp-in TG1C 433MHz Silver Stem Tesla	11,747
Roadster	DarkStar	2008-03	2010-12	2000680	4009	Beru-Huf Clamp-in Separate valve G1.2 433MHz Fiat Group	1
<b>Toyota</b>							
Auris	130A	2014-06	EOP	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	398,884
Auris	130L	2014-06	EOP	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	2
Avensis	445L	2014-06	EOP	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	102,372
Camry	045L	2014-03	EOP	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1
C-HR	560A	2016-01	EOP	42607-48020	4114	Pacific Clamp-in Fixed Angle ver 1 433MHz Lexus	57,120
Corolla	079L,140N,340N	2013-08	EOP	42607-42020	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	4
Corolla	140A	2014-01	EOP	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	4
Corolla	252L	2014-03	EOP	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	2
Corolla	366A	2013-09	EOP	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	56
Corolla	150A	2014-10	EOP	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	10,627
Corolla	150L,252L	2014-03	EOP	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1,282
Corolla	466A	2014-03	EOP	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	26,799
Corolla Verso	681N	2014-06	EOP	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1
Dyna	U300-500	2014-06	EOP	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	3
Dyna	U600/C600	2014-06	EOP	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1
Dyna	Dutro(2)	2014-06	EOP	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	4
Dyna	131N	2014-03	EOP	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1,532
FJ Cruiser	155L	2014-06	EOP	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	4
Fortuner	669L	2014-03	EOP	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	2
GT 86	E88	2014-06	EOP	SU003 05268	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota/Subaru	5,129
Hiace	550N	2014-06	EOP	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1
Highlander	397L	2014-03	EOP	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1
Hilux	640A	2015-10	EOP	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	37,420
Hilux	669L	2014-06	EOP	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	38,341
IQ	630L	2014-06	EOP	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	461
IQ	630X	2016-07	EOP	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	52
Land Cruiser	215L	2014-06	EOP	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	10,096
Land Cruiser	611L	2014-06	EOP	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	16,376
Land Cruiser (LCV)	215L	2014-06	EOP	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	18
Land Cruiser Prado	611L	2014-06	EOP	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	536
Land Cruiser V8	215L	2014-06	EOP	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1,784
Mirai	470A	2015-01	EOP	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	238
Previa	085X	2015-10	EOP	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	7
Previa	085L	2014-03	EOP	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	2
Prius	590L	2014-06	EOP	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	10,769
Prius	690A	2015-01	EOP	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	39,102
Prius	277N	2014-06	EOP	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1
Prius Plus	030A	2014-06	EOP	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	21,401
Proace	G9	2014-06	EOP	9808859080	3003	Schrader Snap-in HS with 20deg angle 433MHz PSA HP	11,167
Proace	K0	2016-01	EOP	9808859080	3003	Schrader Snap-in HS with 20deg angle 433MHz PSA HP	13,676
Proace Combi	G9	2014-06	EOP	9808859080	3003	Schrader Snap-in HS with 20deg angle 433MHz PSA HP	131
Proace Verso	K0	2016-01	EOP	9808859080	3003	Schrader Snap-in HS with 20deg angle 433MHz PSA HP	2,280
RAV4	120L	2005-11	2012-12	42607-50010	4044	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	650
RAV4	120L	2014-03	EOP	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1
RAV4	410A	2013-01	EOP	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	198,912
Sequoia	200L	2015-01	EOP	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1
Sienna	500N	2014-06	EOP	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1
Sienna	580L	2014-06	EOP	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	519
Sienta	433L	2014-03	EOP	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1
Tundra	180L	2014-06	EOP	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	3
Tundra	480A/180L	2014-03	EOP	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	101

Car Make	Car Model Code	Start of application	End of application	OE sensor reference	Schrader Part Number (NEW)	Sensor Description	Direct TPMS Car Park in market 2017
Urban Cruiser	260L	2014-06	EOP	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	5
Verso	151L,595L	2014-06	EOP	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	4
Verso	595L	2014-06	EOP	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	95,500
Verso-S	770L	2014-06	EOP	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	6,554
Yaris	020L	2014-03	EOP	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	7
Yaris	850L	2014-06	EOP	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	598,205
Yaris (LCV)	850L	2014-06	EOP	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	11
<b>Volkswagen</b>							
Amarok	VN817	2009-11	2018-02	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	16,615
Amarok	VN817	2018-03	EOP	2N0907251	3108	Schrader GEN6 WAL GEN DELTA 433 MHz Tx Volkswagen	17,705
Arteon	VW276	2017-01	EOP	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	1,784
CC	VW464	2014-06	EOP	3AA907275B	4011	Beru-Huf Clamp-in Separate valve G3.42 433MHz VW	29
CC	VW484	2015-07	2022-06	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	8
CC	VW483	2017-01	EOP	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	3,624
Crafter	VN830	2006-04	2014-01	2E0907508F / 2E0907508J	4038	Conti Clamp-in MB_no RF link Siemens VDO 433MHz VW	27,546
Crafter	VN840	2018-03	EOP	2N0907251	3108	Schrader GEN6 WAL GEN DELTA 433 MHz Tx Volkswagen	34,333
Crafter Combi	VN830	2014-06	2018-02	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	1,103
Crafter Combi	VN840	2018-03	EOP	2N0907251	3108	Schrader GEN6 WAL GEN DELTA 433 MHz Tx Volkswagen	2,522
Cross Blue	VW416	2016-04	EOP	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	1
Eos	VW465	2006-02	EOP	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	626
Golf	VW360	2014-05	EOP	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	4,807
Golf	VW362	2009-09	EOP	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	3
Golf	VW370	2012-08	2018-06	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	460,084
Golf Plus	VW369	2008-09	2014-01	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	13
Golf Plus	VW379	2014-02	2019-01	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	27
Golf Sportsvan	VW379	2014-03	EOP	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	62,355
Golf SV	VW379	2014-03	EOP	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	2,237
Jetta	VW361	2010-07	EOP	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	8,456
New Beetle	VW314	2006-01	2010-07	1K0907253C	4037	Conti Clamp-in TG1B Siemens VDO 433MHz VW	1,299
New Beetle	VW324	2011-08	EOP	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	9,680
New Beetle Convertible	VW325	2012-09	EOP	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	12,987
Passat	VW451	2005-03	2010-11	1K0907253C	4037	Conti Clamp-in TG1B Siemens VDO 433MHz VW	15,155
Passat	VW471	2014-08	EOP	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	3
Passat	VW471	2010-08	2014-07	3AA907275D	4011	Beru-Huf Clamp-in Separate valve G3.3 433MHz VW	6,987
Passat	VW481	2014-07	EOP	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	172,127
Passat CC	VW464	2014-09	EOP	3AA907275B	4011	Beru-Huf Clamp-in Separate valve G3.42 433MHz VW	6,110
Passat CC	VW464	2008-05	EOP	3AA907275D	4011	Beru-Huf Clamp-in Separate valve G3.3 433MHz VW	5,389
Phaeton	VW611	2002-04	2007-05	99760602100	4001	Beru-Huf Clamp-in Separate valve G1 433MHz Porsche	1,732
Phaeton	VW611	2010-06	EOP	7PP907275F	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	3,297
Phaeton	VW611	2007-06	2010-05	7PP907275F	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	1,083
Polo	VW270	2016-10	EOP	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	18,615
Scirocco	VW364	2008-06	EOP	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	10,171
Sharan	VW428	2010-06	EOP	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	36,528
Tiguan	VW316	2011-05	2014-07	3AA907275D	4011	Beru-Huf Clamp-in Separate valve G3.3 433MHz VW	80,393
Tiguan	VW326	2014-08	2016-08	3AA907275D	4011	Beru-Huf Clamp-in Separate valve G3.3 433MHz VW	87,853
Tiguan	VW376	2016-09	EOP	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	56
Tiguan CC	VW326/4	2017-01	EOP	3AA907275F	4011	Beru-Huf Clamp-in Separate valve G3.3 433MHz VW	4
Tiguan XL	VW326	2017-01	EOP	3AA907275F	4011	Beru-Huf Clamp-in Separate valve G3.3 433MHz VW	4,040
Touareg	VW516	2002-10	2006-12	7L0907275B	4005	Beru-Huf Clamp-in Separate valve G1.2 plus 433MHz VW/Porsche	2,598
Touareg	VW516	2007-01	2010-05	7PP907275F	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	2,598
Touareg	VW526	2017-10	EOP	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	3,129
Touareg	VW526	2010-01	2014-07	7PP907275F	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	2,881
Touareg	VW526	2014-08	2017-09	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	15,448
Touareg	VW536	2017-07	2024-06	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	1,043
Touran	VW368	2010-07	2014-12	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	899
Touran	VW378	2015-01	EOP	3AA907275B	4011	Beru-Huf Clamp-in Separate valve G3.42 433MHz VW	69,624
Touran (LCV)	VW368	2010-07	EOP	3AA907275D	4011	Beru-Huf Clamp-in Separate valve G3.3 433MHz VW	1
Transporter	VN750	2003-03	2018-02	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	1
Transporter	VN760	2018-03	EOP	2N0907251	3108	Schrader GEN6 WAL GEN DELTA 433 MHz Tx Volkswagen	188,575

# Make Model Year Look Up

Europe, Ver. 2.0,  
Update 09/2017

Car Make	Car Model Code	Start of application	End of application	OE sensor reference	Schrader Part Number (NEW)	Sensor Description	Direct TPMS Car Park in market 2017
Transporter Shuttle	VN750	2014-06	2018-02	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	254
Transporter Shuttle	VN760	2018-03	EOP	2N0907251	3108	Schrader GEN6 WAL GEN DELTA 433 MHz Tx Volkswagen	6,142
Up!	VW120	2011-08	EOP	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	64,451
XL1	VW019	2013-08	EOP	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	1
XL1	VW114	2014-03	EOP	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	13
<b>Volvo</b>							
C30	Y279	2006-09	2012-12	30681555	4023	Conti Clamp-in TG1B 433MHz Ford	108
C70	Y281	2006-03	EOP	30681555	4023	Conti Clamp-in TG1B 433MHz Ford	7
S40	Y276	2004-01	EOP	30681555	4023	Conti Clamp-in TG1B 433MHz Ford	1
S90	V541	2016-01	EOP	31362304	3069	Schrader Snap-in HS with 20deg angle 433MHz Volvo	15,591
V40	Y555	2014-03	EOP	31445473	4070	Conti Clamp-in TG1C 433MHz Volvo	201,991
V40 Cross Country	Y555	2014-03	EOP	31445473	4070	Conti Clamp-in TG1C 433MHz Volvo	46,151
V40 XC	Y555	2014-03	EOP	31445473	4070	Conti Clamp-in TG1C 433MHz Volvo	50
V50	Y280	2003-11	2012-05	30681555	4023	Conti Clamp-in TG1B 433MHz Ford	173
V50	Y280	2012-06	EOP	30681555	4023	Conti Clamp-in TG1B 433MHz Ford	4
V60	Y352	2010-09	2014-06	31445473	4070	Conti Clamp-in TG1C 433MHz Volvo	6,790
V60	Y352	2014-07	2017-09	31445473	4070	Conti Clamp-in TG1C 433MHz Volvo	86,821
V60 Cross Country	Y352	2015-01	EOP	31445473	4070	Conti Clamp-in TG1C 433MHz Volvo	22,088
V70	Y285	2006-03	2008-10	30681555	4023	Conti Clamp-in TG1B 433MHz Ford	217
V70	Y285	2014-07	EOP	31445473	4070	Conti Clamp-in TG1C 433MHz Volvo	38,967
V70	Y285	2008-09	2014-06	31445473	4070	Conti Clamp-in TG1C 433MHz Volvo	4,434
V70	Y285	2008-01	2010-08	30681555	4023	Conti Clamp-in TG1B 433MHz Ford	217
V90	V542	2015-04	2016-03	31362304	3069	Schrader Snap-in HS with 20deg angle 433MHz Volvo	3,331
V90 Cross Country	V543	2016-01	EOP	31362304	3069	Schrader Snap-in HS with 20deg angle 433MHz Volvo	11,452
XC60	Y413	2014-07	2016-10	31445473	4070	Conti Clamp-in TG1C 433MHz Volvo	144,283
XC60	Y413	2008-05	2014-06	31445473	4070	Conti Clamp-in TG1C 433MHz Volvo	23,178
XC70	Y381	2014-07	EOP	31445473	4070	Conti Clamp-in TG1C 433MHz Volvo	33,205
XC70	Y381	2007-02	2014-06	31445473	4070	Conti Clamp-in TG1C 433MHz Volvo	2,471
XC90	V526	2015-01	2016-03	31362304	3069	Schrader Snap-in HS with 20deg angle 433MHz Volvo	25,185
XC90	Y289	2015-01	EOP	30748354	3046	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz Volvo	16
XC90	Y289	2002-04	2014-12	30748354	3046	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz Volvo	645

**Euroguide -Sensors Look Up**

**Sensors Look Up:** This list identifies which cars can be fitted with a particular Schrader referenced part number.

- 1/ Identify the Schrader Code of the sensor (After Market reference) in the first column "**Schrader Part Number**"
- 2/ In the same column identify which car manufacturer and car model the sensor is fitted on.  
– When the sensor reference is matching the right car model, all the necessary information concerning the car and the sensor are in the following columns (same line, from left to the right).
- 3/ **Car Model Code** is the Identification code of the vehicle.
- 4/ "**Start of Application**" and "**End of Application**" show if the car has been fitted with a TPMS direct system by the car manufacturer during this period of time.
- 5/ **OE Sensor reference:** This is car manufacturer's part number for the sensor.
- 6/ **Sensor Description:** Description of the After Market reference.
- 7/ **Direct TPMS car park in Market:** number of vehicles introduced in the reference market with direct TPMS systems using the specific sensor indicated in the OE sensor reference column.

TPMS Euroshop makes every effort to ensure that the information contained in this list are correct, but cannot guarantee 100% accuracy of the information. Customers should be aware that they buy and use any products on this website at their own risk. This list will be regularly updated.  
For further information: [tpmseuroshop.com](http://tpmseuroshop.com) or [aftermarket@schrader.co.uk](mailto:aftermarket@schrader.co.uk)

Schrader Part Number (NEW)	Car Model Code	Start of Application	End of Application	Sensor Manufacturer	OE Sensor Reference	Sensor Description	Direct TPMS Car Park in market 2017
<b>3000</b>							
<b>Citroen</b>							
Berlingo	B9	2008-01	2013-09	Schrader	5430W0	Schrader Snap-in GEN4 type 433MHZ PSA	98
C4	B7	2010-06	2014-01	Schrader	5430W0	Schrader Snap-in GEN4 type 433MHZ PSA	29,877
C4 Picasso	B58	2013-10	EOP	Schrader	5430W0	Schrader Snap-in GEN4 type 433MHZ PSA	13
C4 Picasso		2006-05	2013-09	Schrader	5430W0	Schrader Snap-in GEN4 type 433MHZ PSA	86,606
DS4	B75	2010-12	2014-01	Schrader	5430W0	Schrader Snap-in GEN4 type 433MHZ PSA	13,840
DS5	B81	2011-06	2014-01	Schrader	5430W0	Schrader Snap-in GEN4 type 433MHZ PSA	8,638
Jumper	X2/50	2006-01	2013-11	Schrader	5430W0	Schrader Snap-in GEN4 type 433MHZ PSA	98
<b>Peugeot</b>							
3008	T84	2008-11	2013-09	Schrader	5430W0	Schrader Snap-in GEN4 type 433MHZ PSA	88,778
307	T5	2007-01	2007-12	Schrader	5430W0	Schrader Snap-in GEN4 type 433MHZ PSA	86,600
308	T7	2007-04	2013-08	Schrader	5430W0	Schrader Snap-in GEN4 type 433MHZ PSA	49,375
5008	T87	2009-09	2013-09	Schrader	5430W0	Schrader Snap-in GEN4 type 433MHZ PSA	55,001
RCZ	T75	2009-12	2013-09	Schrader	5430W0	Schrader Snap-in GEN4 type 433MHZ PSA	6,507
<b>3001</b>							
<b>Fiat</b>							
Scudo	G9	2006-09	2013-10	Schrader	9677130580	Schrader Snap-in GEN4 type 433MHZ PSA HP	36
Scudo Combi	G9	2006-09	2013-10	Schrader	9677130580	Schrader Snap-in GEN4 type 433MHZ PSA HP	36
<b>Peugeot</b>							
Expert (LCV)	G9	2006-09	2013-12	Schrader	9677130580	Schrader Snap-in GEN4 type 433MHZ PSA HP	43
<b>3002</b>							
<b>Citroen</b>							
Berlingo	B9	2013-10	2017-01	Schrader	9811536380	Schrader Snap-in HS with 20deg angle 433MHZ PSA	204,733
Berlingo Multispace	B9	2013-10	EOP	Schrader	9811536380	Schrader Snap-in HS with 20deg angle 433MHZ PSA	140,481
C4	B7	2014-01	2017-12	Schrader	9811536380	Schrader Snap-in HS with 20deg angle 433MHZ PSA	43
C5	X7	2013-09	2016-09	Schrader	9811536380	Schrader Snap-in HS with 20deg angle 433MHZ PSA	24,379
C-Elysee	M3/M4	2012-10	EOP	Schrader	9811536380	Schrader Snap-in HS with 20deg angle 433MHZ PSA	32,805
DS4	B75	2014-02	EOP	Schrader	9811536380	Schrader Snap-in HS with 20deg angle 433MHZ PSA	56,850
DS5	B81	2014-02	EOP	Schrader	9811536380	Schrader Snap-in HS with 20deg angle 433MHZ PSA	37,380
<b>Peugeot</b>							
207	A7	2013-09	2016-06	Schrader	9811536380	Schrader Snap-in HS with 20deg angle 433MHZ PSA	1,876
3008	T84	2016-10	EOP	Schrader	9811536380	Schrader Snap-in HS with 20deg angle 433MHZ PSA	9,650
3008		2013-09	2016-09	Schrader	9811536380	Schrader Snap-in HS with 20deg angle 433MHZ PSA	166,092
301	M3/M4	2012-10	EOP	Schrader	9811536380	Schrader Snap-in HS with 20deg angle 433MHZ PSA	8,098
308	T7	2015-02	EOP	Schrader	9811536380	Schrader Snap-in HS with 20deg angle 433MHZ PSA	152
308		2013-09	2015-01	Schrader	9811536380	Schrader Snap-in HS with 20deg angle 433MHZ PSA	4,208
5008	T87	2013-09	EOP	Schrader	9811536380	Schrader Snap-in HS with 20deg angle 433MHZ PSA	93,220
508	W2	2013-09	2017-06	Schrader	9811536380	Schrader Snap-in HS with 20deg angle 433MHZ PSA	122,540
508 RXH	W24	2013-09	2017-12	Schrader	9811536380	Schrader Snap-in HS with 20deg angle 433MHZ PSA	12
Partner	B9	2014-06	EOP	Schrader	9811536380	Schrader Snap-in HS with 20deg angle 433MHZ PSA	248,077
Partner Tepee	B9	2014-06	EOP	Schrader	9811536380	Schrader Snap-in HS with 20deg angle 433MHZ PSA	82,726
RCZ	T75	2013-10	2016-12	Schrader	9811536380	Schrader Snap-in HS with 20deg angle 433MHZ PSA	7,751
<b>3003</b>							
<b>Citroen</b>							
Jumpy	G9	2014-06	EOP	Schrader	9808859080	Schrader Snap-in HS with 20deg angle 433MHZ PSA HP	38,026
Jumpy Combi	G9	2014-06	EOP	Schrader	9808859080	Schrader Snap-in HS with 20deg angle 433MHZ PSA HP	6,638
<b>Fiat</b>							
Scudo	G9	2013-11	2015-12	Schrader	9808859080	Schrader Snap-in HS with 20deg angle 433MHZ PSA HP	17,514
Scudo		2016-01	EOP	Schrader	9808859080	Schrader Snap-in HS with 20deg angle 433MHZ PSA HP	11,187

Schrader Part Number (NEW)	Car Model Code	Start of Application	End of Application	Sensor Manufacturer	OE Sensor Reference	Sensor Description	Direct TPMS Car Park in market 2017
Scudo Chassis	G9	2014-03	EOP	Schrader	9808859080	Schrader Snap-in HS with 20deg angle 433MHz PSA HP	2
Scudo Combi	G9	2013-11	EOP	Schrader	9808859080	Schrader Snap-in HS with 20deg angle 433MHz PSA HP	5,407
<b>Peugeot</b>							
Expert	G9	2014-06	EOP	Schrader	9808859080	Schrader Snap-in HS with 20deg angle 433MHz PSA HP	35,080
Expert Tepee	G9	2014-06	EOP	Schrader	9808859080	Schrader Snap-in HS with 20deg angle 433MHz PSA HP	6,352
<b>Toyota</b>							
Proace	G9	2014-06	EOP	Schrader	9808859080	Schrader Snap-in HS with 20deg angle 433MHz PSA HP	11,167
Proace	K0	2016-01	EOP	Schrader	9808859080	Schrader Snap-in HS with 20deg angle 433MHz PSA HP	13,676
Proace Combi	G9	2014-06	EOP	Schrader	9808859080	Schrader Snap-in HS with 20deg angle 433MHz PSA HP	131
Proace Verso	K0	2016-01	EOP	Schrader	9808859080	Schrader Snap-in HS with 20deg angle 433MHz PSA HP	2,280
<b>3004</b>							
<b>Citroen</b>							
C5	X40	2000-12	2004-07	Schrader	543002	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Large Grommet Seal 433MHz PSA	51,960
C8	V3	2002-02	2005-10	Schrader	543002	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Large Grommet Seal 433MHz PSA	8,660
<b>Fiat</b>							
Ulysse	V1	2002-02	2005-10	Schrader	543002	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Large Grommet Seal 433MHz PSA	1,299
<b>Peugeot</b>							
607	Z8	1999-09	2004-10	Schrader	543002	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Large Grommet Seal 433MHz PSA	10,825
807	V2	2002-02	2004-09	Schrader	543002	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Large Grommet Seal 433MHz PSA	9,093
<b>3005</b>							
<b>Jeep</b>							
Compass	MK49	2014-09	EOP	Schrader	56029481AB	Schrader Snap-in GEN4 type 433MHz Chrysler	1,454
Compass		2006-05	2014-08	Schrader	56029481AB	Schrader Snap-in GEN4 type 433MHz Chrysler	8,093
Patriot	MK74	2006-12	2014-08	Schrader	56029481AB	Schrader Snap-in GEN4 type 433MHz Chrysler	868
Patriot		2014-09	EOP	Schrader	56029481AB	Schrader Snap-in GEN4 type 433MHz Chrysler	3
<b>3006</b>							
<b>Chrysler</b>							
300/300C	LE48	2005-06	2010-06	Schrader	56029359AC	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	4,330
Grand Voyager	RT	2007-07	2011-01	Schrader	56029359AC	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	1,299
Sebring	JS41C	2006-08	EOP	Schrader	56029359AC	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	89
Sebring Convertible	JS27	2007-02	EOP	Schrader	56029359AC	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	132
Town & Country	RT	2007-07	2011-01	Schrader	56029359AC	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	433
<b>Dodge</b>							
Avenger	JS41D	2006-11	EOP	Schrader	56029359AC	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	68
Caliber	PM49	2006-01	EOP	Schrader	56029359AC	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	217
Challenger	LC22	2008-01	2010-01	Schrader	56029359AC	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	87
Nitro	KA	2006-08	EOP	Schrader	56029359AC	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	153
<b>Jeep</b>							
Cherokee	KK	2007-07	EOP	Schrader	56029359AC	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	456
Grand Cherokee	WH	2005-03	2010-06	Schrader	56029359AC	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	4,330
Wrangler	JK72	2006-08	2010-09	Schrader	56029359AC	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	2,165
Wrangler (LCV)	JK72	2006-08	EOP	Schrader	56029359AC	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	885
<b>Lancia</b>							
Voyager	RT	2007-07	2011-01	Schrader	56029359AC	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	2,165
<b>3007</b>							
<b>Chrysler</b>							
Grand Voyager	RT	2011-01	2017-09	Schrader	56029398AB	Schrader Snap-in GEN4 type 433MHz Chrysler	3
Viper	ZD	2012-12	EOP	Schrader	56029398AB	Schrader Snap-in GEN4 type 433MHz Chrysler	1
Voyager	RT	2014-06	EOP	Schrader	56029398AB	Schrader Snap-in GEN4 type 433MHz Chrysler	8
<b>Dodge</b>							
Caravan	RT	2011-06	2017-05	Schrader	56029398AB	Schrader Snap-in GEN4 type 433MHz Chrysler	44
Challenger	LC22	2010-02	2017-09	Schrader	56029398AB	Schrader Snap-in GEN4 type 433MHz Chrysler	207
Charger	LD	2010-12	2014-09	Schrader	56029398AB	Schrader Snap-in GEN4 type 433MHz Chrysler	87
Charger		2014-10	2016-06	Schrader	68241067AA	Schrader Snap-in GEN4 type 433MHz Chrysler	1
Charger	LX48D	2010-11	EOP	Schrader	56029398AB	Schrader Snap-in GEN4 type 433MHz Chrysler	50
Durango	WD75	2010-11	EOP	Schrader	56029398AB	Schrader Snap-in GEN4 type 433MHz Chrysler	673
Journey	JC49	2011-01	2014-06	Schrader	56029398AB	Schrader Snap-in GEN4 type 433MHz Chrysler	43
Journey		2014-07	2015-09	Schrader	68241067AA	Schrader Snap-in GEN4 type 433MHz Chrysler	55
Ram	DS	2010-01	2013-06	Schrader	56029398AB	Schrader Snap-in GEN4 type 433MHz Chrysler	690
<b>Fiat</b>							
Freemont	JF	2016-01	EOP	Schrader	68241067AB	Schrader Snap-in GEN4 type 433MHz Chrysler	3,028
Freemont		2014-07	2015-09	Schrader	68241067AA	Schrader Snap-in GEN4 type 433MHz Chrysler	14,418
Freemont		2011-03	2014-06	Schrader	56029398AB	Schrader Snap-in GEN4 type 433MHz Chrysler	31,962
<b>Jeep</b>							
Grand Cherokee	WK74	2010-07	2016-03	Schrader	56029398AB	Schrader Snap-in GEN4 type 433MHz Chrysler	38,757
Wrangler	JK72	2010-10	2013-12	Schrader	56029398AB	Schrader Snap-in GEN4 type 433MHz Chrysler	5,300
Wrangler		2014-03	EOP	Schrader	68241067AA	Schrader Snap-in GEN4 type 433MHz Chrysler	20,445
Wrangler	JK72(2)	2014-01	EOP	Schrader	68241067AA	Schrader Snap-in GEN4 type 433MHz Chrysler	75
<b>Lancia</b>							
Voyager	RT	2011-02	2013-07	Schrader	56029398AB	Schrader Snap-in GEN4 type 433MHz Chrysler	25
Voyager	RT,RU	2011-01	2015-10	Schrader	56029398AB	Schrader Snap-in GEN4 type 433MHz Chrysler	5



Schrader Part Number (NEW)	Car Model Code	Start of Application	End of Application	Sensor Manufacturer	OE Sensor Reference	Sensor Description	Direct TPMS Car Park in market 2017
<b>3008</b>							
<b>Chrysler</b>							
300	LE48	2014-06	EOP	Schrader	56029400AD	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	9
300	LX	2011-01	2016-06	Schrader	56029400AD	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	1
<b>Dodge</b>							
Viper	ZD	2013-08	2015-06	Schrader	56029400AD	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	2
<b>Lancia</b>							
Thema	LX	2011-01	EOP	Schrader	56029400AD	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	1,765
<b>3009</b>							
<b>Alfa Romeo</b>							
4C	4C	2013-06	2021-03	Schrader	05154876AA	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	3,776
<b>Citroen</b>							
Jumper	X2/50	2013-12	EOP	Schrader	05154876AA	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	136,332
Jumper Chassis	X2/50	2014-06	EOP	Schrader	05154876AA	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	
Jumper Combi	X2/50	2014-06	EOP	Schrader	05154876AA	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	15,386
<b>Dodge</b>							
Viper	ZD	2015-07	EOP	Schrader	05154876AA	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	4
<b>Fiat</b>							
Ducato	X2/50	2014-06	EOP	Schrader	05154876AA	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	29,351
Ducato Chassis	X2/50	2014-06	EOP	Schrader	05154876AA	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	0
Ducato Combi	X2/50	2014-06	EOP	Schrader	05154876AA	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	10,675
<b>Maserati</b>							
Alfieri	M165	2016-01	EOP	Schrader	05154876AA	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	33
Ghibli	M157	2013-11	EOP	Schrader	05154876AA	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	15,151
GranCabrio	M147	2015-07	2017-12	Schrader	05154876AA	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	445
GranTurismo	M145	2014-01	2020-03	Schrader	05154876AA	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	1,081
GT Coupe	M145(2)	2014-01	EOP	Schrader	05154876AA	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	23
GT Coupe	M138	2014-03	EOP	Schrader	95518233/670002790	Schrader Clamp-in Gen Gamma 433MHz Maserati / Alfa Romeo	1
Levante	WM	2015-04	2021-09	Schrader	05154876AA	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	61
Levante	M161	2016-01	EOP	Schrader	05154876AA	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	6,460
Quattroporte	M156	2013-01	EOP	Schrader	05154876AA	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	2,645
<b>Peugeot</b>							
Boxer	X2/50	2013-12	EOP	Schrader	05154876AA	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	168,441
Boxer Combi	X2/50	2013-12	EOP	Schrader	05154876AA	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	5,160
<b>3011</b>							
<b>Mercedes-Benz</b>							
B-Class	W246	2013-01	EOP	Schrader	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	260,679
C-Class	C204	2014-03	EOP	Schrader	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	4,768
C-Class	W204	2013-01	EOP	Schrader	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	5,176
C-Class Coupe	C204	2012-12	EOP	Schrader	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	23
CL	C217	2014-04	2020-06	Schrader	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	77
CLA	C117	2012-12	2014-11	Schrader	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	174
CLC	C203	2014-06	EOP	Schrader	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	1
CLK	C209	2014-06	EOP	Schrader	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	1
CLS	C218	2013-01	2014-11	Schrader	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	4,282
CLS		2009-08	2012-12	Schrader	A0009054100	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	2,166
E-Class	W212	2013-01	2014-11	Schrader	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	25,095
E-Class		2009-04	2012-12	Schrader	A0009054100	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	4,677
E-Class Coupe	C207	2009-01	2012-12	Schrader	A0009054100	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	1,559
GLA	X156	2014-01	2014-11	Schrader	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	26,318
GL-Class	X164	2009-06	2012-12	Schrader	A0009054100	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	1,302
GL-Class	X166	2013-01	EOP	Schrader	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	7,108
GLK	X204	2012-12	2015-09	Schrader	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	22,178
G-Wagen	G463/461	2013-01	2022-12	Schrader	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	71
G-Wagen		2007-04	2012-12	Schrader	A0009054100	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	654
G-Wagen (LCV)	G463/461	2012-12	2022-12	Schrader	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	14
ML-Class	W166	2011-07	2012-12	Schrader	A0009054100	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	3
R-Class	V251	2013-01	EOP	Schrader	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	68
R-Class		2009-07	2012-12	Schrader	A0009054100	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	652
S-Class	W221	2013-01	2013-06	Schrader	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	3
S-Class		2009-07	2012-12	Schrader	A0009054100	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	2,168
SL	R231	2013-01	2014-05	Schrader	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	834
SL		2009-08	2012-12	Schrader	A0009054100	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	1,518
SLK	R172	2013-01	2014-11	Schrader	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	7,961
SLS	C197	2013-01	2023-09	Schrader	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	323
SLS		2010-02	2012-12	Schrader	A0009054100	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	871
Sprinter	NCV3	2014-06	EOP	Schrader	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	335,198
Sprinter Combi	NCV3	2013-01	EOP	Schrader	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	29,052
Vito Combi	VS20	2012-12	2023-04	Schrader	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	43,128
<b>Smart</b>							
Fortwo	A451	2016-01	EOP	Schrader	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	668
Fortwo		2013-01	2015-12	Schrader	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	2,549

Schrader Part Number (NEW)	Car Model Code	Start of Application	End of Application	Sensor Manufacturer	OE Sensor Reference	Sensor Description	Direct TPMS Car Park In market 2017
<b>3012</b>							
<b>Mercedes-Benz</b>							
Vario	T2N	2014-03	EOP	Schrader	A4479050500	Schrader Snap-in HS with 10deg angle 433MHz Daimler	38
V-Class	VS20	2014-03	EOP	Schrader	A4479050500	Schrader Snap-in HS with 10deg angle 433MHz Daimler	84,529
V-Class	W638	2014-06	EOP	Schrader	A4479050500	Schrader Snap-in HS with 10deg angle 433MHz Daimler	408
Viano	VS20	2014-06	EOP	Schrader	A4479050500	Schrader Snap-in HS with 10deg angle 433MHz Daimler	4
Viano	W639	2014-03	EOP	Schrader	A4479050500	Schrader Snap-in HS with 10deg angle 433MHz Daimler	4,033
Viano (LCV)	VS20	2014-08	2023-07	Schrader	A4479050500	Schrader Snap-in HS with 10deg angle 433MHz Daimler	28
Vito	VS20	2014-07	EOP	Schrader	A4479050500	Schrader Snap-in HS with 10deg angle 433MHz Daimler	141,449
<b>3013</b>							
<b>Aston Martin</b>							
DB11	VH500	2016-01	EOP	Schrader	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	1,053
<b>Infiniti</b>							
Q30	GD1A	2015-10	EOP	Schrader	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	22,582
QX30	GD1A	2016-01	EOP	Schrader	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	10,310
<b>Mercedes-Benz</b>							
A-Class	S176	2014-03	EOP	Schrader	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	390,579
C-Class	C205	2015-01	EOP	Schrader	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	68,265
C-Class	W205	2014-01	2021-03	Schrader	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	467,653
C-Class Coupe	C205	2015-06	EOP	Schrader	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	76
CLA	C117	2014-12	EOP	Schrader	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	181,126
CLS	C218	2014-12	EOP	Schrader	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	24,728
E-Class	C207	2014-06	EOP	Schrader	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	34,364
E-Class	W212	2014-12	EOP	Schrader	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	90,160
G-Class	G463/461	2014-03	EOP	Schrader	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	11,434
GLA	X156	2014-12	2020-12	Schrader	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	181,342
GLC	X253	2015-01	EOP	Schrader	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	142,494
GLC Coupe	C253	2016-01	EOP	Schrader	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	20,926
GLE	W166	2015-01	EOP	Schrader	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	55,244
GLE Coupe	C292	2015-01	EOP	Schrader	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	29,474
GLK	X253	2015-10	EOP	Schrader	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	78
GLS	X166	2015-01	EOP	Schrader	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	8,605
GT	C190	2014-01	EOP	Schrader	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	7,794
MLC	C292	2012-12	EOP	Schrader	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	75
ML-Class	W166	2014-07	EOP	Schrader	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	10,968
S-Class	W222	2014-12	EOP	Schrader	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	34,593
S-Class Coupe	C217	2014-07	EOP	Schrader	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	10,472
S-Class Pullman	X222	2014-03	EOP	Schrader	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	46
SL	R231	2014-06	EOP	Schrader	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	4,997
SLC	R172	2016-01	EOP	Schrader	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	16,748
SLK	R172	2014-12	EOP	Schrader	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	11,374
<b>3016</b>							
<b>Alfa Romeo</b>							
MiTo	955	2013-08	EOP	Schrader	53104671	Schrader Snap-in GEN4 type 433MHz Fiat	38,669
<b>Chrysler</b>							
Ypsilon	846	2011-04	EOP	Schrader	53104671	Schrader Snap-in GEN4 type 433MHz Fiat	181,771
<b>Citroen</b>							
Nemo	225	2007-10	2015-12	Schrader	53104671	Schrader Snap-in GEN4 type 433MHz Fiat	13,470
Nemo	225(2)	2015-10	2022-12	Schrader	53104671	Schrader Snap-in GEN4 type 433MHz Fiat	27
Nemo Multispace	225	2007-10	EOP	Schrader	53104671	Schrader Snap-in GEN4 type 433MHz Fiat	5,073
Nemo Multispace	225(2)	2015-10	EOP	Schrader	53104671	Schrader Snap-in GEN4 type 433MHz Fiat	19
<b>Fiat</b>							
500	312	2015-08	EOP	Schrader	53104671	Schrader Snap-in GEN4 type 433MHz Fiat	373,590
500		2007-05	2015-07	Schrader	53104671	Schrader Snap-in GEN4 type 433MHz Fiat	115,893
500C	312	2007-05	EOP	Schrader	53104671	Schrader Snap-in GEN4 type 433MHz Fiat	69,597
Doblo	223	2014-06	EOP	Schrader	53104671	Schrader Snap-in GEN4 type 433MHz Fiat	0
Doblo	263	2009-12	EOP	Schrader	53104671	Schrader Snap-in GEN4 type 433MHz Fiat	147,821
Doblo Combi	263	2014-06	EOP	Schrader	53104671	Schrader Snap-in GEN4 type 433MHz Fiat	3,286
Fiorino	225	2014-06	EOP	Schrader	53104671	Schrader Snap-in GEN4 type 433MHz Fiat	5,708
Fiorino Qubo	225	2014-06	EOP	Schrader	53104671	Schrader Snap-in GEN4 type 433MHz Fiat	2,745
Linea	200	2007-03	EOP	Schrader	53104671	Schrader Snap-in GEN4 type 433MHz Fiat	14
Qubo	225	2007-10	EOP	Schrader	53104671	Schrader Snap-in GEN4 type 433MHz Fiat	6,234
Strada	178	1998-09	EOP	Schrader	53104671	Schrader Snap-in GEN4 type 433MHz Fiat	102
Strada	326	2013-01	EOP	Schrader	53104671	Schrader Snap-in GEN4 type 433MHz Fiat	9
<b>Lancia</b>							
Delta	PK	2014-06	EOP	Schrader	53104671	Schrader Snap-in GEN4 type 433MHz Fiat	57
<b>Opel</b>							
Combo	263	2014-06	EOP	Schrader	53104671	Schrader Snap-in GEN4 type 433MHz Fiat	66,053
Combo Combi	263	2014-06	EOP	Schrader	53104671	Schrader Snap-in GEN4 type 433MHz Fiat	6,671
<b>3017</b>							
<b>Fiat</b>							
Idea	350	2003-09	EOP	Schrader	51750439	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz Fiat/GM	236

Schrader Part Number (NEW)	Car Model Code	Start of Application	End of Application	Sensor Manufacturer	OE Sensor Reference	Sensor Description	Direct TPMS Car Park in market 2017
<b>Lancia</b>							
Musa	848	2004-07	EOP	Schrader	51750439	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz Fiat/GM	255
<b>3019</b>							
<b>Ford</b>							
Ecosport	B515	2012-07	2014-09	Schrader	DR3V-1A180-BB	Schrader Clamp-in Fixed 20deg angle 433MHz Ford	6,810
Touneo Courier	B460	2014-03	2014-09	Schrader	DR3V-1A180-BB	Schrader Clamp-in Fixed 20deg angle 433MHz Ford	992
Transit	V347,V348	2014-03	EOP	Schrader	DR3V-1A180-BB	Schrader Clamp-in Fixed 20deg angle 433MHz Ford	5
Transit Chassis	V348	2014-03	EOP	Schrader	DR3V-1A180-BB	Schrader Clamp-in Fixed 20deg angle 433MHz Ford	1
Transit Combi	V184	2014-03	EOP	Schrader	DR3V-1A180-BB	Schrader Clamp-in Fixed 20deg angle 433MHz Ford	9
Transit Combi	V347	2014-03	EOP	Schrader	DR3V-1A180-BB	Schrader Clamp-in Fixed 20deg angle 433MHz Ford	1
Transit Combi	V347,V348	2014-03	EOP	Schrader	DR3V-1A180-BB	Schrader Clamp-in Fixed 20deg angle 433MHz Ford	1
Transit Combi	V348	2014-03	EOP	Schrader	DR3V-1A180-BB	Schrader Clamp-in Fixed 20deg angle 433MHz Ford	11
Transit Courier	B460	2014-03	2014-09	Schrader	DR3V-1A180-BB	Schrader Clamp-in Fixed 20deg angle 433MHz Ford	2,274
<b>3020</b>							
<b>Ford</b>							
Edge	U387	2014-06	EOP	Schrader	BB5T-1A180-AA	Schrader Snap-in GEN4 type 433MHz Ford	260
Escape	C520	2012-04	2017-06	Schrader	BB5T-1A180-AA	Schrader Snap-in GEN4 type 433MHz Ford	2
Expedition	U222(2)	2005-01	2008-11	Schrader	BB5T-1A180-AA	Schrader Snap-in GEN4 type 433MHz Ford	43
Explorer	U502	2010-11	EOP	Schrader	BB5T-1A180-AA	Schrader Snap-in GEN4 type 433MHz Ford	168
F-150	P415	2008-09	2014-06	Schrader	BB5T-1A180-AA	Schrader Snap-in GEN4 type 433MHz Ford	43
F-Series	P 415	2008-09	2014-02	Schrader	BB5T-1A180-AA	Schrader Snap-in GEN4 type 433MHz Ford	8
Tourneo Custom	V362	2013-04	EOP	Schrader	DV6T-1A180-AA	Schrader Snap-in GEN4 type 433MHz Ford (China)	51,380
Transit	V363	2013-06	EOP	Schrader	DV6T-1A180-AA	Schrader Snap-in GEN4 type 433MHz Ford (China)	237,743
Transit Chassis	V363	2013-06	EOP	Schrader	DV6T-1A180-AA	Schrader Snap-in GEN4 type 433MHz Ford (China)	1,230
Transit Combi	V348,V363	2013-06	2021-03	Schrader	DV6T-1A180-AA	Schrader Snap-in GEN4 type 433MHz Ford (China)	45
Transit Combi	V363	2013-06	EOP	Schrader	DV6T-1A180-AA	Schrader Snap-in GEN4 type 433MHz Ford (China)	23,495
Transit Custom	V362	2013-04	EOP	Schrader	DV6T-1A180-AA	Schrader Snap-in GEN4 type 433MHz Ford (China)	322,772
<b>Mazda</b>							
B-Series	J26E	2015-06	EOP	Schrader	BB5T-1A180-AA	Schrader Snap-in GEN4 type 433MHz Ford	3
BT-50	J26E	2011-05	EOP	Schrader	BB5T-1A180-AA	Schrader Snap-in GEN4 type 433MHz Ford	6
<b>3021</b>							
<b>Ford</b>							
B-Max	B232	2014-06	EOP	Schrader	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford (China)	135,824
C-MAX	C344	2014-03	EOP	Schrader	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford (China)	281,355
Ecosport	B515	2014-10	EOP	Schrader	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford (China)	145,970
Escape	C520(2)	2014-03	EOP	Schrader	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford (China)	2
F-150	P552	2015-03	EOP	Schrader	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford (China)	236
F-150	P415(2)	2014-03	EOP	Schrader	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford (China)	2
Fiesta	B299	2016-01	EOP	Schrader	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford (China)	410,397
Fiesta		2014-05	2015-12	Schrader	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford (China)	308,937
Fiesta Van	B299	2014-06	EOP	Schrader	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford (China)	22,718
Fiesta Van	B256/257	2014-03	EOP	Schrader	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford (China)	1
Focus	C346	2014-03	EOP	Schrader	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford (China)	662,000
Focus (LCV)	C346	2010-12	EOP	Schrader	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford (China)	9
Focus C-Max	C214	2014-03	EOP	Schrader	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford (China)	2
F-Series	P415	2014-03	EOP	Schrader	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford (China)	18
F-Series	P552	2015-01	EOP	Schrader	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford (China)	33
Kuga	C520	2012-11	2019-09	Schrader	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford (China)	370,102
Mondeo	CD391	2014-10	EOP	Schrader	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford (China)	206,160
Ranger	P375	2014-06	EOP	Schrader	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford (China)	94,180
Tourneo Connect	V408	2014-03	EOP	Schrader	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford (China)	43,324
Tourneo Courier	B460	2014-10	EOP	Schrader	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford (China)	22,676
Transit	V184	2014-06	EOP	Schrader	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford (China)	1
Transit	V347	2014-06	EOP	Schrader	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford (China)	4
Transit	V348	2014-06	EOP	Schrader	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford (China)	3
Transit Connect	V408	2014-03	EOP	Schrader	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford (China)	162,869
Transit Courier	B460	2014-10	EOP	Schrader	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford (China)	64,245
<b>3023</b>							
<b>Ford</b>							
Edge	CD539	2014-08	EOP	Schrader	F2GT-1A180-CB	Schrader Snap-in Faraday 433MHz Ford (China)	18,399
Edge	CD389	2015-01	EOP	Schrader	F2GT-1A180-CB	Schrader Snap-in Faraday 433MHz Ford (China)	62
Fiesta	B479	2017-01	2022-03	Schrader	F2GT-1A180-CB	Schrader Snap-in Faraday 433MHz Ford (China)	170,222
Fiesta Van	B479	2017-01	EOP	Schrader	F2GT-1A180-CB	Schrader Snap-in Faraday 433MHz Ford (China)	2,588
Galaxy	CD390	2015-06	2022-06	Schrader	F2GT-1A180-CB	Schrader Snap-in Faraday 433MHz Ford (China)	43,649
Mustang	S550	2014-05	EOP	Schrader	F2GT-1A180-CB	Schrader Snap-in Faraday 433MHz Ford (China)	31,502
S-MAX	CD539	2015-06	2021-06	Schrader	F2GT-1A180-CB	Schrader Snap-in Faraday 433MHz Ford (China)	78
S-MAX	CD389	2015-01	EOP	Schrader	F2GT-1A180-CB	Schrader Snap-in Faraday 433MHz Ford (China)	89,420
<b>3026</b>							
<b>Chevrolet</b>							
Volt	D1JCI	2010-11	EOP	Schrader	13348393	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	773

Schrader Part Number (NEW)	Car Model Code	Start of Application	End of Application	Sensor Manufacturer	OE Sensor Reference	Sensor Description	Direct TPMS Car Park in market 2017
<b>Opel</b>							
Ampera	D1J0I	2011-09	EOP	Schrader	13348393	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	339
Astra	GM A3300	2014-01	EOP	Schrader	13348393	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	1,895
Astra		2011-07	2013-12	Schrader	13348393	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	217
Astra	GM P3400	2009-10	2011-09	Schrader	13327259	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	5,196
Astra		2011-09	2014-05	Schrader	13348393	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	7,501
Cascada	D1AO	2013-01	2014-05	Schrader	13348393	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	798
Insignia	GM G3700	2008-10	2011-09	Schrader	13327259	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	21,650
Insignia		2011-09	2014-04	Schrader	13348393	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	20,869
Zafira	GM A3370	2011-07	2016-09	Schrader	13348393	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	10,160
Zafira Tourer	GM P3470	2011-09	2014-05	Schrader	13348393	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	17,556
<b>3027</b>							
<b>Opel</b>							
Adam	GM 4403	2013-01	2014-07	Schrader	13581562	Schrader Snap-in GEN4 type 433MHz GM	280
Corsa Van	GM S4400	2007-07	2014-10	Schrader	13581562	Schrader Snap-in GEN4 type 433MHz GM	12
<b>3031</b>							
<b>Opel</b>							
Astra	GM A3300	2004-01	2011-06	Schrader	13172567	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	2,165
Astra Van	GM A3300	2004-01	EOP	Schrader	13172567	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	91
Signum	(blank)	2004-11	EOP	Schrader	13172567	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	238
Vectra	GM Z3200	2002-01	2008-09	Schrader	13172567	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	25,980
Zafira	GM A3370	2005-04	2011-06	Schrader	13172567	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	2,165
<b>3033</b>							
<b>Chevrolet</b>							
Corvette	Y1BC	2014-03	EOP	Schrader	13581560	Schrader Clamp-in Gen Gamma 433MHz GM	2,091
<b>Opel</b>							
Astra	GM P3400	2014-06	EOP	Schrader	13581560	Schrader Clamp-in Gen Gamma 433MHz GM	247,604
Astra Van	D2J0,GM P3400	2014-06	EOP	Schrader	13581560	Schrader Clamp-in Gen Gamma 433MHz GM	3
Astra Van	GM P3400	2014-06	EOP	Schrader	13581560	Schrader Clamp-in Gen Gamma 433MHz GM	117
Cascada	D1AO	2014-06	EOP	Schrader	13581560	Schrader Clamp-in Gen Gamma 433MHz GM	12,112
Insignia	GM G3700	2014-05	EOP	Schrader	13581560	Schrader Clamp-in Gen Gamma 433MHz GM	169,626
Zafira	GM P3470	2015-01	EOP	Schrader	13581560	Schrader Clamp-in Gen Gamma 433MHz GM	177
Zafira Tourer	GM P3470	2014-06	EOP	Schrader	13581560	Schrader Clamp-in Gen Gamma 433MHz GM	162,768
<b>3037</b>							
<b>Nissan</b>							
Primera	ED	2001-12	2007-05	Schrader	40700AV600	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz Nissan	1,299
<b>3038</b>							
<b>Infiniti</b>							
M	L53E	2009-12	EOP	Schrader	40700JY00B	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	883
<b>Nissan</b>							
370Z	C53D	2008-10	2014-06	Schrader	40700JY00B	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	3,627
370Z	RC53D	2009-03	EOP	Schrader	40700JY00B	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	1,195
GT-R	D52E	2007-09	2014-06	Schrader	40700JY00B	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	2,409
Murano	P42D	2007-10	EOP	Schrader	40700JY00B	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	19
Navara	H60A	2014-09	EOP	Schrader	40700JY00B	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	52,496
Navara	H61B	2004-10	EOP	Schrader	40700JY00B	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	362
Navara	D22,H61B	2014-03	EOP	Schrader	40700JY00B	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	3
Pathfinder	P61B	2004-08	EOP	Schrader	40700JY00B	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	157
Pixo	YC5	2009-01	EOP	Schrader	40700JY00B	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	3
<b>3039</b>							
<b>Infiniti</b>							
EX	P53B	2007-10	2016-03	Schrader	407001AY0A	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	1,085
FX	P53C	2008-03	2014-08	Schrader	407001AY0A	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	1,405
G	L53A	2006-08	2013-03	Schrader	407001AY0A	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	449
<b>Renault</b>							
Koleos	H45	2008-02	2013-12	Schrader	407001AY0A	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	130
<b>3040</b>							
<b>Renault</b>							
Clio	X85	2005-04	2014-05	Schrader	8200253215	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz Renault	12,990
Modus	J77	2004-05	EOP	Schrader	8200253215	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz Renault	2,166
<b>3042</b>							
<b>Renault</b>							
Espace	J81	2002-07	EOP	Schrader	8200023746	Schrader Clamp-in Gen 2/3 Type fixed 10deg angle Small Grommet Seal 433MHz Renault	53,637
Grand Espace	J81	2002-07	EOP	Schrader	8200023746	Schrader Clamp-in Gen 2/3 Type fixed 10deg angle Small Grommet Seal 433MHz Renault	4,332
Laguna	X74	2000-12	2007-09	Schrader	8200023746	Schrader Clamp-in Gen 2/3 Type fixed 10deg angle Small Grommet Seal 433MHz Renault	108,250
Megane	X64	1997-01	2002-10	Schrader	8200023746	Schrader Clamp-in Gen 2/3 Type fixed 10deg angle Small Grommet Seal 433MHz Renault	8,660
Scenic	J64	1997-01	2003-06	Schrader	8200023746	Schrader Clamp-in Gen 2/3 Type fixed 10deg angle Small Grommet Seal 433MHz Renault	8,660
Vel Satis	X73	2001-09	2009-11	Schrader	8200023746	Schrader Clamp-in Gen 2/3 Type fixed 10deg angle Small Grommet Seal 433MHz Renault	108,250
<b>3046</b>							
<b>Volvo</b>							
XC90	Y289	2015-01	EOP	Schrader	30748354	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz Volvo	16
XC90		2002-04	2014-12	Schrader	30748354	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz Volvo	645

Schrader Part Number (NEW)	Car Model Code	Start of Application	End of Application	Sensor Manufacturer	OE Sensor Reference	Sensor Description	Direct TPMS Car Park in market 2017
<b>3049</b>							
<b>Buick</b>							
Park Avenue	G-CAR	1997-01	2004-06	Schrader	25789964	Schrader Snap-in GEN4 type 433MHz GM	22
<b>Cadillac</b>							
CTS	GMX206	2008-01	EOP	Schrader	20922901	Schrader Snap-in GEN4 type 433MHz GM	47
CTS	GMX226	2010-06	EOP	Schrader	20922901	Schrader Snap-in GEN4 type 433MHz GM	43
Escalade	GMT926	2005-12	EOP	Schrader	22853740	Schrader Snap-in GEN4 type 433MHz GM (China)	36
Escalade	K2UL	2014-01	EOP	Schrader	22853740	Schrader Snap-in GEN4 type 433MHz GM (China)	486
SRX	GMT166	2009-07	EOP	Schrader	25789964	Schrader Snap-in GEN4 type 433MHz GM	364
SRX	GMT265	2005-06	2009-02	Schrader	25789964	Schrader Snap-in GEN4 type 433MHz GM	87
XTS	P1LL	2012-05	EOP	Schrader	22853740	Schrader Snap-in GEN4 type 433MHz GM (China)	11
<b>Chevrolet</b>							
Aveo	G1JC	2014-03	EOP	Schrader	22853740	Schrader Snap-in GEN4 type 433MHz GM (China)	12
Aveo	G1SC	2010-11	2016-12	Schrader	22853740	Schrader Snap-in GEN4 type 433MHz GM (China)	350
Aveo			2018-05	Schrader	22853740	Schrader Snap-in GEN4 type 433MHz GM (China)	95
Aveo	T250	2014-03	EOP	Schrader	22853740	Schrader Snap-in GEN4 type 433MHz GM (China)	2
Captiva	C100	2006-06	2014-05	Schrader	25789964	Schrader Snap-in GEN4 type 433MHz GM	8,540
Captiva			EOP	Schrader	25789964	Schrader Snap-in GEN4 type 433MHz GM	7,548
Cruze	D1JC	2014-06	EOP	Schrader	22853740	Schrader Snap-in GEN4 type 433MHz GM (China)	17
Cruze	D1SC	2008-10	EOP	Schrader	22853740	Schrader Snap-in GEN4 type 433MHz GM (China)	175
Cruze	D1WC	2014-06	EOP	Schrader	22853740	Schrader Snap-in GEN4 type 433MHz GM (China)	16
Express	GMT610	2014-06	EOP	Schrader	22853740	Schrader Snap-in GEN4 type 433MHz GM (China)	3
Express (PC)	GMT610	2002-07	EOP	Schrader	22853740	Schrader Snap-in GEN4 type 433MHz GM (China)	65
Malibu	V300	2010-07	2011-06	Schrader	20922901	Schrader Snap-in GEN4 type 433MHz GM	30
Orlando	D1NC	2014-06	EOP	Schrader	22853740	Schrader Snap-in GEN4 type 433MHz GM (China)	464
Orlando	J309	2010-09	2017-12	Schrader	22853740	Schrader Snap-in GEN4 type 433MHz GM (China)	94
Silverado	K2XC	2014-06	EOP	Schrader	22853740	Schrader Snap-in GEN4 type 433MHz GM (China)	125
Spark	M1JC	2009-07	EOP	Schrader	22853740	Schrader Snap-in GEN4 type 433MHz GM (China)	1,561
Suburban	GMT931	2006-03	EOP	Schrader	22853740	Schrader Snap-in GEN4 type 433MHz GM (China)	37
Trax	G1UC	2012-03	EOP	Schrader	22853740	Schrader Snap-in GEN4 type 433MHz GM (China)	11,647
<b>GMC</b>							
Savana	GMT610	2002-07	2012-01	Schrader	25789964	Schrader Snap-in GEN4 type 433MHz GM	17
Savana Cargo	GMT610	2002-07	EOP	Schrader	25789964	Schrader Snap-in GEN4 type 433MHz GM	42
Sierra	GMT902	2006-10	2009-05	Schrader	22853740	Schrader Snap-in GEN4 type 433MHz GM (China)	65
Sierra		2009-06	EOP	Schrader	20922901	Schrader Snap-in GEN4 type 433MHz GM	6
Sierra	K2XG	2013-04	EOP	Schrader	22853740	Schrader Snap-in GEN4 type 433MHz GM (China)	31
Yukon	GMT922	2014-03	EOP	Schrader	22853740	Schrader Snap-in GEN4 type 433MHz GM (China)	6
Yukon	K2UG	2014-03	EOP	Schrader	22853740	Schrader Snap-in GEN4 type 433MHz GM (China)	330
Yukon	GMT922(2)	2005-12	2013-12	Schrader	22853740	Schrader Snap-in GEN4 type 433MHz GM (China)	218
<b>Hummer</b>							
H2	H2	2002-04	2008-12	Schrader	25789964	Schrader Snap-in GEN4 type 433MHz GM	130
H3	GMT345	2005-03	2012-01	Schrader	25789964	Schrader Snap-in GEN4 type 433MHz GM	66
<b>Opel</b>							
Antara	C105	2010-11	2015-12	Schrader	22853740	Schrader Snap-in GEN4 type 433MHz GM (China)	11,994
Antara		2006-08	2010-11	Schrader	25789964	Schrader Snap-in GEN4 type 433MHz GM	520
Mokka	G1UO	2012-06	2015-08	Schrader	22853740	Schrader Snap-in GEN4 type 433MHz GM (China)	177,549
<b>3053</b>							
<b>Cadillac</b>							
STS	GMX295	2005-06	2011-04	Schrader	25758221	Schrader Clamp-in Gen J 433MHz GM	22
XLR	GMX215	2003-05	2009-04	Schrader	25758221	Schrader Clamp-in Gen J 433MHz GM	22
<b>Chevrolet</b>							
Colorado (LCV)	GMT355	2003-10	EOP	Schrader	25758221	Schrader Clamp-in Gen J 433MHz GM	43
Corvette	GMX245	2004-07	2010-01	Schrader	25758221	Schrader Clamp-in Gen J 433MHz GM	2,598
<b>3054</b>							
<b>Cadillac</b>							
ATS	A1BL	2014-07	EOP	Schrader	20925925	Schrader Clamp-in Gen J 433MHz GM	211
ATS	A1SL	2012-07	EOP	Schrader	20925925	Schrader Clamp-in Gen J 433MHz GM	309
CTS	A1LL	2013-09	EOP	Schrader	20925925	Schrader Clamp-in Gen J 433MHz GM	397
<b>Chevrolet</b>							
Camaro	A1BC	2015-10	EOP	Schrader	20925925	Schrader Clamp-in Gen J 433MHz GM	1,889
Camaro	GMX521	2010-11	EOP	Schrader	20925925	Schrader Clamp-in Gen J 433MHz GM	1,141
Colorado	GMI700	2011-10	EOP	Schrader	20925925	Schrader Clamp-in Gen J 433MHz GM	4
Corvette	GMX245	2010-02	2014-12	Schrader	20925925	Schrader Clamp-in Gen J 433MHz GM	1,311
Corvette	GMX245(2)	2014-03	EOP	Schrader	20925925	Schrader Clamp-in Gen J 433MHz GM	2
Tahoe	GMT921	2014-03	EOP	Schrader	20925925	Schrader Clamp-in Gen J 433MHz GM	63
<b>Opel</b>							
VXR8	Z2	2014-03	EOP	Schrader	20925925	Schrader Clamp-in Gen J 433MHz GM	31
<b>3055</b>							
<b>Cadillac</b>							
CTS	GMX322	2013-09	EOP	Schrader	25774007	Schrader Clamp-in Gen J 433MHz GM	6
CTS		2006-01	2007-06	Schrader	25774007	Schrader Clamp-in Gen J 433MHz GM	56

Schrader Part Number (NEW)	Car Model Code	Start of Application	End of Application	Sensor Manufacturer	OE Sensor Reference	Sensor Description	Direct TPMS Car Park in market 2017
<b>Chevrolet</b>							
Trailblazer (LCV)	GMT360	2001-01	EOP	Schrader	25774007	Schrader Clamp-in Gen J 433MHz GM	217
<b>3056</b>							
<b>Hyundai</b>							
Veloster	FS	2011-02	EOP	Schrader	52933-2V100	Schrader Snap-in GEN4 type 433MHz HKMC	884
Veloster	JS	2017-01	EOP	Schrader	52933-2V100	Schrader Snap-in GEN4 type 433MHz HKMC	8
<b>3057</b>							
<b>Alpina</b>							
Alpina 5	G30	2017-01	EOP	Schrader	36106872774	Schrader Clamp-in Gen Delta 433MHz BMW	38
Alpina 7	G11	2016-01	EOP	Schrader	36106872774	Schrader Clamp-in Gen Delta 433MHz BMW	25
<b>BMW</b>							
5-Series	G30	2017-01	EOP	Schrader	36106872774	Schrader Clamp-in Gen Delta 433MHz BMW	76,153
5-Series GT	G32	2017-01	EOP	Schrader	36106872774	Schrader Clamp-in Gen Delta 433MHz BMW	1,953
7-Series	G11	2015-07	2022-06	Schrader	36106872774	Schrader Clamp-in Gen Delta 433MHz BMW	27,570
X3	G01	2017-01	EOP	Schrader	36106872774	Schrader Clamp-in Gen Delta 433MHz BMW	4,830
<b>Mercedes-Benz</b>							
E-Class	C238	2017-07	EOP	Schrader	A0009052102	Schrader Clamp-in Gen Delta 433MHz Daimler	7,470
E-Class	W213	2015-11	2023-03	Schrader	A0009052102	Schrader Clamp-in Gen Delta 433MHz Daimler	157,459
<b>Rolls-Royce</b>							
Phantom	RR11	2017-01	EOP	Schrader	36106872774	Schrader Clamp-in Gen Delta 433MHz BMW	62
<b>3058</b>							
<b>Lotus</b>							
3-ELEVEN	3-ELEVEN	2016-01	EOP	Schrader	B121G600F	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	46
Elise	Monza	2008-01	EOP	Schrader	B121G600F	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	1,371
Evora	Eagle	2010-01	EOP	Schrader	B121G600F	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	876
Exige	Monza	2008-01	EOP	Schrader	B121G600F	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	1,140
<b>Saab</b>							
Saab 9-3	SB440	2007-07	EOP	Schrader	B121G600F	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	3
<b>3059</b>							
<b>Hyundai</b>							
i10	IA	2013-11	EOP	Schrader	52933-B2100	Schrader Snap-in HS with 20deg angle 433MHz HKMC	277,664
<b>Kia</b>							
Carnival	YP	2014-07	EOP	Schrader	52933-B2100	Schrader Snap-in HS with 20deg angle 433MHz HKMC	5
Soul	PS	2013-11	EOP	Schrader	52933-B2100	Schrader Snap-in HS with 20deg angle 433MHz HKMC	47,066
<b>3060</b>							
<b>Hyundai</b>							
i20	GB	2014-01	EOP	Schrader	52933-C1100	Schrader Snap-in Faraday 433MHz HKMC	261,846
i20	GB,IB	2014-11	EOP	Schrader	52933-C1100	Schrader Snap-in Faraday 433MHz HKMC	67
Tucson	TL	2015-01	EOP	Schrader	52933-C1100	Schrader Snap-in Faraday 433MHz HKMC	334,018
<b>3062</b>							
<b>Chevrolet</b>							
Malibu	V300	2014-07	EOP	Schrader	13581561	Schrader Snap-in GEN4 type 433MHz GM	2
Malibu	GMX351	2015-01	EOP	Schrader	13581561	Schrader Snap-in GEN4 type 433MHz GM	1
Malibu	GMX386	2014-03	EOP	Schrader	13581561	Schrader Snap-in GEN4 type 433MHz GM	1
<b>Mahindra</b>							
Bolero	CL/MM	2014-06	EOP	Schrader	1805BA0131N-A	Schrader Snap-in GEN4 type 433MHz Mahindra	1
Bolero	U301	2015-07	EOP	Schrader	1805BA0131N-A	Schrader Snap-in GEN4 type 433MHz Mahindra	2
Goa	W105	2015-01	EOP	Schrader	1805BA0131N-A	Schrader Snap-in GEN4 type 433MHz Mahindra	276
KUV100	S101	2016-01	EOP	Schrader	1805BA0131N-A	Schrader Snap-in GEN4 type 433MHz Mahindra	19
NC	CL/MM	2014-06	EOP	Schrader	1805BA0131N-A	Schrader Snap-in GEN4 type 433MHz Mahindra	4
Scorpio	U202	2015-01	EOP	Schrader	1805BA0131N-A	Schrader Snap-in GEN4 type 433MHz Mahindra	7
Thar	CL/MM	2014-06	EOP	Schrader	1805BA0131N-A	Schrader Snap-in GEN4 type 433MHz Mahindra	4
XUV500	W201	2014-06	EOP	Schrader	1805BA0131N-A	Schrader Snap-in GEN4 type 433MHz Mahindra	1,174
<b>Opel</b>							
Adam	GM 4403	2014-08	2015-08	Schrader	13581561	Schrader Snap-in GEN4 type 433MHz GM	45,360
Adam		2015-08	EOP	Schrader	13581561	Schrader Snap-in GEN4 type 433MHz GM	124,723
Corsa	GM 4530	2014-11	2015-02	Schrader	13581561	Schrader Snap-in GEN4 type 433MHz GM	33,892
Corsa		2015-03	EOP	Schrader	13581561	Schrader Snap-in GEN4 type 433MHz GM	668,109
Corsa Van	GM 4530	2014-03	EOP	Schrader	13581561	Schrader Snap-in GEN4 type 433MHz GM	15,136
Meriva	GM S4470	2014-08	EOP	Schrader	13581561	Schrader Snap-in GEN4 type 433MHz GM	114,400
<b>3063</b>							
<b>Cadillac</b>							
CT6	O1SL	2016-01	EOP	Schrader	13589601	Schrader Snap-in Faraday 433MHz GM	183
SRX	C1UL	2016-01	EOP	Schrader	13598773	Schrader Snap-in Faraday 433MHz GM (China)	12
XT5	C1UL	2016-01	EOP	Schrader	13598773	Schrader Snap-in Faraday 433MHz GM (China)	364
<b>Opel</b>							
Ampera-e	G2KCZ	2017-01	EOP	Schrader	13589601	Schrader Snap-in Faraday 433MHz GM	3,514
Antara	C105	2016-01	EOP	Schrader	13598773	Schrader Snap-in Faraday 433MHz GM (China)	3,901
Bolt	G2KCZ	2017-01	EOP	Schrader	13589601	Schrader Snap-in Faraday 433MHz GM	15
Karl	M2JO	2015-01	EOP	Schrader	13598773	Schrader Snap-in Faraday 433MHz GM (China)	105,604
Mokka	G1UO	2015-09	EOP	Schrader	13598773	Schrader Snap-in Faraday 433MHz GM (China)	381,005
Viva	M2JO	2015-01	EOP	Schrader	13598773	Schrader Snap-in Faraday 433MHz GM (China)	30,259

Schrader Part Number (NEW)	Car Model Code	Start of Application	End of Application	Sensor Manufacturer	OE Sensor Reference	Sensor Description	Direct TPMS Car Park in market 2017
<b>3064</b>							
<b>Subaru</b>							
C-Concept	VL9	2014-06	EOP	Schrader	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	84
Forester	FM5	2014-01	EOP	Schrader	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	45,617
Forester	PF3	2014-01	EOP	Schrader	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	9
Impreza	MF1	2014-01	EOP	Schrader	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	2,968
Impreza	ZR1	2014-01	EOP	Schrader	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	549
Justy	D71A	2014-01	EOP	Schrader	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	1
Legacy	BF4	2014-01	EOP	Schrader	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	1,648
Legacy	EZ5	2014-03	EOP	Schrader	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	753
Levorg	VL9	2015-09	EOP	Schrader	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	9,436
Outback	04AL	2014-11	EOP	Schrader	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	32
Outback	BF4	2014-09	EOP	Schrader	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	23,735
Outback	EZ5	2014-03	EOP	Schrader	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	6
Trezia	217A	2014-01	EOP	Schrader	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	290
Tribeca	00X(2)	2016-05	EOP	Schrader	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	10
WRX	MF1	2014-03	EOP	Schrader	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	2
WRX	VL9	2014-03	EOP	Schrader	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	2,075
XV	MF1	2014-01	EOP	Schrader	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	32,241
<b>3068</b>							
<b>Ssangyong</b>							
Actyon	C100	2014-03	EOP	Schrader	41990-34000	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	60
Actyon Sports	Q150	2014-03	EOP	Schrader	41990-34000	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	296
Actyon SUT	Q150	2014-11	EOP	Schrader	41990-34000	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	412
Actyon SUT	Q100	2014-03	EOP	Schrader	41990-34000	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	174
Korando	K150	2014-03	EOP	Schrader	41990-34000	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	36
Korando C	C200/AS11	2013-08	EOP	Schrader	41990-34000	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	17,110
Korando Sports	Q150	2014-11	EOP	Schrader	41990-34000	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	444
Musso	Q150	2016-01	EOP	Schrader	41990-34000	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	315
Rexton	Y200	2014-05	EOP	Schrader	41990-34000	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	6,467
Rexton	Y400	2016-10	EOP	Schrader	41990-34000	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	556
Rexton SC	Y200	2014-05	EOP	Schrader	41990-34000	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	28
Rodius	A100	2014-05	EOP	Schrader	41990-34000	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	6,244
<b>3069</b>							
<b>Volvo</b>							
S90	V541	2016-01	EOP	Schrader	31362304	Schrader Snap-in HS with 20deg angle 433MHz Volvo	15,591
V90	V542	2015-04	2016-03	Schrader	31362304	Schrader Snap-in HS with 20deg angle 433MHz Volvo	3,331
V90 Cross Country	V543	2016-01	EOP	Schrader	31362304	Schrader Snap-in HS with 20deg angle 433MHz Volvo	11,452
XC90	V526	2015-01	2016-03	Schrader	31362304	Schrader Snap-in HS with 20deg angle 433MHz Volvo	25,185
<b>3071</b>							
<b>Cadillac</b>							
ELR	D1BLI	2016-01	EOP	Schrader	13594222	Schrader Snap-in Faraday 433MHz GM	4
<b>Chevrolet</b>							
Volt	D2JCI	2015-06	2020-09	Schrader	13594222	Schrader Snap-in Faraday 433MHz GM	70
<b>Opel</b>							
Ampera	D2JCI	2015-01	EOP	Schrader	13594222	Schrader Snap-in Faraday 433MHz GM	39
Ampera	D2JOI	2016-01	EOP	Schrader	13594222	Schrader Snap-in Faraday 433MHz GM	43
Astra	D2JO	2015-08	EOP	Schrader	13594222	Schrader Snap-in Faraday 433MHz GM	479,352
Astra Van	D2JO	2015-01	EOP	Schrader	13594222	Schrader Snap-in Faraday 433MHz GM	526
Equinox	D2UC	2017-01	EOP	Schrader	13594222	Schrader Snap-in Faraday 433MHz GM	9,322
<b>3073</b>							
<b>Renault</b>							
Clio	X98	2014-06	EOP	Schrader	407009987R	Schrader Snap-in Faraday 433MHz Renault T4	293,981
Clio Van	X10_X98	2014-03	EOP	Schrader	407009987R	Schrader Snap-in Faraday 433MHz Renault T4	3
<b>3076</b>							
<b>Subaru</b>							
Impreza	HR3	2017-01	EOP	Schrader	28103FL000/FL00A	Schrader Snap-in Faraday 433MHz Subaru	4,246
<b>4001</b>							
<b>Alfa Romeo</b>							
8C Competizione	920	2007-01	EOP	Huf	99760602100	Beru-Huf Clamp-in Separate valve G1 433MHz Porsche	72
<b>Audi</b>							
A6 Allroad	AU566	2000-04	2005-08	Huf	4D0907275C	Beru-Huf Clamp-in Separate valve G1.2 433MHz VW Group	130
A8	AU631	1999-09	2010-07	Huf	4D0907275C	Beru-Huf Clamp-in Separate valve G1.2 433MHz VW Group	6,495
<b>Bentley</b>							
Continental GT	BY614	2003-09	2005-05	Huf	4D0907275	Beru-Huf Clamp-in Separate valve G1 433MHz VW Group	4
<b>Maybach</b>							
57/62	W240	2002-09	EOP	Huf	A0055422318	Beru-Huf Clamp-in Separate valve G1.2 433MHz Daimler	221
<b>Mercedes-Benz</b>							
C-Class	W203	2000-01	2006-12	Huf	A0055422318	Beru-Huf Clamp-in Separate valve G1.2 433MHz Daimler	13
CL	C215	1999-07	2005-09	Huf	A0055422318	Beru-Huf Clamp-in Separate valve G1.2 433MHz Daimler	130
CLS	C219	2004-10	2005-06	Huf	A0055422318	Beru-Huf Clamp-in Separate valve G1.2 433MHz Daimler	217
S-Class	W220	1999-07	2005-09	Huf	A0055422318	Beru-Huf Clamp-in Separate valve G1.2 433MHz Daimler	650

Schrader Part Number (NEW)	Car Model Code	Start of Application	End of Application	Sensor Manufacturer	OE Sensor Reference	Sensor Description	Direct TPMS Car Park in market 2017
SL	R230	2001-01	2005-05	Huf	A0055422318	Beru-Huf Clamp-in Separate valve G1.2 433MHz Daimler	650
SLR	C199	2004-01	2010-12	Huf	A0055422318	Beru-Huf Clamp-in Separate valve G1.2 433MHz Daimler	433
<b>Porsche</b>							
911	997	2004-07	2008-03	Huf	99760602100	Beru-Huf Clamp-in Separate valve G1 433MHz Porsche	1,299
Boxster	987	2004-11	2008-10	Huf	99760602100	Beru-Huf Clamp-in Separate valve G1 433MHz Porsche	1,083
Cayman	987	2005-01	2008-01	Huf	99760602100	Beru-Huf Clamp-in Separate valve G1 433MHz Porsche	650
<b>Volkswagen</b>							
Phaeton	VW611	2002-04	2007-05	Huf	99760602100	Beru-Huf Clamp-in Separate valve G1 433MHz Porsche	1,732
<b>4002</b>							
<b>BMW</b>							
3-Series	E46	1997-05	2004-12	Huf	36112360420	Beru-Huf Clamp-in Separate valve G1.2 433MHz BMW	2,165
3-Series		2005-01	EOP	Huf	36112360420	Beru-Huf Clamp-in Separate valve G1.2 433MHz BMW	16
5-Series	E39	1998-09	2003-07	Huf	36118378682	Beru-Huf Clamp-in Separate valve G1 433MHz BMW	1,299
7-Series	E39	1998-09	2001-10	Huf	36112360420	Beru-Huf Clamp-in Separate valve G1.2 433MHz BMW	1,299
7-Series	E65	2001-11	2003-11	Huf	36112360420	Beru-Huf Clamp-in Separate valve G1.2 433MHz BMW	1,299
<b>4003</b>							
<b>BMW</b>							
X5	E53	1999-10	2004-04	Huf	36146752128	Beru-Huf Clamp-in Separate valve G1.2 plus 433MHz BMW	1,299
<b>4005</b>							
<b>Ferrari</b>							
Enzo	Enzo	2003-09	2004-12	Huf	193867	Beru-Huf Clamp-in Separate valve G1 plus 433MHz Ferrari	69
<b>Porsche</b>							
Cayenne	E2	2002-12	2006-12	Huf	95536166101	Beru-Huf Clamp-in Separate valve G1.2 plus 433MHz Porsche	1,299
<b>Volkswagen</b>							
Touareg	VW516	2002-10	2006-12	Huf	7L0907275B	Beru-Huf Clamp-in Separate valve G1.2 plus 433MHz VW/Porsche	2,598
<b>4007</b>							
<b>Alpina</b>							
Alpina 3	E90	2007-03	2009-09	Huf	36236798726	Beru-Huf Clamp-in Separate valve G2.4 433MHz BMW	65
Alpina 6	E63	2006-03	EOP	Huf	36236798726	Beru-Huf Clamp-in Separate valve G2.4 433MHz BMW	6
<b>BMW</b>							
3-Series	E90/E91/E92/E93	2006-06	2009-09	Huf	36236798726	Beru-Huf Clamp-in Separate valve G2.4 433MHz BMW	43
5-Series	E60/E61/F07	2004-01	2010-08	Huf	36236798726	Beru-Huf Clamp-in Separate valve G2.4 433MHz BMW	866
6-Series	E63	2006-03	2010-12	Huf	36236798726	Beru-Huf Clamp-in Separate valve G2.4 433MHz BMW	433
7-Series	E65/E66	2006-03	2008-07	Huf	36236798726	Beru-Huf Clamp-in Separate valve G2.4 433MHz BMW	1,299
7-Series	F01/F02/E68	2008-09	2010-08	Huf	36236798726	Beru-Huf Clamp-in Separate valve G2.4 433MHz BMW	1,299
X3	E83	2003-03	2010-08	Huf	36236798726	Beru-Huf Clamp-in Separate valve G2.4 433MHz BMW	433
X5	E70	2006-10	2010-09	Huf	36236798726	Beru-Huf Clamp-in Separate valve G2.4 433MHz BMW	3,248
X6	E71	2007-12	2011-10	Huf	36236798726	Beru-Huf Clamp-in Separate valve G2.4 433MHz BMW	433
Z4	E89	2009-05	2010-08	Huf	36236798726	Beru-Huf Clamp-in Separate valve G2.4 433MHz BMW	22
Z4 Coupe	E86	2006-04	2008-08	Huf	36236798726	Beru-Huf Clamp-in Separate valve G2.4 433MHz BMW	43
<b>Mini</b>							
Clubman	R55	2007-08	2009-09	Huf	36236798726	Beru-Huf Clamp-in Separate valve G2.4 433MHz BMW	43
<b>Rolls-Royce</b>							
Ghost	RR04	2009-12	2010-08	Huf	36236798726	Beru-Huf Clamp-in Separate valve G2.4 433MHz BMW	22
Phantom	RR01	2007-09	2011-12	Huf	36236798726	Beru-Huf Clamp-in Separate valve G2.4 433MHz BMW	87
Phantom Drophead Coupe	RR02	2006-08	EOP	Huf	36236798726	Beru-Huf Clamp-in Separate valve G2.4 433MHz BMW	196
<b>4009</b>							
<b>Aston Martin</b>							
DB9	AM803	2012-07	EOP	Huf	AD43-360671-AA	Beru-Huf Clamp-in Separate valve G1.2 433MHz Fiat Group	546
DB9		2009-01	2012-06	Huf	AD43-360671-AA	Beru-Huf Clamp-in Separate valve G1.2 433MHz Fiat Group	15
DB9	VH500	2016-10	EOP	Huf	CD23-360671-CA	Beru-Huf Clamp-in Separate valve G1.2 433MHz Fiat Group	29
DBS	AM803	2009-01	EOP	Huf	AD43-360671-AA	Beru-Huf Clamp-in Separate valve G1.2 433MHz Fiat Group	2
Lagonda	COMET	2015-01	EOP	Huf	CD23-360671-CA	Beru-Huf Clamp-in Separate valve G1.2 433MHz Fiat Group	8
Rapide	VH400	2010-01	EOP	Huf	282189	Beru-Huf Clamp-in Separate valve G2.4 433MHz Fiat	502
V12 Zagato	Zagato	2012-09	EOP	Huf	CD23-360671-CA	Beru-Huf Clamp-in Separate valve G1.2 433MHz Fiat Group	1
V8 Vantage	AM305	2009-01	EOP	Huf	AD43-360671-AA	Beru-Huf Clamp-in Separate valve G1.2 433MHz Fiat Group	45
V8 Vantage	VH600	2014-01	2016-12	Huf	AD43-360671-AA	Beru-Huf Clamp-in Separate valve G1.2 433MHz Fiat Group	42
V8 Vantage	VH600(1)	2017-01	EOP	Huf	CD23-360671-CA	Beru-Huf Clamp-in Separate valve G1.2 433MHz Fiat Group	12
Vanquish	AM310	2012-06	EOP	Huf	CD23-360671-CA	Beru-Huf Clamp-in Separate valve G1.2 433MHz Fiat Group	775
Vantage	AM305	2014-03	EOP	Huf	AD43-360671-AA	Beru-Huf Clamp-in Separate valve G1.2 433MHz Fiat Group	1,981
Vantage	VH600	2017-01	EOP	Huf	CD23-360671-CA	Beru-Huf Clamp-in Separate valve G1.2 433MHz Fiat Group	61
<b>Audi</b>							
A4	AU461/AU471	2004-11	2007-10	Huf	7PP907275F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	2,165
A4 Cabrio	AU465/AU475	2008-08	EOP	Huf	7PP907275F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	1
A4 Cabrio		2006-01	2008-07	Huf	7PP907275F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	433
A6	AU561	2009-06	2011-03	Huf	7PP907275F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	433
A6		2004-05	2009-06	Huf	7PP907275F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	433
A6	AU571	2011-01	EOP	Huf	7PP907275F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	98,483
A6 Allroad	AU566	2009-06	2011-08	Huf	7PP907275F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	130
A6 Allroad		2006-05	2009-06	Huf	7PP907275F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	130
A6 Allroad	AU572/4	2012-01	EOP	Huf	7PP907275F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	4,802
A8	AU641	2009-11	EOP	Huf	7PP907275F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	17,216



Schrader Part Number (NEW)	Car Model Code	Start of Application	End of Application	Sensor Manufacturer	OE Sensor Reference	Sensor Description	Direct TPMS Car Park in market 2017
Q7	AU716	2006-03	2009-06	Huf	7PP907275F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	2,165
Q7		2009-06	2014-05	Huf	7PP907275F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	3,278
R8	AU714	2009-06	2015-03	Huf	7PP907275F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	718
R8		2007-04	2009-06	Huf	7PP907275F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	433
<b>Bentley</b>							
Azure	BY824	2006-06	2011-12	Huf	7PP907275F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	4
Azure	BY835	2013-10	2020-10	Huf	7PP907275F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	23
Bentayga	BY636	2016-01	EOP	Huf	7PP907275F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	2,265
Continental	ROLLS ROYCE	2014-03	EOP	Huf	4F0907275B	Beru-Huf Clamp-in Separate valve G2.2 433MHz VW/Porsche	1
Continental Flying Spur	BY611	2005-03	2010-12	Huf	7PP907275F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	1,300
Continental Flying Spur	BY621	2010-01	EOP	Huf	7PP907275F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	2,100
Continental Flying Spur	BY611(2)	2011-01	EOP	Huf	7PP907275F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	2
Continental GT	BY634	2017-07	EOP	Huf	7PP907275F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	26
Continental GT	BY624	2014-03	EOP	Huf	4F0907275B	Beru-Huf Clamp-in Separate valve G2.2 433MHz VW/Porsche	2,803
Continental GTC	BY615	2006-12	EOP	Huf	7PP907275F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	2,603
Continental GTC	BY625	2011-11	EOP	Huf	7PP907275F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	3,246
E-CUV	BY716	2014-11	2022-10	Huf	7PP907275F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	48
E-CUV	BY736	2016-03	EOP	Huf	7PP907275F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	33
Mulsanne	BY831	2009-09	EOP	Huf	7PP907275F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	706
Mulsanne	BY731	2014-03	EOP	Huf	7PP907275F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	711
<b>Bugatti</b>							
Royale	BG831	2016-01	EOP	Huf	7PP907275F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	14
Veyron	BG824	2011-12	EOP	Huf	7PP907275F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	15
Veyron		2005-09	2011-11	Huf	7PP907275F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	2
<b>Ferrari</b>							
550 Maranello	F133	2002-03	EOP	Huf	248887	Beru-Huf Clamp-in Separate valve G1.2 433MHz Fiat Group	217
California	F149	2014-11	EOP	Huf	228887	Beru-Huf Clamp-in Separate valve G2.3 433MHz Fiat	1,910
California		2008-07	2014-10	Huf	228887	Beru-Huf Clamp-in Separate valve G2.3 433MHz Fiat	2,240
California	F149(2)	2017-01	EOP	Huf	228887	Beru-Huf Clamp-in Separate valve G2.3 433MHz Fiat	553
F12	F152	2012-10	EOP	Huf	282189	Beru-Huf Clamp-in Separate valve G2.4 433MHz Fiat	1,606
F430	F131	2007-07	2009-12	Huf	228887	Beru-Huf Clamp-in Separate valve G2.3 433MHz Fiat	22
F430 Scuderia	F131	2007-07	2012-06	Huf	99760602120	Beru-Huf Clamp-in Separate valve G2.3 433MHz Fiat	43
F458	F142	2009-12	EOP	Huf	228887	Beru-Huf Clamp-in Separate valve G2.3 433MHz Fiat	5,318
F488	F142M	2015-01	EOP	Huf	282189	Beru-Huf Clamp-in Separate valve G2.4 433MHz Fiat	3,300
FF	F151	2011-06	EOP	Huf	282189	Beru-Huf Clamp-in Separate valve G2.4 433MHz Fiat	825
LaFerrari	F150	2013-07	EOP	Huf	282189	Beru-Huf Clamp-in Separate valve G2.4 433MHz Fiat	228
<b>Lamborghini</b>							
Aventador	LB834	2011-05	EOP	Huf	7PP907275F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	43
Aventador	LB734	2014-03	EOP	Huf	7PP907275F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	910
Gallardo	LB714	2010-02	2013-05	Huf	4F0907275D	Beru-Huf Clamp-in Separate valve G2.3 433MHz VW/Porsche	448
Gallardo		2007-06	2010-01	Huf	4F0907275D	Beru-Huf Clamp-in Separate valve G2.3 433MHz VW/Porsche	433
Gallardo	LB724	2013-06	2021-03	Huf	7PP907275F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	45
Gallardo	LB614	2014-03	EOP	Huf	7PP907275F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	19
Huracan	LB724	2014-03	EOP	Huf	7PP907275F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	36
Huracan	LB624	2014-03	EOP	Huf	7PP907275F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	1,793
Murcielago	LB824	2010-11	EOP	Huf	4F0907275D	Beru-Huf Clamp-in Separate valve G2.3 433MHz VW/Porsche	1
<b>Maserati</b>							
GranCabrio	M147	2009-09	2015-06	Huf	99760602120	Beru-Huf Clamp-in Separate valve G2.3 433MHz Fiat	161
GranTurismo	M145	2010-09	2013-12	Huf	282189	Beru-Huf Clamp-in Separate valve G2.4 433MHz Fiat	13
GT Coupe	M145	2009-07	2013-12	Huf	228887	Beru-Huf Clamp-in Separate valve G2.3 433MHz Fiat	224
GT Coupe		2002-01	2009-06	Huf	248887	Beru-Huf Clamp-in Separate valve G1.2 433MHz Fiat Group	217
Quattroporte	M139	2010-01	EOP	Huf	228887	Beru-Huf Clamp-in Separate valve G2.3 433MHz Fiat	433
Quattroporte		2004-04	2009-12	Huf	248887	Beru-Huf Clamp-in Separate valve G1.2 433MHz Fiat Group	437
<b>McLaren</b>							
MP4-12C	P11	2011-04	EOP	Huf	11B0015CP	Beru-Huf Clamp-in Separate valve G1.2 433MHz Fiat Group	18
P1	P12	2013-01	EOP	Huf	11B0015CP	Beru-Huf Clamp-in Separate valve G1.2 433MHz Fiat Group	3
P13	P13	2015-08	EOP	Huf	11B0015CP	Beru-Huf Clamp-in Separate valve G1.2 433MHz Fiat Group	30
Sports Series	P13	2015-01	EOP	Huf	11B0015CP	Beru-Huf Clamp-in Separate valve G1.2 433MHz Fiat Group	1,587
Super Series	P11	2014-03	EOP	Huf	11B0015CP	Beru-Huf Clamp-in Separate valve G1.2 433MHz Fiat Group	591
Ultimate Series	P12	2014-03	EOP	Huf	11B0015CP	Beru-Huf Clamp-in Separate valve G1.2 433MHz Fiat Group	17
<b>Porsche</b>							
911	991	2011-12	2015-08	Huf	7PP907275F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	41
911	997	2008-04	2011-12	Huf	7PP907275F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	3,464
911	PO674	2014-03	EOP	Huf	7PP907275F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	46,075
918 Spyder	918	2015-01	EOP	Huf	7PP907275F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	9
918 Spyder		2013-09	2014-12	Huf	7PP907275F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	3
918 Spyder	PO715	2014-03	EOP	Huf	7PP907275F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	171
Boxster	981	2012-01	EOP	Huf	7PP907275F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	18,667
Boxster	987	2008-11	2011-12	Huf	7PP907275F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	1,084
Cayenne	E2	2007-01	2010-12	Huf	7PP907275F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	2,165
Cayenne		2010-06	2014-05	Huf	7PP907275F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	6,525
Cayman	981	2013-03	EOP	Huf	7PP907275F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	11,583
Cayman	987	2009-02	2013-02	Huf	7PP907275F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	875

Schrader Part Number (NEW)	Car Model Code	Start of Application	End of Application	Sensor Manufacturer	OE Sensor Reference	Sensor Description	Direct TPMS Car Park in market 2017
<b>Panamera</b>	970	2009-09	2013-12	Huf	7PP907275F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	3,934
<b>Volkswagen</b>							
Phaeton	VW611	2010-06	EOP	Huf	7PP907275F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	3,297
Phaeton		2007-06	2010-05	Huf	7PP907275F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	1,083
Touareg	VW516	2007-01	2010-05	Huf	7PP907275F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	2,598
Touareg	VW526	2010-01	2014-07	Huf	7PP907275F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	2,881
<b>4010</b>							
<b>Alpina</b>							
Alpina 3	E90	2009-09	2012-12	Huf	36106856227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	1
Alpina 3		2013-01	EOP	Huf	36106856227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	11
Alpina 5	F10	2010-01	2014-02	Huf	36106790054	Beru-Huf Clamp-in Separate valve G3.3 433MHz BMW	99
Alpina 6	F12	2010-12	2014-02	Huf	36106856227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	15
Alpina 7	F01	2010-09	2014-02	Huf	36106856227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	5
Alpina 7	F25	2010-09	2014-02	Huf	36106856227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	14
<b>BMW</b>							
1-Series	E88/E82	2009-09	2011-07	Huf	36106856227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	433
3-Series	E90	2014-03	EOP	Huf	36106856227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	35
3-Series	E90/E91/E92/E93	2009-09	2014-02	Huf	36106856227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	43
5-Series	F10	2010-09	2014-02	Huf	36106790054	Beru-Huf Clamp-in Separate valve G3.3 433MHz BMW	22,254
5-Series GT	F07	2010-09	2014-02	Huf	36106790054	Beru-Huf Clamp-in Separate valve G3.3 433MHz BMW	350
6-Series	F12	2011-03	2014-02	Huf	36106856227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	230
6-Series Gran Coupe	F06	2011-03	2014-02	Huf	36106856227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	216
7-Series	F01	2014-06	EOP	Huf	36106856227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	40
X1	E84	2009-09	2014-02	Huf	36106856227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	3,104
X3	F25	2010-11	2014-02	Huf	36106856227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	6,897
X5	E70	2010-03	EOP	Huf	36106856227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	3,252
X6	E71	2011-12	EOP	Huf	36106856227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	3
Z4	E89	2010-09	2014-02	Huf	36106856227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	364
<b>Mini</b>							
Clubman	R55	2009-08	EOP	Huf	36106856227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	43
Clubvan	R55	2012-07	2015-06	Huf	36106856227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	5
Countryman	R60	2010-08	2014-06	Huf	36106856227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	18,709
Coupe	R58	2011-07	2014-06	Huf	36106856227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	166
Paceman	R61	2012-11	2014-06	Huf	36106856227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	3,059
Roadster	R59	2011-12	2014-06	Huf	36106856227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	285
<b>Rolls-Royce</b>							
Dawn	RR06	2016-01	EOP	Huf	36106856227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	597
Ghost	RR04	2010-09	EOP	Huf	36106856227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	517
Phantom	RR01	2012-01	EOP	Huf	36106856227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	58
Phantom Coupe	RR02	2014-06	EOP	Huf	36106856227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	39
Wraith	RR05	2014-03	EOP	Huf	36106856227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	803
<b>4011</b>							
<b>Volkswagen</b>							
CC	VW464	2014-06	EOP	Huf	3AA907275B	Beru-Huf Clamp-in Separate valve G3.42 433MHz VW	29
Passat	VW471	2010-08	2014-07	Huf	3AA907275D	Beru-Huf Clamp-in Separate valve G3.3 433MHz VW	6,987
Passat CC	VW464	2014-09	EOP	Huf	3AA907275B	Beru-Huf Clamp-in Separate valve G3.42 433MHz VW	6,110
Passat CC		2008-05	EOP	Huf	3AA907275D	Beru-Huf Clamp-in Separate valve G3.3 433MHz VW	5,389
Tiguan	VW316	2011-05	2014-07	Huf	3AA907275D	Beru-Huf Clamp-in Separate valve G3.3 433MHz VW	80,393
Tiguan	VW326	2014-08	2016-08	Huf	3AA907275D	Beru-Huf Clamp-in Separate valve G3.3 433MHz VW	87,853
Touran	VW378	2015-01	EOP	Huf	3AA907275B	Beru-Huf Clamp-in Separate valve G3.42 433MHz VW	69,624
Touran (LCV)	VW368	2010-07	EOP	Huf	3AA907275D	Beru-Huf Clamp-in Separate valve G3.3 433MHz VW	1
<b>4012</b>							
<b>Audi</b>							
A3 Sportback	AU370	2012-06	EOP	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	78,453
A4	AU481	2015-01	EOP	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	4,833
A4	AU491	2014-10	2021-10	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	15,966
A4 Allroad	AU486	2009-03	2015-12	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	4
A4 Allroad	AU492/4	2016-04	EOP	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	50
A4 Allroad	AU496	2016-01	2022-12	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	10
A5	AU484	2006-12	2015-06	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	1,135
A5	AU494	2015-07	2021-12	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	4,628
A5 Cabrio	AU485	2008-11	EOP	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	17,894
A5 Cabrio	AU495	2016-01	2022-12	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	1,815
A5 Sportback	AU483	2009-07	EOP	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	12,388
A5 Sportback	AU493	2016-10	EOP	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	6,525
A7	AU573	2010-09	EOP	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	5,344
A8	AU651	2017-01	EOP	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	1,716
C-MPV	AU378	2016-04	EOP	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	28
Q1	AU276	2016-01	EOP	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	56
Q2	AU276	2016-01	EOP	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	77,850
Q3	AU316	2011-07	2018-03	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	59,226
Q4	AU319	2016-08	EOP	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	55
Q5	AU416	2008-09	EOP	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	33,685

Schrader Part Number (NEW)	Car Model Code	Start of Application	End of Application	Sensor Manufacturer	OE Sensor Reference	Sensor Description	Direct TPMS Car Park in market 2017
Q5	AU426	2016-01	2022-12	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	10,840
Q7	AU716	2014-06	EOP	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	2,831
R8	AU624	2015-01	EOP	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	3,817
TT	AU334	2014-02	EOP	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	17
<b>Porsche</b>							
911	991	2015-09	EOP	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	72
918 Spyder	PO815	2014-03	EOP	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	14
Cayenne	E2	2014-05	EOP	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	91
Cayenne	PO536	2017-01	2024-08	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	1,318
Cayenne	PO526	2014-03	EOP	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	50,336
Cayman	981_PO444	2017-01	EOP	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	3
Macan	PO416	2013-11	EOP	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	73,083
Panamera	970	2014-01	EOP	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	45
Panamera	PO620	2013-04	2022-07	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	52
Panamera	PO623	2016-01	EOP	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	7,136
Panamera	PO613	2014-03	EOP	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	7,017
<b>Skoda</b>							
Citigo	SK120	2011-10	EOP	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	11,753
Fabia	SK260	2014-03	EOP	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	45,429
Fabia Van	SK260	2014-03	EOP	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	49
Kodiaq	SK326/1	2016-01	EOP	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	4,739
Octavia	SK371	2012-11	2019-06	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	65,547
Octavia (LCV)	SK371	2012-11	EOP	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	1
Praktik	SK337	2016-01	EOP	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	3
Rapid	SK251/1	2012-09	2020-04	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	9
Rapid	SK351/3	2014-03	EOP	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	7,266
Rapid Spaceback	SK253/1	2013-10	EOP	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	9
Rapid Spaceback	SK350/3	2014-03	EOP	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	14,206
Roomster	SK337	2016-01	EOP	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	6
Roomster (LCV)	SK258	2006-04	EOP	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	1
Superb	SK461	2008-03	EOP	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	453
Superb	SK481	2014-11	EOP	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	18,849
Yeti	SK316	2009-06	EOP	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	19,469
Yeti (LCV)	SK316	2009-06	EOP	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	1
<b>Volkswagen</b>							
Amarok	VN817	2009-11	2018-02	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	16,615
Arteon	VW276	2017-01	EOP	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	1,784
CC	VW484	2015-07	2022-06	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	8
CC	VW483	2017-01	EOP	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	3,624
Crafter Combi	VN830	2014-06	2018-02	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	1,103
Cross Blue	VW416	2016-04	EOP	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	1
Eos	VW465	2006-02	EOP	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	626
Golf	VW360	2014-05	EOP	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	4,807
Golf	VW362	2009-09	EOP	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	3
Golf	VW370	2012-08	2018-06	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	460,084
Golf Plus	VW369	2008-09	2014-01	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	13
Golf Plus	VW379	2014-02	2019-01	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	27
Golf Sportsvan	VW379	2014-03	EOP	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	62,355
Golf SV	VW379	2014-03	EOP	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	2,237
Jetta	VW361	2010-07	EOP	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	8,456
New Beetle	VW324	2011-08	EOP	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	9,680
New Beetle Convertible	VW325	2012-09	EOP	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	12,987
Passat	VW471	2014-08	EOP	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	3
Passat	VW481	2014-07	EOP	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	172,127
Polo	VW270	2016-10	EOP	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	18,615
Scirocco	VW364	2008-06	EOP	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	10,171
Sharan	VW428	2010-06	EOP	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	36,528
Tiguan	VW376	2016-09	EOP	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	56
Touareg	VW526	2017-10	EOP	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	3,129
Touareg		2014-08	2017-09	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	15,448
Touareg	VW536	2017-07	2024-06	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	1,043
Touran	VW368	2010-07	2014-12	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	899
Transporter	VN750	2003-03	2018-02	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	1
Transporter Shuttle	VN750	2014-06	2018-02	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	254
Up!	VW120	2011-08	EOP	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	64,451
XL1	VW019	2013-08	EOP	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	1
XL1	VW114	2014-03	EOP	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	13
<b>4015</b>							
<b>Lancia</b>							
Flavia	JS27	2010-10	EOP	Conti	68078768AA	Conti Clamp-in TG1C 433MHz Chrysler	654

Schrader Part Number (NEW)	Car Model Code	Start of Application	End of Application	Sensor Manufacturer	OE Sensor Reference	Sensor Description	Direct TPMS Car Park in market 2017
<b>4016</b>							
<b>Alfa Romeo</b>							
169	N936	2015-11	EOP	Conti	68105280AF	Conti Snap-in TG1D 433MHz Chrysler	58
Giulia	952	2016-05	EOP	Conti	68105280AF	Conti Snap-in TG1D 433MHz Chrysler	34,477
<b>Chrysler</b>							
Grand Voyager	RU	2016-01	EOP	Conti	68105280AF	Conti Snap-in TG1D 433MHz Chrysler	2
<b>Jeep</b>							
C-CUV	MP	2016-01	EOP	Conti	68105280AF	Conti Snap-in TG1D 433MHz Chrysler	24
Renegade	520	2014-03	2019-12	Conti	68105280AF	Conti Snap-in TG1D 433MHz Chrysler	191,456
<b>Lancia</b>							
Flavia	UF	2014-02	EOP	Conti	68105280AF	Conti Snap-in TG1D 433MHz Chrysler	8
Voyager	RA	2015-11	EOP	Conti	68105280AF	Conti Snap-in TG1D 433MHz Chrysler	17
Voyager	RU	2015-11	EOP	Conti	68105280AF	Conti Snap-in TG1D 433MHz Chrysler	16
<b>4019</b>							
<b>Jaguar</b>							
F-Type	X152	2012-10	EOP	Conti	C2D21599	Conti Clamp-in TG1C 433MHz Ford	15,223
XJ	X351	2014-03	EOP	Conti	C2D21599	Conti Clamp-in TG1C 433MHz Ford	5,139
XK	X150	2014-03	EOP	Conti	C2D21599	Conti Clamp-in TG1C 433MHz Ford	7
<b>Land Rover</b>							
Defender	L316	2014-06	EOP	Conti	LR021935	Conti Clamp-in TG1C 433MHz Ford	26,053
Defender (LCV)	L316	2014-06	EOP	Conti	LR021935	Conti Clamp-in TG1C 433MHz Ford	37
Discovery	L319	2009-09	EOP	Conti	LR021935	Conti Clamp-in TG1C 433MHz Ford	37,230
Discovery Sport	L550	2014-01	EOP	Conti	LR021935	Conti Clamp-in TG1C 433MHz Ford	115,613
Freelander	L359	2014-03	EOP	Conti	LR021935	Conti Clamp-in TG1C 433MHz Ford	8,415
Freelander	L550	2006-10	EOP	Conti	LR021935	Conti Clamp-in TG1C 433MHz Ford	93
Range Rover	L405	2010-01	EOP	Conti	LR021935	Conti Clamp-in TG1C 433MHz Ford	45,495
Range Rover Evoque	L538	2012-01	EOP	Conti	LR021935	Conti Clamp-in TG1C 433MHz Ford	200,212
Range Rover Sport	L494	2014-03	EOP	Conti	FW931A159AB	Conti Clamp-in TG1C 433MHz Conti Volvo	88,969
<b>4021</b>							
<b>Ford</b>							
S-MAX	CD340	2006-02	EOP	Conti	8G921A159-AE	Conti Clamp-in TG1C 433MHz Ford	4,771
<b>4023</b>							
<b>Jaguar</b>							
XF	X250	2007-11	EOP	Conti	LR032835	Conti Clamp-in TG1B 433MHz Ford	25,116
XJ	X350	2003-05	2009-09	Conti	LR032835	Conti Clamp-in TG1B 433MHz Ford	1,299
XK	X150	2006-01	2014-02	Conti	LR032835	Conti Clamp-in TG1B 433MHz Ford	430
X-Type	X400	2007-01	EOP	Conti	LR032835	Conti Clamp-in TG1B 433MHz Ford	866
<b>Land Rover</b>							
Discovery (LCV)	L319	2004-07	2009-09	Conti	RQH500470	Conti Clamp-in TG1B 433MHz Ford	58
Range Rover	L322	2005-01	2009-12	Conti	RQH500470	Conti Clamp-in TG1B 433MHz Ford	1
<b>Volvo</b>							
C30	Y279	2006-09	2012-12	Conti	30681555	Conti Clamp-in TG1B 433MHz Ford	108
C70	Y281	2006-03	EOP	Conti	30681555	Conti Clamp-in TG1B 433MHz Ford	7
S40	Y276	2004-01	EOP	Conti	30681555	Conti Clamp-in TG1B 433MHz Ford	1
V50	Y280	2003-11	2012-05	Conti	30681555	Conti Clamp-in TG1B 433MHz Ford	173
V50		2012-06	EOP	Conti	30681555	Conti Clamp-in TG1B 433MHz Ford	4
V70	Y285	2006-03	2008-10	Conti	30681555	Conti Clamp-in TG1B 433MHz Ford	217
V70		2008-01	2010-08	Conti	30681555	Conti Clamp-in TG1B 433MHz Ford	217
<b>4026</b>							
<b>Hyundai</b>							
i10	IA,PA	2007-10	EOP	Conti	52933-2L600	Conti Clamp-in TG1B 433MHz HKMC	7,258
i10	PA	2007-10	2013-10	Conti	52933-2L600	Conti Clamp-in TG1B 433MHz HKMC	17
i30	FD	2007-10	2011-10	Conti	52933-2L600	Conti Clamp-in TG1B 433MHz HKMC	2,217
<b>Kia</b>							
Cee'd	ED	2006-01	2012-02	Conti	52933-2L600	Conti Clamp-in TG1B 433MHz HKMC	22
<b>4027</b>							
<b>Hyundai</b>							
i20	PB	2008-08	2014-06	Conti	52933-1J000	Conti Clamp-in TG1C 433MHz HKMC	218
ix20	JC(1)	2010-09	2013-09	Conti	52933-1J000	Conti Clamp-in TG1C 433MHz HKMC	88
Sub-Compact SUV	IB	2015-05	EOP	Conti	52933-1J000	Conti Clamp-in TG1C 433MHz HKMC	76
<b>Kia</b>							
Optima	TF	2011-09	2013-08	Conti	52933-1J000	Conti Clamp-in TG1C 433MHz HKMC	27
Sorento	XM	2009-05	2012-09	Conti	52933-1J000	Conti Clamp-in TG1C 433MHz HKMC	40
Soul	AM	2008-10	EOP	Conti	52933-1J000	Conti Clamp-in TG1C 433MHz HKMC	1
<b>4028</b>							
<b>Alfa Romeo</b>							
Spider	J12A	2015-04	EOP	Conti	BHB637140	Conti Clamp-in TG1C 433MHz Mazda	56
<b>Fiat</b>							
124	J12F	2016-01	EOP	Conti	BHB637140	Conti Clamp-in TG1C 433MHz Mazda	10,493
<b>Mazda</b>							
2	J03	2014-05	EOP	Conti	BHB637140	Conti Clamp-in TG1C 433MHz Mazda	27,948
2	J03W	2014-01	EOP	Conti	BHB637140	Conti Clamp-in TG1C 433MHz Mazda	64,181

Schrader Part Number (NEW)	Car Model Code	Start of Application	End of Application	Sensor Manufacturer	OE Sensor Reference	Sensor Description	Direct TPMS Car Park in market 2017
3	J68C	2009-06	2013-03	Conti	GS1D37140	Conti Clamp-in TG1C 433MHz Mazda	991
5	J74G	2010-07	EOP	Conti	BHB637140	Conti Clamp-in TG1C 433MHz Mazda	9,027
6	J61A	2012-09	2014-02	Conti	BHB637140	Conti Clamp-in TG1C 433MHz Mazda	1
6		2007-08	2012-08	Conti	GS1D37140	Conti Clamp-in TG1C 433MHz Mazda	173
CX-7	J31H	2009-06	EOP	Conti	GS1D37140	Conti Clamp-in TG1C 433MHz Mazda	81
CX-9	J50C	2010-08	2015-12	Conti	BHB637140	Conti Clamp-in TG1C 433MHz Mazda	879
MX-5	J12A	2015-01	2019-12	Conti	BHB637140	Conti Clamp-in TG1C 433MHz Mazda	21,757
MX-5	J04C(2)	2014-03	2014-12	Conti	BHB637140	Conti Clamp-in TG1C 433MHz Mazda	18
Premacy	J54L	2014-03	EOP	Conti	BHB637140	Conti Clamp-in TG1C 433MHz Mazda	3
<b>4031</b>							
<b>Citroen</b>							
C4	B5	2004-11	2008-06	Conti	5430T4	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	2,165
C5	X3/X40	2004-08	2007-12	Conti	5430T4	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	67,981
C5	X7	2008-01	2013-09	Conti	5430T4	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	43,740
C6	X6	2005-09	2012-12	Conti	5430T4	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	1,083
C8	V3	2014-07	EOP	Conti	5430T4	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	12
C8		2005-09	2014-06	Conti	5430T4	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	8,668
<b>Fiat</b>							
Ulysse	V1	2005-11	2010-10	Conti	9673198580/9681102280	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	650
<b>Lancia</b>							
Phedra	(blank)	2001-01	2010-10	Conti	9673198580/9681102280	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	650
Voyager	RT	2013-08	EOP	Conti	9673198580/9681102280	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	3,660
<b>Peugeot</b>							
1007	PF1	2005-01	EOP	Conti	5430T4	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	866
1007	A08	2014-03	EOP	Conti	5430T4	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	1
207	A7	2005-11	2013-09	Conti	5430T4	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	2,165
307	T5	2006-11	2006-12	Conti	5430T4	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	61,053
407	D2	2004-01	2006-02	Conti	5430T4	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	173,200
508	W2	2010-11	2013-09	Conti	5430T4	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	30,323
607	Z8	2004-10	2009-03	Conti	5430T4	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	7,361
807	V2	2004-10	EOP	Conti	5430T4	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	13,459
<b>4032</b>							
<b>Lada</b>							
Granta	2190	2015-04	2016-06	Conti	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	930
<b>Nissan</b>							
Atleon	F91A	2014-06	EOP	Conti	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	4
Atleon	F91B	2014-03	EOP	Conti	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	24
Atleon	F91G	2014-01	EOP	Conti	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	28
Cabstar	F91A	2014-06	EOP	Conti	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	15,033
Cabstar	F91A(2)	2017-01	EOP	Conti	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	5,778
Cabstar E	F91A	2014-06	EOP	Conti	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	3,895
C-Hatch	B12L	2014-10	EOP	Conti	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	97
Cube	X12B	2014-10	EOP	Conti	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	1
Evalia	X11M	2014-03	EOP	Conti	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	489
Frontier	H60A	2014-09	2023-03	Conti	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	3
GT-R	D52E	2016-01	EOP	Conti	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	1,017
Note	J02C	2013-08	EOP	Conti	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	140,759
Note	L11E	2014-03	EOP	Conti	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	13
NP300	D22	2014-03	EOP	Conti	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	168
NP300	H60A	2014-09	EOP	Conti	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	131
NT500	F91G	2014-03	EOP	Conti	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	2,028
NV200	X11M	2014-04	2016-09	Conti	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	55,873
NV200 Combi	X11M	2014-04	EOP	Conti	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	17,572
NV400 Combi	X81F	2014-03	EOP	Conti	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	4
Pulsar	B12L	2014-03	2016-09	Conti	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	100,297
Qashqai	P32S	2014-03	2016-09	Conti	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	745,371
Sentra	L12F	2014-08	EOP	Conti	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	1
Tiida	B11C	2014-03	2016-09	Conti	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	1
X-Trail	P32R	2013-11	2016-09	Conti	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	137,712
<b>Renault</b>							
Alaskan	U60A	2016-01	EOP	Conti	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	5,157
Koleos	H45	2014-01	EOP	Conti	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	8,438
<b>4034</b>							
<b>Lada</b>							
Kalina	1117-1119	2014-03	EOP	Conti	407004CBOA	Conti Snap-in TG1D 433MHz Renault	420
Kalina	2192	2013-07	EOP	Conti	407004CBOA	Conti Snap-in TG1D 433MHz Renault	1,227
<b>Nissan</b>							
Micra	B02E	2016-12	EOP	Conti	407004CBOA	Conti Snap-in TG1D 433MHz Renault	83,352
<b>Renault</b>							
Espace	JFC	2015-01	EOP	Conti	407004CBOA	Conti Snap-in TG1D 433MHz Renault	70,865
Kadjar	HFE	2015-01	EOP	Conti	407004CBOA	Conti Snap-in TG1D 433MHz Renault	307,775
Kangoo	XFG	2017-10	2026-03	Conti	407004CBOA	Conti Snap-in TG1D 433MHz Renault	8
Kangoo Passenger	XFG	2017-10	EOP	Conti	407004CBOA	Conti Snap-in TG1D 433MHz Renault	3

Schrader Part Number (NEW)	Car Model Code	Start of Application	End of Application	Sensor Manufacturer	OE Sensor Reference	Sensor Description	Direct TPMS Car Park in market 2017
Laguna	LFD	2015-01	2021-09	Conti	407004CB0A	Conti Snap-in TG1D 433MHz Renault	72
Megane	BFB	2015-01	EOP	Conti	407004CB0A	Conti Snap-in TG1D 433MHz Renault	57
Megane	LFF	2016-01	EOP	Conti	407004CB0A	Conti Snap-in TG1D 433MHz Renault	8,936
Megane	BFB(2)	2015-04	2021-12	Conti	407004CB0A	Conti Snap-in TG1D 433MHz Renault	68
Scenic	JFA	2016-01	EOP	Conti	407004CB0A	Conti Snap-in TG1D 433MHz Renault	183,530
<b>4035</b>							
<b>Renault</b>							
Fluence	L38	2009-10	EOP	Conti	407000435R	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	10,783
Grand Scenic	J95	2009-01	EOP	Conti	407000435R	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	8,660
Laguna	X91	2007-10	EOP	Conti	407000435R	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	48,739
Laguna Coupe	D91	2014-07	EOP	Conti	407000435R	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	164
Laguna Coupe		2008-07	2014-06	Conti	407000435R	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	6,928
Latitude	L43	2010-09	EOP	Conti	407000435R	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	650
Megane	B32	2009-11	EOP	Conti	407000435R	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	4,330
Megane	B32_X95	2011-05	EOP	Conti	407000435R	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	582
Megane	X84	2008-12	EOP	Conti	407000435R	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	142
Megane	X95	2008-11	EOP	Conti	407000435R	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	193,490
Megane Van	BFB	2015-01	EOP	Conti	407000435R	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	12
Megane Van	X95	2014-06	EOP	Conti	407000435R	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	6,829
Scenic	J95	2015-01	EOP	Conti	407000435R	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	148,453
Scenic		2009-01	EOP	Conti	407000435R	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	234,880
Zoe	X10	2012-09	EOP	Conti	407000435R	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	69,995
<b>4036</b>							
<b>Renault</b>							
Megane	X84	2002-11	2008-11	Conti	407005578R	Conti Clamp-in TG1B Siemens VDO 433MHz Renault	43,300
Scenic	J95	2003-06	2007-10	Conti	407005578R	Conti Clamp-in TG1B Siemens VDO 433MHz Renault	51,980
<b>4037</b>							
<b>Volkswagen</b>							
New Beetle	VW314	2006-01	2010-07	Conti	1K0907253C	Conti Clamp-in TG1B Siemens VDO 433MHz VW	1,299
Passat	VW451	2005-03	2010-11	Conti	1K0907253C	Conti Clamp-in TG1B Siemens VDO 433MHz VW	15,155
<b>4038</b>							
<b>Mercedes-Benz</b>							
Sprinter (LCV)	NCV3	2006-06	2011-10	Conti	A0025409517	Conti Clamp-in MB_no RF link Siemens VDO 433MHz Daimler	4,330
Viano (LCV) (Mid-Line)	W639	2003-07	2014-06	Conti	A0025409517	Conti Clamp-in MB_no RF link Siemens VDO 433MHz Daimler	2,165
Vito Combi	W639	2014-03	EOP	Conti	A0025409517	Conti Clamp-in MB_no RF link Siemens VDO 433MHz Daimler	3
<b>Volkswagen</b>							
Crafter	VN830	2006-04	2014-01	Conti	2E0907508F / 2E0907508J	Conti Clamp-in MB_no RF link Siemens VDO 433MHz VW	27,546
<b>4040</b>							
<b>Mercedes-Benz</b>							
CL	C216	2006-07	2014-03	Conti	A0025406717	Conti Clamp-in MB_no RF link Siemens VDO 433MHz Daimler	78
CLS	C219	2005-01	2009-07	Conti	A0025406717	Conti Clamp-in MB_no RF link Siemens VDO 433MHz Daimler	260
GL-Class	X164	2006-09	2009-07	Conti	A0025406717	Conti Clamp-in MB_no RF link Siemens VDO 433MHz Daimler	43
R-Class	V251	2005-06	2009-07	Conti	A0025406717	Conti Clamp-in MB_no RF link Siemens VDO 433MHz Daimler	325
S-Class	W221	2005-10	2009-06	Conti	A0025406717	Conti Clamp-in MB_no RF link Siemens VDO 433MHz Daimler	2,165
SL	R230	2005-01	2009-07	Conti	A0025406717	Conti Clamp-in MB_no RF link Siemens VDO 433MHz Daimler	866
<b>4043</b>							
<b>Alpina</b>							
Alpina 3	F30	2012-03	EOP	Conti	6855539	Conti Clamp-in TG1C 433MHz BMW	891
Alpina 3	F32	2013-04	EOP	Conti	6855539	Conti Clamp-in TG1C 433MHz BMW	8
Alpina 4	F32	2014-03	EOP	Conti	6855539	Conti Clamp-in TG1C 433MHz BMW	435
<b>BMW</b>							
1-Series	E80	2014-06	2016-12	Conti	6855539	Conti Clamp-in TG1C 433MHz BMW	2
1-Series	F20	2011-07	2016-12	Conti	6855539	Conti Clamp-in TG1C 433MHz BMW	268,851
2-Series	F22	2013-11	2016-12	Conti	6855539	Conti Clamp-in TG1C 433MHz BMW	62,948
2-Series Active Tourer	F45	2014-07	2016-12	Conti	6855539	Conti Clamp-in TG1C 433MHz BMW	181,605
2-Series Gran Tourer	F46	2015-01	2016-12	Conti	6855539	Conti Clamp-in TG1C 433MHz BMW	94,087
3-Series	F30	2012-03	2016-12	Conti	6855539	Conti Clamp-in TG1C 433MHz BMW	257,891
3-Series GT	F34	2013-03	2016-12	Conti	6855539	Conti Clamp-in TG1C 433MHz BMW	40,982
4-Series	F32	2013-10	2016-12	Conti	6855539	Conti Clamp-in TG1C 433MHz BMW	89,909
4-Series	F82	2013-10	2016-12	Conti	6855539	Conti Clamp-in TG1C 433MHz BMW	433
4-Series Gran Coupe	F36	2014-07	2016-12	Conti	6855539	Conti Clamp-in TG1C 433MHz BMW	69,041
i3	I01	2013-08	2016-12	Conti	6855539	Conti Clamp-in TG1C 433MHz BMW	29,279
i8	I12	2014-01	2016-12	Conti	6855539	Conti Clamp-in TG1C 433MHz BMW	5,855
X5	F15	2013-05	2016-12	Conti	6855539	Conti Clamp-in TG1C 433MHz BMW	128,297
X6	F16	2014-08	2016-12	Conti	6855539	Conti Clamp-in TG1C 433MHz BMW	35,072
<b>Mini</b>							
Clubman	F54	2015-07	2016-12	Conti	6855539	Conti Clamp-in TG1C 433MHz BMW	34,423
Clubman	F55	2013-11	2016-12	Conti	6855539	Conti Clamp-in TG1C 433MHz BMW	650
Clubman / Cooper	F55	2013-11	2016-12	Conti	6855539	Conti Clamp-in TG1C 433MHz BMW	650
Clubvan	F54	2015-07	2016-12	Conti	6855539	Conti Clamp-in TG1C 433MHz BMW	25
Cooper	F55	2013-11	2015-05	Conti	6855539	Conti Clamp-in TG1C 433MHz BMW	650
Cooper		2015-06	2016-12	Conti	6855539	Conti Clamp-in TG1C 433MHz BMW	650

Schrader Part Number (NEW)	Car Model Code	Start of Application	End of Application	Sensor Manufacturer	OE Sensor Reference	Sensor Description	Direct TPMS Car Park in market 2017
Cooper	F57	2015-11	2016-12	Conti	6855539	Conti Clamp-in TG1C 433MHz BMW	65
Countryman	F60	2016-01	EOP	Conti	6855539	Conti Clamp-in TG1C 433MHz BMW	59,200
Mini	F56	2013-12	2016-12	Conti	6855539	Conti Clamp-in TG1C 433MHz BMW	286,416
Mini	R56	2014-06	2015-05	Conti	6855539	Conti Clamp-in TG1C 433MHz BMW	34
<b>4045</b>							
<b>Aston Martin</b>							
Cygnnet	630L	2014-06	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1
<b>Lexus</b>							
CT	080A	2014-06	EOP	Pacific	42607-30070	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	29,310
GS	920L	2014-06	EOP	Pacific	42607-30070	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	5,106
IS	030L	2014-06	EOP	Pacific	42607-30070	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	2
IS	400A	2013-07	EOP	Pacific	42607-30070	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	24,740
IS	720A	2015-02	EOP	Pacific	42607-30070	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	49
LF-A	973L	2014-06	EOP	Pacific	42607-30070	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1
LS	250L	2014-01	EOP	Pacific	42607-30070	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	427
LS	200B	2017-01	EOP	Pacific	42607-30070	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	4
NX	600A	2014-03	EOP	Pacific	42607-30070	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	46,253
RC	720A	2014-01	EOP	Pacific	42607-30070	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	2,857
RX	640L	2014-06	2016-09	Pacific	42607-30070	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	5,061
<b>Scion</b>							
iC	745L	2015-01	EOP	Pacific	42607-30070	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1
<b>Subaru</b>							
BRZ	E88	2014-01	EOP	Pacific	SU003 05268	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota/Subaru	1,541
<b>Toyota</b>							
Auris	130A	2014-06	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	398,884
Auris	130L	2014-06	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	2
Avensis	445L	2014-06	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	102,372
Camry	045L	2014-03	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1
Corolla	079L,140N,340N	2013-08	EOP	Pacific	42607-42020	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	4
Corolla	140A	2014-01	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	4
Corolla	150A	2014-10	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	10,627
Corolla	252L	2014-03	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	2
Corolla	366A	2013-09	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	56
Corolla	150L,252L	2014-03	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1,282
Corolla	466A	2014-03	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	26,799
Corolla Verso	681N	2014-06	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1
Dyna	Dutro(2)	2014-06	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	4
Dyna	U300-500	2014-06	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	3
Dyna	U600/C600	2014-06	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1
Dyna	131N	2014-03	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1,532
FJ Cruiser	155L	2014-06	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	4
Fortuner	669L	2014-03	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	2
GT 86	E88	2014-06	EOP	Pacific	SU003 05268	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota/Subaru	5,129
Hiace	550N	2014-06	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1
Highlander	397L	2014-03	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1
Hilux	640A	2015-10	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	37,420
Hilux	669L	2014-06	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	38,341
IQ	630L	2014-06	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	461
IQ	630X	2016-07	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	52
Land Cruiser	215L	2014-06	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	10,096
Land Cruiser	611L	2014-06	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	16,376
Land Cruiser (LCV)	215L	2014-06	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	18
Land Cruiser Prado	611L	2014-06	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	536
Land Cruiser V8	215L	2014-06	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1,784
Mirai	470A	2015-01	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	238
Previa	085X	2015-10	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	7
Previa	085L	2014-03	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	2
Prius	277N	2014-06	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1
Prius	590L	2014-06	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	10,769
Prius	690A	2015-01	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	39,102
Prius Plus	030A	2014-06	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	21,401
RAV4	120L	2014-03	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1
RAV4	410A	2013-01	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	198,912
Sequoia	200L	2015-01	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1
Sienna	500N	2014-06	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1
Sienna	580L	2014-06	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	519
Sienta	433L	2014-03	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1
Tundra	180L	2014-06	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	3
Tundra	480A/180L	2014-03	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	101
Urban Cruiser	260L	2014-06	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	5
Verso	151L,595L	2014-06	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	4
Verso	595L	2014-06	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	95,500
Verso-S	770L	2014-06	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	6,554

Schrader Part Number (NEW)	Car Model Code	Start of Application	End of Application	Sensor Manufacturer	OE Sensor Reference	Sensor Description	Direct TPMS Car Park in market 2017
Yaris	020L	2014-03	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	7
Yaris	850L	2014-06	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	598,205
Yaris (LCV)	850L	2014-06	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	11
<b>4047</b>							
<b>Infiniti</b>							
FX	P53C	2014-09	2020-09	Pacific	40700-6WY0A	Pacific Clamp-in Fixed Angle ver 1 433MHz Nissan	13
G	L53A	2013-04	2019-01	Pacific	40700-6WY0A	Pacific Clamp-in Fixed Angle ver 1 433MHz Nissan	1
Q60	L53A	2013-11	EOP	Pacific	40700-6WY0A	Pacific Clamp-in Fixed Angle ver 1 433MHz Nissan	67
Q70	L53E	2013-11	EOP	Pacific	40700-6WY0A	Pacific Clamp-in Fixed Angle ver 1 433MHz Nissan	1,279
QX40	PD2A	2017-04	EOP	Pacific	40700-6WY0A	Pacific Clamp-in Fixed Angle ver 1 433MHz Nissan	23
QX50	P53B	2014-06	EOP	Pacific	40700-6WY0A	Pacific Clamp-in Fixed Angle ver 1 433MHz Nissan	467
QX70	P53C	2013-08	EOP	Pacific	40700-6WY0A	Pacific Clamp-in Fixed Angle ver 1 433MHz Nissan	4,821
<b>Nissan</b>							
370Z	C53D(2)	2014-07	2016-03	Pacific	40700-6WY0A	Pacific Clamp-in Fixed Angle ver 1 433MHz Nissan	43
370Z	RC53D(2)	2016-04	EOP	Pacific	40700-6WY0A	Pacific Clamp-in Fixed Angle ver 1 433MHz Nissan	43
GT-R	D52E	2014-07	2015-12	Pacific	40700-6WY0A	Pacific Clamp-in Fixed Angle ver 1 433MHz Nissan	2,805
Juke	P12C	2010-05	2015-09	Pacific	40700-6WY0A	Pacific Clamp-in Fixed Angle ver 1 433MHz Nissan	130,052
Leaf	B12G	2010-10	2015-09	Pacific	40700-6WY0A	Pacific Clamp-in Fixed Angle ver 1 433MHz Nissan	54,744
Murano	P42M	2015-06	EOP	Pacific	40700-6WY0A	Pacific Clamp-in Fixed Angle ver 1 433MHz Nissan	1,021
<b>4052</b>							
<b>Genesis</b>							
G90	HI	2016-01	EOP	TRW	52933-3M000	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	14
<b>Hyundai</b>							
iX35	LM	2010-09	2014-02	TRW	52933-3M000	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	10,936
<b>4053</b>							
<b>Hyundai</b>							
C-Green	AE	2016-01	EOP	TRW	52933-3X300	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	24
Elantra	HD	2014-03	EOP	TRW	52933-3X300	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	33
Elantra	MD	2014-03	EOP	TRW	52933-3X300	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	56
<b>Kia</b>							
Rio	UB	2012-03	EOP	TRW	52933-3X300	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	158,299
<b>4054</b>							
<b>Alfa Romeo</b>							
159	939	2005-07	EOP	TRW	51839114	TRW Clamp-in Variable Angle ver 2 433MHz Fiat	243
Brera	946	2005-11	2010-12	TRW	51839114	TRW Clamp-in Variable Angle ver 2 433MHz Fiat	22
MiTo	955	2008-06	2013-07	TRW	51839114	TRW Clamp-in Variable Angle ver 2 433MHz Fiat	472
Spider	946	2006-06	2010-12	TRW	51839114	TRW Clamp-in Variable Angle ver 2 433MHz Fiat	22
Spider	946(2)	2011-01	EOP	TRW	51839114	TRW Clamp-in Variable Angle ver 2 433MHz Fiat	1
<b>Chrysler</b>							
Delta	844	2013-02	EOP	TRW	51839114	TRW Clamp-in Variable Angle ver 2 433MHz Fiat	1
<b>Fiat</b>							
Bravo	198	2007-01	EOP	TRW	51839114	TRW Clamp-in Variable Angle ver 2 433MHz Fiat	674
Punto	199	2005-09	EOP	TRW	51839114	TRW Clamp-in Variable Angle ver 2 433MHz Fiat	228,150
<b>Lancia</b>							
Delta	844	2008-04	EOP	TRW	51839114	TRW Clamp-in Variable Angle ver 2 433MHz Fiat	2,821
<b>4056</b>							
<b>Kia</b>							
Rio	QB(1)	2000-01	EOP	Lear	52933-3J000	Lear Clamp-in Variable Angle ver 1 433MHz HKMC	4
<b>4057</b>							
<b>Hyundai</b>							
Santa Fe	CM	2005-12	EOP	Lear	52933-2B000	Lear Snap-in Fixed Angle ver 1 433MHz HKMC	160
<b>4058</b>							
<b>Tesla</b>							
Model S	Model S	2013-05	2014-08	Baolong	FS1511	Baolong Clamp-in Variable angle detachable valve 433MHz Tesla	4,393
<b>4059</b>							
<b>Hyundai</b>							
Genesis	DH	2014-03	EOP	Conti	52933-3N100	Conti Clamp-in TG1C 433MHz HKMC	524
Genesis Coupe	BK	2014-03	EOP	Conti	52933-3N100	Conti Clamp-in TG1C 433MHz HKMC	23
Genesis Coupe	VK	2015-11	EOP	Conti	52933-3N100	Conti Clamp-in TG1C 433MHz HKMC	17
Genesis Coupe	IK	2017-01	EOP	Conti	52933-3N100	Conti Clamp-in TG1C 433MHz HKMC	1
i30	GD	2011-11	2016-07	Conti	52933-3N100	Conti Clamp-in TG1C 433MHz HKMC	205,342
ix55	EN	2014-03	EOP	Conti	52933-3N100	Conti Clamp-in TG1C 433MHz HKMC	4
Santa Fe	DM	2012-04	EOP	Conti	52933-3N100	Conti Clamp-in TG1C 433MHz HKMC	46,578
<b>Kia</b>							
Carens	RP	2012-12	EOP	Conti	52933-3N100	Conti Clamp-in TG1C 433MHz HKMC	68,316
Carens	UN	2014-03	EOP	Conti	52933-3N100	Conti Clamp-in TG1C 433MHz HKMC	2,292
Cee'd	JD	2012-03	EOP	Conti	52933-3N100	Conti Clamp-in TG1C 433MHz HKMC	33,320
New Carens	RP	2013-06	EOP	Conti	52933-3N100	Conti Clamp-in TG1C 433MHz HKMC	9
Picanto	TA	2014-04	EOP	Conti	52933-3N100	Conti Clamp-in TG1C 433MHz HKMC	138,189
Venga	YN	2014-03	EOP	Conti	52933-3N100	Conti Clamp-in TG1C 433MHz HKMC	90,683



Schrader Part Number (NEW)	Car Model Code	Start of Application	End of Application	Sensor Manufacturer	OE Sensor Reference	Sensor Description	Direct TPMS Car Park in market 2017
<b>4060</b>							
<b>Hyundai</b>							
Equus	HI	2016-03	EOP	Conti	52933-2M650	Conti Clamp-in TG1C 433MHz HKMC	2
H100	HR	2014-03	EOP	Conti	52933-A5100	Conti Clamp-in TG1C 433MHz HKMC	5
H100 Van	AU	2014-01	EOP	Conti	52933-A5100	Conti Clamp-in TG1C 433MHz HKMC	246
H100 Van	HR	2014-03	EOP	Conti	52933-A5100	Conti Clamp-in TG1C 433MHz HKMC	180
H100 Van	LU	2017-01	EOP	Conti	52933-A5100	Conti Clamp-in TG1C 433MHz HKMC	347
ix20	JC	2013-05	EOP	Conti	52933-2M650	Conti Clamp-in TG1C 433MHz HKMC	120,598
ix25	OS	2017-01	EOP	Conti	52933-2M650	Conti Clamp-in TG1C 433MHz HKMC	14,929
<b>Kia</b>							
Camival	VQ	2014-03	EOP	Conti	52933-2M650	Conti Clamp-in TG1C 433MHz HKMC	1
Grand Carnival	YP	2014-09	EOP	Conti	52933-2M650	Conti Clamp-in TG1C 433MHz HKMC	12
Optima	TF	2013-08	2015-06	Conti	52933-2M650	Conti Clamp-in TG1C 433MHz HKMC	337
Sorento	UM	2014-01	EOP	Conti	52933-2M650	Conti Clamp-in TG1C 433MHz HKMC	42,864
Sorento	XM	2012-07	EOP	Conti	52933-2M650	Conti Clamp-in TG1C 433MHz HKMC	475
<b>4061</b>							
<b>Hyundai</b>							
i40	VF	2011-04	2014-03	TRW	52933-3V100	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	1,767
<b>4062</b>							
<b>Hyundai</b>							
iX35	LM	2014-03	EOP	TRW	52933-2S400	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	120,371
<b>Kia</b>							
Sportage	SL	2010-01	EOP	TRW	52933-2S410	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	167,922
<b>4065</b>							
<b>Fiat</b>							
Sedici	YY2	2014-06	EOP	Conti	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	813
<b>Opel</b>							
Agila	H0310	2014-06	EOP	Conti	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	4,243
<b>Suzuki</b>							
Alto	YC5	2014-06	EOP	Conti	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	1,710
Baleno	YR	2015-01	EOP	Conti	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	51,682
B-Cross	YJ	2016-01	EOP	Conti	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	56
B-Hatch	YRA	2015-01	EOP	Conti	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	58
Carry Van	YV7	2015-04	EOP	Conti	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	8
Celerio	YLA	2014-03	EOP	Conti	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	71,734
Grand Vitara	YT4	2014-06	EOP	Conti	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	3,120
Ignis	YJ	2016-01	EOP	Conti	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	47,028
Jimny	YR6,YR7	2014-06	EOP	Conti	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	5,177
Jimny	YR7	2014-06	EOP	Conti	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	34,156
Splash	YV1	2014-06	EOP	Conti	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	3,947
Splash	YV1,YV4	2014-06	EOP	Conti	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	2
Splash	YV4	2013-09	EOP	Conti	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	2
Splash	YV5	2015-05	EOP	Conti	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	64
Swift	YP6	2014-04	EOP	Conti	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	27,552
Swift	YP6,YP7	2014-06	EOP	Conti	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	95,559
Swift	YS	2016-01	EOP	Conti	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	51,201
SX4	YY1	2013-08	EOP	Conti	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	234
SX4	YY1,YY3	2013-08	EOP	Conti	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	3,948
SX4	YY3	2014-03	EOP	Conti	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	1
SX4 S-Cross	YAA	2013-11	EOP	Conti	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	98,979
Vitara	YFA	2015-01	EOP	Conti	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	182,155
Vitara	YG4,YH4	2014-03	EOP	Conti	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	40
<b>4066</b>							
<b>Jaguar</b>							
I-PACE	X590	2017-01	EOP	Conti	GX63-1A159-AA	Conti Clamp-in TG1C 433MHz JLR	468
RD-7	X760	2015-04	EOP	Conti	GX63-1A159-AA	Conti Clamp-in TG1C 433MHz JLR	78
<b>Land Rover</b>							
Discovery	L462	2016-02	EOP	Conti	LR070840	Conti Clamp-in TG1C 433MHz JLR	19,820
Discovery (LCV)	L462	2017-02	EOP	Conti	LR070840	Conti Clamp-in TG1C 433MHz JLR	5
Range Rover	L405	2015-06	EOP	Conti	LR070840	Conti Clamp-in TG1C 433MHz JLR	31,991
Range Rover Sport	L494	2015-06	EOP	Conti	LR070840	Conti Clamp-in TG1C 433MHz JLR	63,995
<b>4068</b>							
<b>Dodge</b>							
Ram	DS	2013-07	2017-12	TRW	68239720AB	TRW Snap-in Fixed Angle ver 1 433MHz Chrysler	2,567
<b>Ram</b>							
1500	DS	2014-03	2017-12	TRW	68239720AB	TRW Snap-in Fixed Angle ver 1 433MHz Chrysler	2,088
<b>4069</b>							
<b>Alpina</b>							
Alpina 5	F10	2014-03	2017-10	Huf	36106798872	Beru-Huf Clamp-in 433MHz BMW	156
Alpina 6	F06	2014-03	2018-10	Huf	36106798872	Beru-Huf Clamp-in 433MHz BMW	3
Alpina 6	F12	2015-01	EOP	Huf	36106798872	Beru-Huf Clamp-in 433MHz BMW	63
Alpina 7	F01	2014-03	EOP	Huf	36106798872	Beru-Huf Clamp-in 433MHz BMW	1

Schrader Part Number (NEW)	Car Model Code	Start of Application	End of Application	Sensor Manufacturer	OE Sensor Reference	Sensor Description	Direct TPMS Car Park in market 2017
XD3	F25	2014-03	EOP	Huf	36106798872	Beru-Huf Clamp-in 433MHz BMW	483
<b>BMW</b>							
5-Series	F10	2014-03	2016-10	Huf	36106798872	Beru-Huf Clamp-in 433MHz BMW	136,379
5-Series GT	F07	2014-03	2017-03	Huf	36106798872	Beru-Huf Clamp-in 433MHz BMW	7,062
6-Series	F12	2014-03	2017-12	Huf	36106798872	Beru-Huf Clamp-in 433MHz BMW	6,744
6-Series Gran Coupe	F06	2014-03	2018-10	Huf	36106798872	Beru-Huf Clamp-in 433MHz BMW	10,999
X1	E84	2014-03	2015-06	Huf	36106798872	Beru-Huf Clamp-in 433MHz BMW	20,892
X3	F25	2014-03	EOP	Huf	36106798872	Beru-Huf Clamp-in 433MHz BMW	143,196
X4	F26	2014-04	2020-03	Huf	36106798872	Beru-Huf Clamp-in 433MHz BMW	66,665
Z4	E89	2014-03	EOP	Huf	36106798872	Beru-Huf Clamp-in 433MHz BMW	6,915
<b>Mini</b>							
Countryman	R60	2014-07	EOP	Huf	36106798872	Beru-Huf Clamp-in 433MHz BMW	85,351
Coupe	R58	2014-07	EOP	Huf	36106798872	Beru-Huf Clamp-in 433MHz BMW	1,458
Paceman	R61	2014-07	EOP	Huf	36106798872	Beru-Huf Clamp-in 433MHz BMW	10,198
Roadster	R59	2014-07	EOP	Huf	36106798872	Beru-Huf Clamp-in 433MHz BMW	1,121
<b>4070</b>							
<b>Volvo</b>							
V40	Y555	2014-03	EOP	Conti	31445473	Conti Clamp-in TG1C 433MHz Volvo	201,991
V40 Cross Country	Y555	2014-03	EOP	Conti	31445473	Conti Clamp-in TG1C 433MHz Volvo	46,151
V40 XC	Y555	2014-03	EOP	Conti	31445473	Conti Clamp-in TG1C 433MHz Volvo	50
V60	Y352	2010-09	2014-06	Conti	31445473	Conti Clamp-in TG1C 433MHz Volvo	6,790
V60		2014-07	2017-09	Conti	31445473	Conti Clamp-in TG1C 433MHz Volvo	86,821
V60 Cross Country	Y352	2015-01	EOP	Conti	31445473	Conti Clamp-in TG1C 433MHz Volvo	22,088
V70	Y285	2014-07	EOP	Conti	31445473	Conti Clamp-in TG1C 433MHz Volvo	38,967
V70		2008-09	2014-06	Conti	31445473	Conti Clamp-in TG1C 433MHz Volvo	4,434
XC60	Y413	2014-07	2016-10	Conti	31445473	Conti Clamp-in TG1C 433MHz Volvo	144,283
XC60		2008-05	2014-06	Conti	31445473	Conti Clamp-in TG1C 433MHz Volvo	23,178
XC70	Y381	2014-07	EOP	Conti	31445473	Conti Clamp-in TG1C 433MHz Volvo	33,205
XC70		2007-02	2014-06	Conti	31445473	Conti Clamp-in TG1C 433MHz Volvo	2,471
<b>4071</b>							
<b>Infiniti</b>							
JX	P42J	2014-03	EOP	Conti	407003JA0A	Conti Clamp-in TG1C 433MHz Conti Nissan	1
Q50	D53H	2013-04	EOP	Conti	407003JA0A	Conti Clamp-in TG1C 433MHz Conti Nissan	60
Q50	L53H	2014-03	EOP	Conti	407003JA0A	Conti Clamp-in TG1C 433MHz Conti Nissan	8,413
Q60	D53H	2015-05	EOP	Conti	407003JA0A	Conti Clamp-in TG1C 433MHz Conti Nissan	805
Q60	L53H	2016-01	EOP	Conti	407003JA0A	Conti Clamp-in TG1C 433MHz Conti Nissan	16
QX50	P53B(2)	2015-11	EOP	Conti	407003JA0A	Conti Clamp-in TG1C 433MHz Conti Nissan	45
QX70	P53J	2016-01	EOP	Conti	407003JA0A	Conti Clamp-in TG1C 433MHz Conti Nissan	40
<b>Nissan</b>							
Murano	P42M	2014-10	2015-05	Conti	407003JA0A	Conti Clamp-in TG1C 433MHz Conti Nissan	46
Pathfinder (LCV)	P61B	2014-06	EOP	Conti	407003JA0A	Conti Clamp-in TG1C 433MHz Conti Nissan	4
<b>4072</b>							
<b>Honda</b>							
Accord	2GA	2013-07	EOP	Conti	42753-TL0-G520	Conti Clamp-in TG1C 433MHz Conti Honda	2
Accord	QE	2013-07	EOP	Conti	42753-TL0-G520	Conti Clamp-in TG1C 433MHz Conti Honda	854
Accord	QP	2013-07	EOP	Conti	42753-TL0-G520	Conti Clamp-in TG1C 433MHz Conti Honda	342
Jazz	2AP_2HQ	2014-06	EOP	Conti	42753-TL0-G520	Conti Clamp-in TG1C 433MHz Conti Honda	8
Jazz	2WF	2014-09	EOP	Conti	42753-TL0-G520	Conti Clamp-in TG1C 433MHz Conti Honda	82,890
Jazz	2AP	2014-03	EOP	Conti	42753-TL0-G520	Conti Clamp-in TG1C 433MHz Conti Honda	1,374
<b>Qoros</b>							
3	CF11	2014-07	EOP	Conti	42753-TL0-G520	Conti Clamp-in TG1C 433MHz Conti Honda	680
3	CF14	2014-11	EOP	Conti	42753-TL0-G520	Conti Clamp-in TG1C 433MHz Conti Honda	685
3 Cross	CF14K	2015-03	EOP	Conti	42753-TL0-G520	Conti Clamp-in TG1C 433MHz Conti Honda	253
<b>4073</b>							
<b>Citroen</b>							
C4 Aircross	J4	2014-04	EOP	Conti	1612477080	Conti Clamp-in TG1C 433MHz Conti PSA	31,586
C4 Aircross	ZC(2)	2016-08	EOP	Conti	4250C477	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	56
C-Crosser	J4	2014-03	EOP	Conti	4250C477	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	1
C-ZERO	S4	2014-06	EOP	Conti	1612477080	Conti Clamp-in TG1C 433MHz Conti PSA	3,643
<b>Fiat</b>							
1-Tonne Pickup	4P00	2016-01	EOP	Conti	4250C477	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	56
Fullback	4P00	2016-01	EOP	Conti	4250C477	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	11,749
<b>Mitsubishi</b>							
ASX	ZC	2014-06	EOP	Conti	4250C477	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	131,151
C-SUV	BSUV	2017-01	EOP	Conti	4250C477	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	28
i-MiEV	TQ	2014-06	EOP	Conti	4250C477	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	1,878
L200	4P00	2014-11	EOP	Conti	4250C477	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	41,113
L200	4P00_CR	2014-06	EOP	Conti	4250C477	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	6,387
L200	CR	2014-06	EOP	Conti	4250C477	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	60
Lancer	GS41	2014-06	EOP	Conti	4250C477	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	10,399
Lancer	JT41	2014-06	EOP	Conti	4250C477	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	3
Outlander	RE	2014-06	EOP	Conti	4250C477	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	125,397
Outlander	GS45X.RE	2014-03	EOP	Conti	4250C477	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	2,235

Schrader Part Number (NEW)	Car Model Code	Start of Application	End of Application	Sensor Manufacturer	OE Sensor Reference	Sensor Description	Direct TPMS Car Pk in market 2017
Pajero	BK	2014-07	EOP	Conti	4250C477	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	20,368
Spacestar	EL	2014-07	EOP	Conti	4250C477	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	81,971
<b>Peugeot</b>							
4007	I3	2014-03	EOP	Conti	1612477080	Conti Clamp-in TG1C 433MHz Conti PSA	1
4008	J3	2014-06	EOP	Conti	1612477080	Conti Clamp-in TG1C 433MHz Conti PSA	5,399
4008	ZC(2)	2016-09	EOP	Conti	1612477080	Conti Clamp-in TG1C 433MHz Conti PSA	53
iOn	S3	2014-06	EOP	Conti	4250C477	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	4,690
<b>4077</b>							
<b>Nissan</b>							
Micra	B02A	2010-03	2016-11	Pacific	40700-3HN0B	Pacific Clamp-in Fixed Angle 433MHz Nissan	143,143
Patrol	Y62	2014-06	EOP	Pacific	40700-3HN0B	Pacific Clamp-in Fixed Angle 433MHz Nissan	1
<b>4078</b>							
<b>Hyundai</b>							
i40	VF	2014-04	EOP	TRW	52933-3V600	TRW Clamp-in Variable Angle ver 1 433MHz HKMC	60,518
<b>Kia</b>							
Rio	QB	2014-03	EOP	TRW	52933-3V600	TRW Clamp-in Variable Angle ver 1 433MHz HKMC	8,660
<b>4079</b>							
<b>Mitsubishi</b>							
Attrage	EL-L	2014-03	EOP	Conti	4250C275	Conti Snap-in TG1D 433MHz Conti Mitsubishi	566
B-SUV	BSUV	2017-01	EOP	Conti	4250C275	Conti Snap-in TG1D 433MHz Conti Mitsubishi	28
Colt	ZM	2014-03	EOP	Conti	4250C275	Conti Snap-in TG1D 433MHz Conti Mitsubishi	1
Mirage	EL	2013-05	EOP	Conti	4250C275	Conti Snap-in TG1D 433MHz Conti Mitsubishi	5,633
Pajero	GSPJ	2016-07	EOP	Conti	4250C275	Conti Snap-in TG1D 433MHz Conti Mitsubishi	6
Pajero	4T45	2017-01	EOP	Conti	4250C275	Conti Snap-in TG1D 433MHz Conti Mitsubishi	6
Pajero (LCV)	BK	2014-07	EOP	Conti	4250C275	Conti Snap-in TG1D 433MHz Conti Mitsubishi	14
Pajero Sport	4P45	2015-01	EOP	Conti	4250C275	Conti Snap-in TG1D 433MHz Conti Mitsubishi	1,805
Pinin Pajero	MINICAB	2014-03	EOP	Conti	4250C275	Conti Snap-in TG1D 433MHz Conti Mitsubishi	1
<b>4081</b>							
<b>Tesla</b>							
Model S	Model S	2014-09	EOP	Conti	1034602-00-A	Conti Clamp-in TG1C 433MHz Silver Stem Tesla	38,911
Model X	Model X	2015-08	EOP	Conti	1034602-00-A	Conti Clamp-in TG1C 433MHz Silver Stem Tesla	11,747
<b>4083</b>							
<b>Great Wall</b>							
Steed	K2/K4	2014-06	EOP	SATE	3641110AK80XA	SATE Clamp-in 433MHz Great Wall	1,738
Voleex C20R	CH035	2014-03	EOP	SATE	3641110AK80XA	SATE Clamp-in 433MHz Great Wall	17
Voleex C30	CH041	2014-03	EOP	SATE	3641110AK80XA	SATE Clamp-in 433MHz Great Wall	176
<b>4084</b>							
<b>Ssangyong</b>							
LUVi	X100	2016-01	EOP	Huf	41990-35000	Huf Snap-in 433MHz Huf Ssangyong	73
Tivoli	X100	2015-01	EOP	Huf	41990-35000	Huf Snap-in 433MHz Huf Ssangyong	24,085
Tivoli Air	X105	2016-01	EOP	Huf	41990-35000	Huf Snap-in 433MHz Huf Ssangyong	26
Tivoli XLV	X105	2016-01	EOP	Huf	41990-35000	Huf Snap-in 433MHz Huf Ssangyong	4,392
<b>4085</b>							
<b>Hyundai</b>							
Elantra	AD	2015-01	EOP	Conti	52933-D4100	Conti Clamp-in TG1C 433MHz HKMC Conti LoS Optima	4,072
Grandeur	IG	2017-01	EOP	Conti	52933-D4100	Conti Clamp-in TG1C 433MHz HKMC Conti LoS Optima	9
i30	PD	2016-08	EOP	Conti	52933-D4100	Conti Clamp-in TG1C 433MHz HKMC Conti LoS Optima	61,776
<b>Kia</b>							
Optima	JF	2015-07	EOP	Conti	52933-D4100	Conti Clamp-in TG1C 433MHz HKMC Conti LoS Optima	25,269
<b>4086</b>							
<b>Fisker</b>							
Karma	K1	2014-03	EOP	Lear	C131124501000	Lear Snap-in Fixed Angle ver 1 433MHz Fisker sensor	11
<b>4087</b>							
<b>Hyundai</b>							
i40	IF	2017-01	EOP	Conti	52933-D9100	Conti Clamp-in TG1C 433MHz HKMC Conti QL Platform	6,325
<b>Kia</b>							
Cadenza	YG	2016-01	EOP	Conti	52933-D9100	Conti Clamp-in TG1C 433MHz HKMC Conti QL Platform	1
Picanto	JA	2017-01	EOP	Conti	52933-D9100	Conti Clamp-in TG1C 433MHz HKMC Conti QL Platform	42,023
Sportage	QL	2016-01	EOP	Conti	52933-D9100	Conti Clamp-in TG1C 433MHz HKMC Conti QL Platform	272,288
<b>4089</b>							
<b>Hyundai</b>							
H1	TQ	2014-03	EOP	Conti	52933-4H100	Conti Clamp in TG1C 433MHz HKMC H1 Starex	352
H1 Combi	TQ	2014-03	EOP	Conti	52933-4H100	Conti Clamp in TG1C 433MHz HKMC H1 Starex	63
H1 Van	TQ	2014-03	EOP	Conti	52933-4H100	Conti Clamp in TG1C 433MHz HKMC H1 Starex	446
H100	TQ	2014-03	EOP	Conti	52933-4H100	Conti Clamp in TG1C 433MHz HKMC H1 Starex	2,632
H100 Van	TQ	2014-03	EOP	Conti	52933-4H100	Conti Clamp in TG1C 433MHz HKMC H1 Starex	1,016
i800	TQ	2014-06	EOP	Conti	52933-4H100	Conti Clamp in TG1C 433MHz HKMC H1 Starex	1,986

Schrader Part Number (NEW)	Car Model Code	Start of Application	End of Application	Sensor Manufacturer	OE Sensor Reference	Sensor Description	Direct TPMS Car Park in market 2017
Iload	TQ	2014-03	EOP	Conti	52933-4H100	Conti Clamp in TG1C 433MHz HKMC H1 Starex	443
Starex	A1	2014-03	EOP	Conti	52933-4H100	Conti Clamp in TG1C 433MHz HKMC H1 Starex	9
<b>4102</b>							
<b>Alfa Romeo</b>							
Stelvio	949	2017-01	EOP	Conti	50547691	Conti Clamp-in TG1C 433MHz Alfa Giulia	8,585

## Euroguide -Service Kits Look Up

**Service Kits Look Up:** The application sensor list applied to a service kit is a list detailing which sensors can be serviced with that particular service kit. The number besides the code represents the quantity included in package (for example 5001-10 means a package containing 10 Service kits)

1/ The first column "**Service Kits Part Nr./ Schrader Part Number (NEW)**" lists each service kit and identifies the sensors matching with the selected service kit (red references)

2/ The second column titled "**Service Kit Description**" shows the description of the selected service kit.

3/ The remaining column details the After Market "**Sensor Description**" of the sensor that can be serviced with the selected service kit.

TPMS Euroshop makes every effort to ensure that the information contained in this list are correct, but cannot guarantee 100% accuracy of the information. Customers should be aware that they buy and use any products on this website at their own risk. This list will be regularly updated. For further information: [tpmseuroshop.com](http://tpmseuroshop.com) or [aftermarket@schrader.co.uk](mailto:aftermarket@schrader.co.uk)

Service Kits Part Nr. Schrader Part Number (NEW)	Service Kit Description	Sensor Description
<b>5001-10</b>		
3042	Service kit for SEL Clamp-in Gen2 type 433MHz Renault grommet seal	Schrader Clamp-in Gen 2/3 Type fixed 10deg angle Small Grommet Seal 433MHz Renault
<b>5002-10</b>		
3040	Service kit for SEL Clamp-in Gen2 type 433MHz Renault conical seal coloured rings	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz Renault
3043	Service kit for SEL Clamp-in Gen2 type 433MHz Renault conical seal coloured rings	Schrader Clamp-in Gen 2/3 Type fixed 10deg angle Conical Seal 433MHz Renault
<b>5003-10</b>		
3004	Service Kit for SEL Clamp-in Gen2 type 433MHz PSA PWM	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Large Grommet Seal 433MHz PSA
<b>5004-10</b>		
3026	Service Kit for SEL Gen2 conical seal	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM
3031	Service Kit for SEL Gen2 conical seal	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM
3037	Service Kit for SEL Gen2 conical seal	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz Nissan
3046	Service Kit for SEL Gen2 conical seal	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz Volvo
3058	Service Kit for SEL Gen2 conical seal	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM
<b>5005</b>		
4036	Service Kit for Conti TG1B Renault	Conti Clamp-in TG1B Siemens VDO 433MHz Renault
<b>5006</b>		
4031	Service Kit for Conti TG1B PSA Ford	Conti Clamp-in TG1B Siemens VDO 433MHz PSA
<b>5007</b>		
4037	Service Kit for Conti TG1B black nut VW	Conti Clamp-in TG1B Siemens VDO 433MHz VW
<b>5008</b>		
4040	Service Kit for Conti TG1B (MB) Daimler	Conti Clamp-in MB_no RF link Siemens VDO 433MHz Daimler

Service Kits Part Nr. Schrader Part Number (NEW)	Service Kit Description	Sensor Description
<b>5014</b>		
4026	Service Kit for Conti TG1B HKMC	Conti Clamp-in TG1B 433MHz HKMC
<b>5015</b>		
4038	Service Kit for Conti TG1B (MB) Daimler	Conti Clamp-in MB_no RF link Siemens VDO 433MHz Daimler
<b>5016-10</b>		
3039	Service Kit for SEL Gen 3.1 Nissan	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan
<b>5017-10</b>		
3011	Service Kit for SEL Gen-Alpha Aluminium rims Daimler Chrysler WAL	Schrader Clamp-in Gen Alpha for Alloy / Steel rims 433MHz Daimler
<b>5018</b>		
4035	Service Kit for Conti TG1C Renault	Conti Clamp-in TG1C Siemens VDO 433MHz Renault
<b>5020</b>		
4019	Service Kit for Conti TG1C	Conti Clamp-in TG1C 433MHz Ford
4065	Service Kit for Conti TG1C	Conti Clamp-in TG1C 433MHz Suzuki
4021	Service Kit for Conti TG1C	Conti Clamp-in TG1C 433MHz Ford
4070	Service Kit for Conti TG1C	Conti Clamp-in TG1C 433MHz Volvo
4072	Service Kit for Conti TG1C	Conti Clamp-in TG1C 433MHz Conti Honda
4066	Service Kit for Conti TG1C	Conti Clamp-in TG1C 433MHz JLR
4071	Service Kit for Conti TG1C	Conti Clamp-in TG1C 433MHz Conti Nissan
4023	Service Kit for Conti TG1C	Conti Clamp-in TG1B 433MHz Ford
4090	Service Kit for Conti TG1C	Conti Clamp-in TG1C 433MHz Conti JLR FSK
<b>5021</b>		
4027	Service Kit for Conti TG1C HKMC	Conti Clamp-in TG1C 433MHz HKMC
4060	Service Kit for Conti TG1C HKMC	Conti Clamp-in TG1C 433MHz HKMC
<b>5022</b>		
4028	Service Kit for Conti TG1C Mazda	Conti Clamp-in TG1C 433MHz Mazda
4085	Service Kit for Conti TG1C Mazda	Conti Clamp-in TG1C 433MHz HKMC Conti LoS Optima
4087	Service Kit for Conti TG1C Mazda	Conti Clamp-in TG1C 433MHz HKMC Conti QL Platform
<b>5024-10</b>		
3000	Service kit Aluminium valve for SEL Snap-in Gen4 with valve	Schrader Snap-in GEN4 type 433MHz PSA
3001	Service kit Aluminium valve for SEL Snap-in Gen4 with valve	Schrader Snap-in GEN4 type 433MHz PSA HP
3005	Service kit Aluminium valve for SEL Snap-in Gen4 with valve	Schrader Snap-in GEN4 type 433MHz Chrysler
3007	Service kit Aluminium valve for SEL Snap-in Gen4 with valve	Schrader Snap-in GEN4 type 433MHz Chrysler
3020	Service kit Aluminium valve for SEL Snap-in Gen4 with valve	Schrader Snap-in GEN4 type 433MHz Ford
3027	Service kit Aluminium valve for SEL Snap-in Gen4 with valve	Schrader Snap-in GEN4 type 433MHz GM
3049	Service kit Aluminium valve for SEL Snap-in Gen4 with valve	Schrader Snap-in GEN4 type 433MHz GM
3056	Service kit Aluminium valve for SEL Snap-in Gen4 with valve	Schrader Snap-in GEN4 type 433MHz HKMC
3062	Service kit Aluminium valve for SEL Snap-in Gen4 with valve	Schrader Snap-in GEN4 type 433MHz GM
2020	Service kit Aluminium valve for SEL Snap-in Gen4 with valve	Schrader Clamp-in Fixed 20deg angle 433Mhz programmable WAL EZ-sensor® sensor Europe

Service Kits Part Nr. Schrader Part Number (NEW)	Service Kit Description	Sensor Description
3068	Service kit Aluminium valve for SEL Snap-in Gen4 with valve	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL
3018	Service kit Aluminium valve for SEL Snap-in Gen4 with valve	Schrader Snap-in GEN4 type 315MHz Ford
1900	Service kit Aluminium valve for SEL Snap-in Gen4 with valve	Schrader programmable EZ-sensor® Snap-in 315/433 MHz USA
3200	Service kit Aluminium valve for SEL Snap-in Gen4 with valve	Schrader Snap-in GEN4 type 315Mhz Programmable NON-WAL EZ-sensor® USA (Was 1200)
3210	Service kit Aluminium valve for SEL Snap-in Gen4 with valve	Schrader Snap-in GEN4 type 433Mhz programmable WAL EZ-sensor® USA (Was 1210)
3063	Service kit Aluminium valve for SEL Snap-in Gen4 with valve	Schrader Snap-in Faraday 433MHz GM
1920	Service kit Aluminium valve for SEL Snap-in Gen4 with valve	Schrader programmable EZ-sensor® Snap-in 315/433 MHz APAC
3078	Service kit Aluminium valve for SEL Snap-in Gen4 with valve	Schrader Snap-in GEN4 type 433MHz Great Wall (China)
3086	Service kit Aluminium valve for SEL Snap-in Gen4 with valve	Schrader Snap-in Faraday 314.9MHz GM (China)
9050	Service kit Aluminium valve for SEL Snap-in Gen4 with valve	Number reserved for RFK 433MHz Faraday LS
9051	Service kit Aluminium valve for SEL Snap-in Gen4 with valve	Number reserved for RFK 314.9MHz Faraday LS
<b>5025-10</b>		
2020	Service kit Aluminium valve for SEL Snap-in Gen4 (5024-10 without valve)	Schrader Clamp-in Fixed 20deg angle 433Mhz programmable WAL EZ-sensor® sensor Europe
<b>5026-10</b>		
3000	Valve for SEL Snap-in REV4 Gen4 - includes mounting screw	Schrader Snap-in GEN4 type 433MHz PSA
3001	Valve for SEL Snap-in REV4 Gen4 - includes mounting screw	Schrader Snap-in GEN4 type 433MHz PSA HP
1900	Valve for SEL Snap-in REV4 Gen4 - includes mounting screw	Schrader programmable EZ-sensor® Snap-in 315/433 MHz USA
3063	Valve for SEL Snap-in REV4 Gen4 - includes mounting screw	Schrader Snap-in Faraday 433MHz GM
1920	Valve for SEL Snap-in REV4 Gen4 - includes mounting screw	Schrader programmable EZ-sensor® Snap-in 315/433 MHz APAC
3086	Valve for SEL Snap-in REV4 Gen4 - includes mounting screw	Schrader Snap-in Faraday 314.9MHz GM (China)
9050	Valve for SEL Snap-in REV4 Gen4 - includes mounting screw	Number reserved for RFK 433MHz Faraday LS
9051	Valve for SEL Snap-in REV4 Gen4 - includes mounting screw	Number reserved for RFK 314.9MHz Faraday LS
<b>5028-10</b>		
3005	Valve for SEL Snap-in REV5 Gen4 - includes mounting screw	Schrader Snap-in GEN4 type 433MHz Chrysler
3007	Valve for SEL Snap-in REV5 Gen4 - includes mounting screw	Schrader Snap-in GEN4 type 433MHz Chrysler
3020	Valve for SEL Snap-in REV5 Gen4 - includes mounting screw	Schrader Snap-in GEN4 type 433MHz Ford
3027	Valve for SEL Snap-in REV5 Gen4 - includes mounting screw	Schrader Snap-in GEN4 type 433MHz GM
3049	Valve for SEL Snap-in REV5 Gen4 - includes mounting screw	Schrader Snap-in GEN4 type 433MHz GM
3056	Valve for SEL Snap-in REV5 Gen4 - includes mounting screw	Schrader Snap-in GEN4 type 433MHz HKMC
3062	Valve for SEL Snap-in REV5 Gen4 - includes mounting screw	Schrader Snap-in GEN4 type 433MHz GM
3068	Valve for SEL Snap-in REV5 Gen4 - includes mounting screw	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL
3018	Valve for SEL Snap-in REV5 Gen4 - includes mounting screw	Schrader Snap-in GEN4 type 315MHz Ford
1900	Valve for SEL Snap-in REV5 Gen4 - includes mounting screw	Schrader programmable EZ-sensor® Snap-in 315/433 MHz USA
3200	Valve for SEL Snap-in REV5 Gen4 - includes mounting screw	Schrader Snap-in GEN4 type 315Mhz Programmable NON-WAL EZ-sensor® USA (Was 1200)
3210	Valve for SEL Snap-in REV5 Gen4 - includes mounting screw	Schrader Snap-in GEN4 type 433Mhz programmable WAL EZ-sensor® USA (Was 1210)
3063	Valve for SEL Snap-in REV5 Gen4 - includes mounting screw	Schrader Snap-in Faraday 433MHz GM
1920	Valve for SEL Snap-in REV5 Gen4 - includes mounting screw	Schrader programmable EZ-sensor® Snap-in 315/433 MHz APAC
3078	Valve for SEL Snap-in REV5 Gen4 - includes mounting screw	Schrader Snap-in GEN4 type 433MHz Great Wall (China)
3086	Valve for SEL Snap-in REV5 Gen4 - includes mounting screw	Schrader Snap-in Faraday 314.9MHz GM (China)
9050	Valve for SEL Snap-in REV5 Gen4 - includes mounting screw	Number reserved for RFK 433MHz Faraday LS
9051	Valve for SEL Snap-in REV5 Gen4 - includes mounting screw	Number reserved for RFK 314.9MHz Faraday LS

Service Kits Part Nr. Schrader Part Number (NEW)	Service Kit Description	Sensor Description
<b>5029-10</b>		
3008	Service Kit for SEL Gen-Alpha Chrysler FSK basic	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler
<b>5030-10</b>		
3053	Service Kit for SEL Gen-J GM	Schrader Clamp-in Gen J 433MHz GM
3054	Service Kit for SEL Gen-J GM	Schrader Clamp-in Gen J 433MHz GM
3055	Service Kit for SEL Gen-J GM	Schrader Clamp-in Gen J 433MHz GM
<b>5033-10</b>		
1210	HSS replacement valve with screw	Schrader programmable EZ-sensor® 2.0 Snap-in 433 MHz Europe
3041	HSS replacement valve with screw	Schrader Snap-in HS with 20deg angle 433MHz Renault
3002	HSS replacement valve with screw	Schrader Snap-in HS with 20deg angle 433MHz PSA
3003	HSS replacement valve with screw	Schrader Snap-in HS with 20deg angle 433MHz PSA HP
3064	HSS replacement valve with screw	Schrader Snap-in HS with 20deg angle 433MHz Subaru
3059	HSS replacement valve with screw	Schrader Snap-in HS with 20deg angle 433MHz HKMC
3060	HSS replacement valve with screw	Schrader Snap-in HS with 20deg angle 433MHz HKMC
3012	HSS replacement valve with screw	Schrader Snap-in HS with 10deg angle 433MHz Daimler
3073	HSS replacement valve with screw	Schrader Snap-in Faraday 433MHz Renault T4
3021	HSS replacement valve with screw	Schrader Snap-in Faraday 433MHz Ford
3069	HSS replacement valve with screw	Schrader Snap-in HS with 20deg angle 433MHz Volvo
3023	HSS replacement valve with screw	Schrader Snap-in Faraday 433MHz Ford
3074	HSS replacement valve with screw	Schrader Snap-in Faraday 433MHz Subaru
9014	HSS replacement valve with screw	Italsensor IT-100 snap-in
3076	HSS replacement valve with screw	Schrader Snap-in Faraday 433MHz Subaru
3047	HSS replacement valve with screw	Schrader Snap-in Faraday 433MHz VW
3025	HSS replacement valve with screw	Schrader Snap-in Faraday 433MHz GM
3029	HSS replacement valve with screw	Schrader Snap-in HS with 20deg angle 433MHz GM
3044	HSS replacement valve with screw	Schrader Snap-in Faraday 433MHz Volvo
3061	HSS replacement valve with screw	Schrader Snap-in Faraday 433MHz HKMC
9049	HSS replacement valve with screw	Number reserved for RFK 433MHz HSSI hybrid
3071	HSS replacement valve with screw	Schrader Snap-in Faraday 433MHz GM
3118	HSS replacement valve with screw	Schrader Snap-in Gen6 Edison 433MHz GM
3131	HSS replacement valve with screw	Schrader Snap-in 433MHz HKMC FSK PAL HSSI
<b>5037-10</b>		
3033	Service Kit for SEL Gen Gamma GM	Schrader Clamp-in Gen Gamma 433MHz GM



Service Kits Part Nr. Schrader Part Number (NEW)	Service Kit Description	Sensor Description
<b>5039</b>		
9009	Service Kit for Huf/Beru valve length L=43mm Gen 2 Silver	Number reserved for Intellisens clamp-in
<b>5050</b>		
9009	Service Kit for Huf/Beru valve length L=43mm Gen 2 Black	Number reserved for Intellisens clamp-in
<b>5056-10</b>		
3013	Service Kit for SEL Gen Gamma Mercedes	Schrader Clamp-in Gen Gamma 433MHz Daimler
2200	Service Kit for SEL Gen Gamma Mercedes	Schrader programmable EZ-sensor® 2.0 Clamp-in variable angle 433MHz Europe
3057	Service Kit for SEL Gen Gamma Mercedes	Schrader Clamp-in Gen Delta 433MHz Daimler/BMW
9047	Service Kit for SEL Gen Gamma Mercedes	Italsensor IT-300 variable angle clamp-in
3134	Service Kit for SEL Gen Gamma Mercedes	Schrader Clamp-in Gen Delta 314.9MHz BMW
<b>5057</b>		
4032	Service Kit for Conti TG1C Renault / Nissan	Conti Clamp-in TG1C 433MHz Renault
4034	Service Kit for Conti TG1C Renault / Nissan	Conti Snap-in TG1D 433MHz Renault
<b>5058</b>		
4043	Service Kit for Conti TG1C BMW / Mini	Conti Clamp-in TG1C 433MHz BMW
<b>5059</b>		
4073	Service Kit for Conti TG1C Mitsubishi	Conti Clamp-in TG1C 433MHz Conti Mitsubishi
<b>5060-10</b>		
3009	Service Kit for SEL Gen Gamma Chrysler/Fiat	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat
<b>5061-10</b>		
1210	Valve for SEL EZ-sensor®2.0 clamp-in 2210 part - includes mounting screw	Schrader programmable EZ-sensor® 2.0 Snap-in 433 MHz Europe
2000	Valve for SEL EZ-sensor®2.0 clamp-in 2210 part - includes mounting screw	Schrader Clamp-in Fixed 10deg angle 433Mhz programmable WAL EZ-sensor® sensor Europe
3041	Valve for SEL EZ-sensor®2.0 clamp-in 2210 part - includes mounting screw	Schrader Snap-in HS with 20deg angle 433MHz Renault
3002	Valve for SEL EZ-sensor®2.0 clamp-in 2210 part - includes mounting screw	Schrader Snap-in HS with 20deg angle 433MHz PSA
3003	Valve for SEL EZ-sensor®2.0 clamp-in 2210 part - includes mounting screw	Schrader Snap-in HS with 20deg angle 433MHz PSA HP
3064	Valve for SEL EZ-sensor®2.0 clamp-in 2210 part - includes mounting screw	Schrader Snap-in HS with 20deg angle 433MHz Subaru
3059	Valve for SEL EZ-sensor®2.0 clamp-in 2210 part - includes mounting screw	Schrader Snap-in HS with 20deg angle 433MHz HKMC
3060	Valve for SEL EZ-sensor®2.0 clamp-in 2210 part - includes mounting screw	Schrader Snap-in HS with 20deg angle 433MHz HKMC
3012	Valve for SEL EZ-sensor®2.0 clamp-in 2210 part - includes mounting screw	Schrader Snap-in HS with 10deg angle 433MHz Daimler
3073	Valve for SEL EZ-sensor®2.0 clamp-in 2210 part - includes mounting screw	Schrader Snap-in Faraday 433MHz Renault T4
3021	Valve for SEL EZ-sensor®2.0 clamp-in 2210 part - includes mounting screw	Schrader Snap-in Faraday 433MHz Ford
3069	Valve for SEL EZ-sensor®2.0 clamp-in 2210 part - includes mounting screw	Schrader Snap-in HS with 20deg angle 433MHz Volvo
2210	Valve for SEL EZ-sensor®2.0 clamp-in 2210 part - includes mounting screw	Schrader programmable EZ-sensor® 2.0 Clamp-in fixed angle 10° 433 MHz Europe
3023	Valve for SEL EZ-sensor®2.0 clamp-in 2210 part - includes mounting screw	Schrader Snap-in Faraday 433MHz Ford
3074	Valve for SEL EZ-sensor®2.0 clamp-in 2210 part - includes mounting screw	Schrader Snap-in Faraday 433MHz Subaru
9014	Valve for SEL EZ-sensor®2.0 clamp-in 2210 part - includes mounting screw	Italsensor IT-100 snap-in

Service Kits Part Nr. Schrader Part Number (NEW)	Service Kit Description	Sensor Description
9005	Valve for SEL EZ-sensor@2.0 clamp-in 2210 part - includes mounting screw	Number reserved for Alcar sensor
9015	Valve for SEL EZ-sensor@2.0 clamp-in 2210 part - includes mounting screw	Italsensor IT-200 clamp-in
3077	Valve for SEL EZ-sensor@2.0 clamp-in 2210 part - includes mounting screw	Schrader Faraday Clamp-in Fixed 20deg angle 433MHz Ford
3094	Valve for SEL EZ-sensor@2.0 clamp-in 2210 part - includes mounting screw	Schrader Faraday Clamp-in Fixed 20deg angle 433MHz GM
9024	Valve for SEL EZ-sensor@2.0 clamp-in 2210 part - includes mounting screw	Number reserved for Mobis Snap-in Polysensor
9021	Valve for SEL EZ-sensor@2.0 clamp-in 2210 part - includes mounting screw	Number reserved for MW-Ital Clamp-in Sensor
9025	Valve for SEL EZ-sensor@2.0 clamp-in 2210 part - includes mounting screw	Number reserved for Mobis Clamp-in Polysensor
9026	Valve for SEL EZ-sensor@2.0 clamp-in 2210 part - includes mounting screw	Number reserved for Alcar P&D2 20 degree
9027	Valve for SEL EZ-sensor@2.0 clamp-in 2210 part - includes mounting screw	Number reserved for Alcar P&D3 20 degree
9028	Valve for SEL EZ-sensor@2.0 clamp-in 2210 part - includes mounting screw	Number reserved for Alcar P&D1 10 degree
9029	Valve for SEL EZ-sensor@2.0 clamp-in 2210 part - includes mounting screw	Number reserved for Alcar P&D2 10 degree
9030	Valve for SEL EZ-sensor@2.0 clamp-in 2210 part - includes mounting screw	Number reserved for Alcar P&D3 10 degree
3076	Valve for SEL EZ-sensor@2.0 clamp-in 2210 part - includes mounting screw	Schrader Snap-in Faraday 433MHz Subaru
3047	Valve for SEL EZ-sensor@2.0 clamp-in 2210 part - includes mounting screw	Schrader Snap-in Faraday 433MHz VW
9046	Valve for SEL EZ-sensor@2.0 clamp-in 2210 part - includes mounting screw	Number reserved for Alcar sensor - ABS 10 degree
3025	Valve for SEL EZ-sensor@2.0 clamp-in 2210 part - includes mounting screw	Schrader Snap-in Faraday 433MHz GM
3029	Valve for SEL EZ-sensor@2.0 clamp-in 2210 part - includes mounting screw	Schrader Snap-in HS with 20deg angle 433MHz GM
3044	Valve for SEL EZ-sensor@2.0 clamp-in 2210 part - includes mounting screw	Schrader Snap-in Faraday 433MHz Volvo
3061	Valve for SEL EZ-sensor@2.0 clamp-in 2210 part - includes mounting screw	Schrader Snap-in Faraday 433MHz HKMC
9049	Valve for SEL EZ-sensor@2.0 clamp-in 2210 part - includes mounting screw	Number reserved for RFK 433MHz HSSI hybrid
3071	Valve for SEL EZ-sensor@2.0 clamp-in 2210 part - includes mounting screw	Schrader Snap-in Faraday 433MHz GM
3118	Valve for SEL EZ-sensor@2.0 clamp-in 2210 part - includes mounting screw	Schrader Snap-in Gen6 Edison 433MHz GM
3131	Valve for SEL EZ-sensor@2.0 clamp-in 2210 part - includes mounting screw	Schrader Snap-in 433MHz HKMC FSK PAL HSSI
<b>5062-10</b>		
2000	Service Kit for SEL EZ-sensor@2.0 clamp-in 2210 part - without valve	Schrader Clamp-in Fixed 10deg angle 433Mhz programmable WAL EZ-sensor@ sensor Europe
2210	Service Kit for SEL EZ-sensor@2.0 clamp-in 2210 part - without valve	Schrader programmable EZ-sensor@ 2.0 Clamp-in fixed angle 10° 433 MHz Europe
9005	Service Kit for SEL EZ-sensor@2.0 clamp-in 2210 part - without valve	Number reserved for Alcar sensor
3077	Service Kit for SEL EZ-sensor@2.0 clamp-in 2210 part - without valve	Schrader Faraday Clamp-in Fixed 20deg angle 433MHz Ford
3094	Service Kit for SEL EZ-sensor@2.0 clamp-in 2210 part - without valve	Schrader Faraday Clamp-in Fixed 20deg angle 433MHz GM
9021	Service Kit for SEL EZ-sensor@2.0 clamp-in 2210 part - without valve	Number reserved for MW-Ital Clamp-in Sensor
9025	Service Kit for SEL EZ-sensor@2.0 clamp-in 2210 part - without valve	Number reserved for Mobis Clamp-in Polysensor
9026	Service Kit for SEL EZ-sensor@2.0 clamp-in 2210 part - without valve	Number reserved for Alcar P&D2 20 degree
9027	Service Kit for SEL EZ-sensor@2.0 clamp-in 2210 part - without valve	Number reserved for Alcar P&D3 20 degree
9028	Service Kit for SEL EZ-sensor@2.0 clamp-in 2210 part - without valve	Number reserved for Alcar P&D1 10 degree
9029	Service Kit for SEL EZ-sensor@2.0 clamp-in 2210 part - without valve	Number reserved for Alcar P&D2 10 degree
9030	Service Kit for SEL EZ-sensor@2.0 clamp-in 2210 part - without valve	Number reserved for Alcar P&D3 10 degree
9046	Service Kit for SEL EZ-sensor@2.0 clamp-in 2210 part - without valve	Number reserved for Alcar sensor - ABS 10 degree
<b>5063-10</b>		
2200	Service Kit for SEL Gen Delta - without valve	Schrader programmable EZ-sensor@ 2.0 Clamp-in variable angle 433MHz Europe
3057	Service Kit for SEL Gen Delta - without valve	Schrader Clamp-in Gen Delta 433MHz Daimler/BMW
9047	Service Kit for SEL Gen Delta - without valve	Italsensor IT-300 variable angle clamp-in
3134	Service Kit for SEL Gen Delta - without valve	Schrader Clamp-in Gen Delta 314.9MHz BMW
<b>8001</b>		
3011	Aluminium valve stem for SEL Gen-Alpha without plastic cap	Schrader Clamp-in Gen Alpha for Alloy / Steel rims 433MHz Daimler

Service Kits Part Nr. Schrader Part Number (NEW)	Service Kit Description	Sensor Description
3008	Aluminium valve stem for SEL Gen-Alpha without plastic cap	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler
<b>8002-10</b>		
4035	Aluminium valve stem for Conti TG1C with plastic cap	Conti Clamp-in TG1C Siemens VDO 433MHz Renault
4032	Aluminium valve stem for Conti TG1C with plastic cap	Conti Clamp-in TG1C 433MHz Renault
4027	Aluminium valve stem for Conti TG1C with plastic cap	Conti Clamp-in TG1C 433MHz HKMC
4021	Aluminium valve stem for Conti TG1C with plastic cap	Conti Clamp-in TG1C 433MHz Ford
4060	Aluminium valve stem for Conti TG1C with plastic cap	Conti Clamp-in TG1C 433MHz HKMC
4018	Aluminium valve stem for Conti TG1C with plastic cap	Conti Clamp-in TG1C 433MHz Jeep FCA
<b>8003-10</b>		
4019	Aluminium valve stem for Conti TG1C with plastic cap	Conti Clamp-in TG1C 433MHz Ford
4065	Aluminium valve stem for Conti TG1C with plastic cap	Conti Clamp-in TG1C 433MHz Suzuki
4028	Aluminium valve stem for Conti TG1C with plastic cap	Conti Clamp-in TG1C 433MHz Mazda
4043	Aluminium valve stem for Conti TG1C with plastic cap	Conti Clamp-in TG1C 433MHz BMW
<b>8004-10</b>		
3000	T10 Screw for Snap-in sensor valve REV4/REV5	Schrader Snap-in GEN4 type 433MHz PSA
3001	T10 Screw for Snap-in sensor valve REV4/REV5	Schrader Snap-in GEN4 type 433MHz PSA HP
3005	T10 Screw for Snap-in sensor valve REV4/REV5	Schrader Snap-in GEN4 type 433MHz Chrysler
3007	T10 Screw for Snap-in sensor valve REV4/REV5	Schrader Snap-in GEN4 type 433MHz Chrysler
3020	T10 Screw for Snap-in sensor valve REV4/REV5	Schrader Snap-in GEN4 type 433MHz Ford
3027	T10 Screw for Snap-in sensor valve REV4/REV5	Schrader Snap-in GEN4 type 433MHz GM
3049	T10 Screw for Snap-in sensor valve REV4/REV5	Schrader Snap-in GEN4 type 433MHz GM
3056	T10 Screw for Snap-in sensor valve REV4/REV5	Schrader Snap-in GEN4 type 433MHz HKMC
3062	T10 Screw for Snap-in sensor valve REV4/REV5	Schrader Snap-in GEN4 type 433MHz GM
3068	T10 Screw for Snap-in sensor valve REV4/REV5	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL
3018	T10 Screw for Snap-in sensor valve REV4/REV5	Schrader Snap-in GEN4 type 315MHz Ford
3200	T10 Screw for Snap-in sensor valve REV4/REV5	Schrader Snap-in GEN4 type 315Mhz Programmable NON-WAL EZ-sensor® USA (Was 1200)
3210	T10 Screw for Snap-in sensor valve REV4/REV5	Schrader Snap-in GEN4 type 433Mhz programmable WAL EZ-sensor® USA (Was 1210)
3078	T10 Screw for Snap-in sensor valve REV4/REV5	Schrader Snap-in GEN4 type 433MHz Great Wall (China)
3024	T10 Screw for Snap-in sensor valve REV4/REV5	Schrader Clamp-in Fixed 20deg angle 433MHz Ford
3048	T10 Screw for Snap-in sensor valve REV4/REV5	Schrader Snap-in GEN4 type 433MHz VW
<b>5064</b>		
4034	Valve for Conti VDO TG1D	Conti Snap-in TG1D 433MHz Renault
4079	Valve for Conti VDO TG1D	Conti Snap-in TG1D 433MHz Conti Mitsubishi
<b>5071</b>		
4018	Service Kit for Conti TG1C	Conti Clamp-in TG1C 433MHz Jeep FCA
4016	Service Kit for Conti TG1C	Conti Snap-in TG1D 433MHz Chrysler
<b>5073</b>		
4089	Service Kit for Conti TG1C	Conti Clamp in TG1C 433MHz HKMC H1 Starex
<b>ALL HUF SERVICE KITS</b>		
4001		Beru-Huf Clamp-in Separate valve G1.2 433MHz Luxury brands
4002		Beru-Huf Clamp-in Separate valve G1.2 433MHz BMW

Service Kits Part Nr. Schrader Part Number (NEW)	Service Kit Description	Sensor Description
4003		Beru-Huf Clamp-in Separate valve G1.2 plus 433MHz BMW
4004		Beru-Huf Clamp-in Separate valve 315MHz Daimler
4005		Beru-Huf Clamp-in Separate valve G1.2 plus 433MHz VW/Porsche
4007		Beru-Huf Clamp-in Separate valve G2.4 433MHz BMW
4009		Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche
4010		Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche
4011		Beru-Huf Clamp-in Separate valve G3.42 433MHz VW
4012		Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche
4067		Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche
4069		Beru-Huf Clamp-in 433MHz BMW
4080		Beru-Huf Clamp-in 433MHz BMW
4082		Beru-Huf Clamp-in 433MHz BMW